



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004389
INV Date 19/06/2020
Reference CC4/FCI20005357/Eea3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMP 943R
Insured Veh. SHC 3278K
Claim No. D20001958MFSH
Policy No. D-20094922MFSH
Accident Date 19/04/2020
Inspection Date 04/05/2020

Description	Total
Survey Inspection	279.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	279.00
GST (7%)	19.53
Grand Total	298.53

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20005357/Eea3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-06-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3278K	Veh. Inspected	SMP 943R
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20001958MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	23/04/2020

2. Vehicle Particulars & Condition

Make & Model	MINI COOPER S	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WMWXS720002E45230	Colour	WHITE
Odometer	33072	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 R17	FIRELLI	5 mm
L/H Front Tyre	205/45 R17	FIRELLI	5 mm
R/H Rear Tyre	205/45 R17	FIRELLI	5 mm
L/H Rear Tyre	205/45 R17	FIRELLI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/04/2020	Inspection Date	04/05/2020
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 943R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LH FRONT DOOR	TO REPAIR SEE LABOUR	1,658.65	-
1	LH REAR DOOR	DENTED	1,358.65	1,136.19
1	LH ROCKER PANEL GARNISH	CUT	983.10	786.40
1	LH REAR WHEEL ARCH GARNISH	NOT NECESSARY	241.60	-
	LESS 10% DISCOUNT		-424.20	-192.26
			3,817.80	1,730.33
<u>SPECIAL NETT ITEMS</u>				
1	MISCELLANEOUS (SN)	NECESSARY	150.00	30.00
			150.00	30.00
<u>LABOUR</u>				
	TO CHECK ELECTRICAL WIRING.		80.00	30.00
	REMOVE AND TRANSFER BOTH LH DOORS FITTING.		300.00	80.00
	CHECK AND RESET FAULT CODE LIGHT ON.	NOT NECESSARY	200.00	-
	TO RESPRAY UNDERCOATING.		100.00	30.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	500.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF LH FRONT DOOR.		800.00	400.00
			2,400.00	1,070.00
GRAND TOTAL			6,367.80	2,830.33
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CC4/FCI20005357/Eea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 943R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 943R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

