



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 943R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LH FRONT DOOR	TO REPAIR SEE LABOUR	1,658.65	-
1	LH REAR DOOR	DENTED	1,358.65	1,136.19
1	LH ROCKER PANEL GARNISH	CUT	983.10	786.40
1	LH REAR WHEEL ARCH GARNISH	NOT NECESSARY	241.60	-
	LESS 10% DISCOUNT		-424.20	-192.26
			3,817.80	1,730.33
<u>SPECIAL NETT ITEMS</u>				
1	MISCELLANEOUS (SN)	NECESSARY	150.00	30.00
			150.00	30.00
<u>LABOUR</u>				
	TO CHECK ELECTRICAL WIRING.		80.00	30.00
	REMOVE AND TRANSFER BOTH LH DOORS FITTING.		300.00	80.00
	CHECK AND RESET FAULT CODE LIGHT ON.	NOT NECESSARY	200.00	-
	TO RESPRAY UNDERCOATING.		100.00	30.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	500.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF LH FRONT DOOR.		800.00	400.00
			2,400.00	1,070.00
GRAND TOTAL			6,367.80	2,830.33
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CC4/FCI20005357/Eea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.