

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20005365/ATF3E2

Date: 23/03/2021

REFERENCE

Insured/Claimant: CHO YOONG CHOW Policy No: 1700059687-02
Date of Loss: 20/04/2020 Nature of Claim: OD Claim No: 5337526322SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS2080L**
Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK043491
Reg. Date: 11/09/2017 (Man. Year: 2017) Chassis No: WAUZZZF57JA021943
Colour: Blue Odometer: 51511 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$126,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,611.00	6,565.66	5,045.34	43.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,112.00	5,602.00	13,510.00	70.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,723.00	12,167.66	18,555.34	60.40
- Excess (S\$)	4,600.00	4,600.00	0.00	0.00
(S\$)	26,123.00	7,567.66	18,555.34	71.03
+ GST 7.00/7.00% (S\$)	1,828.61	529.74	1,298.87	71.03
Nett Amount (S\$)	27,951.61	8,097.40	19,854.21	71.03

INSPECTION

Date of Assignment: 23/04/2020
Date Inspected: 23/04/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER - RH	Dented	2,354.00 FS	*1,883.20 FS
2	1		*SIDE WINDOW - RH	Not Necessary	676.00 FS	*- FS
3	1		*REAR DOOR - RH	Dented	2,946.00 FS	*2,356.80 FS
4	1		*REAR DOOR OUTER SEAL - RH	Necessary	209.00 FS	*167.20 FS
5	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
6	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
7	1		*REAR DOOR CATCH	Damaged	113.00 FS	*90.40 FS
8	1		*CHROME TRIM - RH	Cut	128.00 FS	*102.40 FS
9	1		*DOOR HANDLE TRIM PLATE - RH	Not Necessary	83.00 FS	*- FS
10	1		*DOOR HANDLE SENSOR - RH	Not Necessary	215.00 FS	*- FS
11	1		*EXTERIOR DOOR HANDLE - RH	Repair	40.00 FS	*- FS
12	1		*DOOR LOCK - RH	Not Necessary	623.00 FS	*- FS
13	1		*DOOR INNER PANEL COVER - RH	Not Necessary	30.00 FS	*- FS
14	1		*WINDOW REGULATOR - RH	Not Necessary	338.00 FS	*- FS
15	1		*WINDOW REGULATOR MOTOR - RH	Not Necessary	301.00 FS	*- FS
16	1		*SIDE MEMBER TRIM - RH	Deformed	778.00 FS	*622.00 FS
17	1		*SIDE MEMBER TRIM ATTACHMENT PARTS	Necessary	123.00 FS	*98.00 FS
18	1		*SIDE MEMBER TRIM ADHESIVE TAPES	Necessary	200.00 FS	*159.60 FS
19	1		*REAR ALUMINIUM RIM - RH	Not Necessary	964.00 FS	*- FS
20	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
21	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
22	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
23	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
24	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
25	1		*SUNDRIES	Necessary	500.00 FS	*218.14 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	11,611.00
						6,565.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	0.00
2	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	0.00
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	0.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	0.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	280.00
6	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
7	TO DISMANTLE REAR BUMPER, RHS REAR DOOR AND RHS SILL PANEL TRIM. CUT OUT AND WELD RHS REAR FENDER. TO RENEW RHS REAR DOOR AND RHS SILL PANEL TRIM. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	2,000.00
8	TO RESPRAY REAR BUMPER, RHS REAR DOOR, DOOR HANDLE, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL, RHS SILL PANEL TRIM AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	7,300.00	2,850.00
9	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			19,112.00	5,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >