



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 2261H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT N/S HEADLAMP	DAMAGED	2,541.71	2,043.40
1	FRONT BUMPER	DAMAGED	1,745.60	1,380.00
1	FRONT BUMPER N/S SIDE RETAINER	NECESSARY	129.90	129.90
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR	1,032.50	-
1	FRONT N/S FENDER OUTER GARNISH	DAMAGED	328.10	328.10
1	FRONT N/S DOOR	TO REPAIR SEE LABOUR	1,998.50	-
1	FRONT N/S DOOR RUBBER	NOT NECESSARY	260.80	-
1	FRONT N/S DOOR LOWER GARNISH	DAMAGED	700.80	700.80
1	FRONT N/S WHEEL RIM	TO REPAIR SEE LABOUR	984.60	-
	LESS 25% DISCOUNT		-2,430.63	-1,145.55
			7,291.88	3,436.65
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	FRONT N/S TYRE (DEPRECIATION) (SN)	SERVICEABLE	400.00	-
			460.00	30.00
<u>LABOUR</u>				
	TO CHECK WIRING, LIGHTING AND RESETTING HEADLAMPS FOCUSING.		80.00	30.00
	TO CONDUCT WHEEL ALIGNMENT		150.00	80.00
	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.		150.00	80.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		100.00	40.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT N/S FENDER, FRONT N/S DOOR AND FRONT N/S WHEEL RIM.		1,080.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAITING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,200.00	800.00
			2,760.00	1,630.00
GRAND TOTAL			10,511.88	5,096.65
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS3/ASM20002270/T1tf3s2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.