

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Pava Ubi Industrial Park

Tel: 6844 2475 Fo

Fax: 6844 2474

E-mail: claims@teamworkgarage.com

GST registered number: 201015366H

PROFOMA INVOICE - PI-2145

TOH TEONG CHOON

C/O 53 Ubi Avenue 1 #01-24

Paya Ubi Industrial Park

Singapore 408934

Date

:

28-Mar-20

Vehicle number

SKG2261H

Make Model

TOYOTA ESTIMA

Accident date

24-Jan-20

Reference number

2002-11

Description		Amount SGD\$
Inclusive of supplying parts, labour, panel beating and spray painting		
Lump sum repair	:	7000.00
7% GST	:	490.00
Grand total	:	7490.00
Singdollars:		
SEVEN THOUSAND FOUR HUNDRED AND NINTY DOLLARS		



Teamwork Garage Pte Ltd

Schedule of Surveyor,'s Attendance for Conducting PRS

This document indicates that the 3rd party surveyor has inspected the vehicle as follows:

	Workshop SKG 2261 H	
	Vehicle No. : 5/2 226171	and the second s
	Date of Accident :	
	Name of TP Insurer Co. :	
	Surveyor's Firm & Name :	
	Contact No.	
	Date of Vehicle Send in :	
	1st PRS Conducted.	
	Date & Time of Inspection : 1/7/20 / 1	111 - 17/
	Require of Resurvey Hidden/Check Items : YES / NO	Just Partito
		Signature / Name
	2nd PRS Conduct Hidden/Check Damages Items.	
	Date & Time Informed Surveyor :	By Repairer)
	Date & Time of Inspection	
	Require of Resurvey After Repair: YES / NO	3.
	Remarks :	Signature / Name
		i,
1		
	3rd PRS Conduct After Repairs.	y Repairer)
	Date & Time Informed Surveyor :(S	y Kepanor)
	Date & Time of Inspection :/	
	W	Signature / Name

24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

INVOICE

Invoice No:

CL/200161

Toh Teong Choon

C/o: Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-24

Paya Ubi Industrial Park, Singapore 408934

Ref No:

TWG/02/2004/TP

Date:

27 February 2020

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SKG 2261 H
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

S\$ 589.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CLAPPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.

CL Appraiser Pte Ltd

24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Toh Teong Choon

Date

: 27 February 2020

C/o: Teamwork Garage Pte Ltd

Our ref

: TWG/02/2004/TP

53 Ubi Avenue 1 #01-24

Paya Ubi Industrial Park, Singapore 408934

Accident Date

: 24 January 2020

Type of Survey

: Third Party

Inspection Date : 11 February 2020

Repairer Name

: Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-24

Paya Ubi Industrial Park, Singapore 408934

PARTICULARS OF VEHICLE

Registration No : SKG 2261 H

Year / Capacity

: 2008 / 2362 cc

Make / Model

: Toyota Estima

Colour

: White

Chassis No

: ACR507056208

Mileage

: 139569

Engine No

: 2AZF127215

CONDITION OF TYRES

		Make	Size	Th	read Balance]	Rim
Front Nearside	:	Michelin	225/50 R18		5 mm	S	Sport
Front Offside	:	Michelin	225/50 R18		5 mm	S	Sport
Rear Nearside	:	Michelin	225/50 R18		5 mm	S	Sport
Rear Offside	:	Michelin	225/50 R18		5 mm	S	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s front portion. (Details refer to the photographs attached)

Enclosed number of photographs:

44

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$7,000.00 on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.



Vehicle	Registration	No:	SKG	2261	H

Our Ref No: TWG/02/2004/TP

Qty	Description	Conditions	Repairer's Estimate		Revised Amount	
	SPARE PARTS - LIST ITEMS					
1	Front n/s headlamp	Damage	\$	2,541.71	\$	2,541.71
1	Front bumper	Damage	\$	1,745.60	\$	1,745.60
1	Front bumper n/s side retainer	Necessary	\$	129.90	\$	129.90
1	Front n/s fender	Repair	\$	1,032.50		
1	Front n/s fender outer garnish	Damage	\$	328.10	\$	328.10
1	Front n/s door	Damage	\$	1,998.50	\$	1,998.50
1	Front n/s door rubber	Necessary	\$	260.80	\$	260.80
1	Front n/s door lower garnish	Damage	\$	700.80	\$	700.80
1	Front n/s wheel rim	Damage	\$	984.60	\$	984.60
			\$	9,722.51	\$	8,690.01
		Less 25%	\$	2,430.63	\$	2,172.50
	Total Cost - List Items	2	\$	7,291.88	\$	6,517.51
	SPECIAL NETT ITEMS					
1	Front bumper clip (1 set)	Necessary	\$	60.00	\$	60.00
1	Front n/s tyre (Depreciation)	Damage	\$	400.00	\$	200.00
	Total Cost - Special Nett items		\$	460.00	\$	260.00

Total cost of parts

\$ 7,751.88	\$ 6,777.51



Vehicle Registration No: SKG 2261 H

Our Ref No: TWG/02/2004/TP

S/No	Description	Description Repairer's Estimate			Revised Amount		
	Total cost of parts c/f		7,751.88	\$	6,777.51		
	<u>LABOUR</u>						
1	To check wiring, lighting and resetting headlamps focussing.	\$	80.00	\$	50.00		
2	To conduct wheel alignment.	\$	150.00	\$	120.00		
3	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$	150.00	\$	120.00		
4	To apply undercoating on repaired and replaced panel.	\$	100.00	\$	60.00		
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	1,080.00	\$	750.00		
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,200.00	\$	880.00		
	GRAND TOTAL	\$	10,511.88	\$	8,757.51		



Vehicle Registration No: SKG 2261 H

Our Ref No: TWG/02/2004/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 7,000.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.


Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.


C L APPRAISER PTE LTD

Cheong K. H


Automotive Appraiser

























d 6956E/



