



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9143G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BONNET (CONSISTENT)	DENTED / BUCKLED	1,386.60	983.43
1	FRONT BONNET LOCK (CONSISTENT)	SERVICEABLE	148.00	-
2	FRONT HEAD LAMP @\$862.40 (CONSISTENT)	SCRATCHED / CRACKED	1,724.80	1,724.80
1	FRONT BUMPER (CONSISTENT)	DEFORMED / TORN	1,245.50	864.07
1	SET FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	58.00	58.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	752.00	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	NOT NECESSARY	685.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	TORN	117.60	117.60
1	FRONT GRILLE (CONSISTENT)	CRACKED	484.70	484.70
1	FRONT GRILLE "FIAT LOGO" MOTIF (CONSISTENT)	NECESSARY	142.10	142.10
1	FRONT NUMBER PLATE GARNISH (CONSISTENT)	NOT FITTED	387.00	-
1	FRONT AIR CON CONDENSOR (CONSISTENT)	PUNCTURE	1,278.80	1,278.00
1	FRONT AIR CON CONDENSOR COWLING (CONSISTENT)	TORN	285.00	285.00
	LESS 10% DISCOUNT		-	-593.77
			8,695.10	5,343.93
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER LOWER GRILLE CLIPS (SN) (CONSISTENT)	NOT NECESSARY	65.00	-
1	FRONT NUMBER PLATE AND BASE (SN)(CONSISTENT)	BENT	48.00	40.00
			113.00	40.00
<b><u>LABOUR</u></b>				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		80.00	20.00
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETC.S.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		800.00	400.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		700.00	580.00
	TO REMOVE & REFIX AIR CON,RE-FILL AIR CON GAS & TEST FOR LEAKAGES.		200.00	100.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		50.00	30.00
			1,830.00	1,130.00
<b>GRAND TOTAL</b>			<b>10,638.10</b>	<b>6,513.93</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,200.00</b>

Report Ref No. CC4/ASM20005375/Uea3q2

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.