

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005394/UGA3Q2

Date: 30/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994047

Claimant
Vehicle No : YP4957H **Insured Vehicle No :** SLQ8977Y

Date of Loss: 25/04/2020 Nature of Claim: TP Claim No: 7422812201SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP4957H		
Make & Model:	MITSUBISHI FUSO FIGHTER, 7.5 D FK62 Series (FK62FMZ1RDEB) (M)	Engine No:	6M60221307
Reg. Date:	28/12/2016 (Man. Year: 2016)	Chassis No:	FK62FMA30243
Colour:	White	Odometer:	132540 km
Engine Capacity:	7545 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/70 R19.5	Rear Tyre Size:	245/70 R19.5 (D)
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5/5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,250.00	3,639.00	3,611.00	49.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,000.00	1,500.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,750.00	4,639.00	5,111.00	52.42
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	9,750.00	3,700.00	6,050.00	62.05
+ GST 7.00/7.00% (S\$)	682.50	259.00	423.50	62.05
Nett Amount (S\$)	10,432.50	3,959.00	6,473.50	62.05
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,566.45		

INSPECTION

Date of Assignment: 27/04/2020

Date Inspected: 27/04/2020 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LICENCE PLATE LAMP	Cracked	100.00 FL	*100.00 FL
2	1		*REAR LICENCE PLATE BRACKET (2PCS)	Bent (1Pc Only)	400.00 FL	*200.00 FL
3	1		*REAR CROSS-MEMBER	Repair	500.00 FL	*- FL
4	2		*REAR CROSS-MEMBER WOODEN BAR (STRAIGHT AND LONG)	Cracked	2,400.00 FS	*1,700.00 FS
5	1		*REAR STEP WOODEN BAR	Cracked	300.00 FS	*300.00 FS
6	1		*REAR END PANEL WOODEN (TOP)	Not Necessary	700.00 FS	*- FS
7	8		*REAR CROSS-MEMBER WOODEN BAR U-BOLT	Not Necessary	800.00 FS	*- FS
8	20		*REAR CROSS-MEMBER WOODEN SCREW	Not Necessary	600.00 FS	*- FS
9	1		*REAR LICENCE PLATE	Bent	50.00 FS	*14.00 FS
10	1		*REAR SAFETY BAR	Bent	1,000.00 FS	*1,000.00 FS
11	2		*REAR SAFETY BAR BRACKET	Bent / Twisted	500.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 7,350.00 3,714.00
- List Item Discount on L Items 10.00/25.00% (\$\$) 100.00 75.00

Total Parts (\$\$) 7,250.00 3,639.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	20.00
2	TO LIFT-UP THE REAR CARGO FOR FACILITIES REPAIR	New	800.00	380.00
3	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	750.00	400.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	850.00	200.00
Gross Labour Cost (S\$)			2,500.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >