

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005395/UKA3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070034878

Claimant
Vehicle No : SLF8056M **Insured Vehicle No :** GBJ3314Z

Date of Loss: 23/04/2020 Nature of Claim: TP Claim No: 7057800001SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF8056M		
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Engine No:	2AZC062145
Reg. Date:	05/10/2006 (Man. Year: 2006)	Chassis No:	ACR500006145
Colour:	White	Odometer:	176305 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,020.37	5,329.75	4,690.62	46.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	1,180.00	2,920.00	71.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,120.37	6,509.75	7,610.62	53.90
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	14,120.37	5,200.00	8,920.37	63.17
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,702.00		

INSPECTION

Date of Assignment: 27/04/2020

Date Inspected: 27/04/2020 Inspected At:

Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,662.60 FL	*981.10 FL
2	16		*FRONT BUMPER CLIPS	Necessary	62.40 FL	*62.40 FL
3	2		*FRONT BUMPER O/S & N/S SIDE RETAINER	Not Necessary	165.60 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	401.20 FL	*401.20 FL
5	2		*FRONT BUMPER REINFORCEMENT O/S & N/S STAY	Not Necessary	370.00 FL	*- FL
6	1		*FRONT BUMPER O/S TOW BAR COVER	Torn	28.80 FL	*28.80 FL
7	1		*FRONT BUMPER O/S AIR SCOOP GARNISH	Torn	67.90 FL	*67.90 FL
8	1		*FRONT BUMPER CENTRE LOWER AIRSCOOP GRILLE	Cut	231.90 FL	*231.90 FL
9	1		*FRONT BUMPER CENTRE LOWER GRILLE MOULDING CHROME	Cracked	160.30 FL	*160.30 FL
10	1		*FRONT GRILLE	Cracked	607.60 FL	*607.60 FL
11	8		*FRONT GRILLE CLIPS	Not Necessary	31.20 FL	*- FL
12	1		*FRONT GRILLE TOP GARNISH	Not Necessary	460.30 FL	*- FL
13	2		*O/S & N/S HEAD LAMP ASSY (HID)	Holder Cracked	4,446.20 FL	*4,446.20 FL
14	1		*O/S HEAD LAMP BRACKET	Not Necessary	133.50 FL	*- FL
15	1		*FRONT O/S FENDER INNER SHIELD (TORN)	Not Consistent With The Impact	253.80 FL	*- FL
16	8		*FRONT O/S FENDER INNER SHIELD CLIPS	Not Necessary	31.20 FL	*- FL
17	1		*FRONT TOP PANEL	Repair	262.90 FL	*- FL
18	1		*FRONT TOP PANEL GARNISH	Not Necessary	222.80 FL	*- FL
19	8		*FRONT TOP PANEL GARNISH CLIPS	Not Necessary	31.20 FL	*- FL
20	2		*FRONT O/S & N/S HEAD LAMP PANEL	Repair	525.80 FL	*- FL
21	8		*FRONT ENGINE DUCT COVER CLIPS	Not Necessary	31.20 FL	*- FL
22	1		*AIR COND CONDENSER	Not Necessary	1,463.80 FL	*- FL
23	1		*FRONT N/S WIPER SPORT RIM	Repair	1,582.70 FL	*- FL
24	1		*FRONT NUMBER PLATE & FRAME	Cracked	45.00 FS	*40.00 FS
25	1		*FRONT BUMPER SPONGE DAMPER	Torn	65.60 FL	*65.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,345.50 7,093.00
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,325.13 1,763.25

Total Parts (\$\$) 10,020.37 5,329.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	60.00	20.00
2	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	120.00	60.00
3	TO REMOVE,REFIX AIR COND PARTS & REFILL RA134 GAS	New	150.00	0.00
4	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	120.00	0.00
5	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT FRONT TOP PANEL,HEAD LAMP PANEL,WHEEL HOUSE PANEL ,FRONT LOWER MEMBER & NECESSARY PARTS,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,550.00	500.00
6	JACK ,STTRAIGHTEN & KNOCKING OUT FRONT O/S CHASSIS SAME MEMBER	New	450.00	0.00
7	PUTTY & RESPRAY PAINTING (PEARL COLOUR) ON ALL AFFECTED ACCIDENT PARTS	New	1,650.00	600.00
Gross Labour Cost (\$\$)			4,100.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >