

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20005398/GSF3E2  
**Date:** 08/05/2020

### REFERENCE

|  |                               |                        |
|--|-------------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: 2100418735         |                        |
| Claimant Vehicle No : SJN2533Z                         | Insured Vehicle No : SBC7777G |                        |
| Date of Loss: 24/04/2020                               | Nature of Claim: TP           | Claim No: 7383843948SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SJN2533Z                     | Engine No:  | 1NZX865360        |
| Make & Model:               | TOYOTA VIOS, 1.5 G (A)       | Chassis No: | MR053HY9305100501 |
| Reg. Date:                  | 10/02/2009 (Man. Year: 2009) | Odometer:   | 256229 km         |
| Colour:                     | Blue                         |             |                   |
| Engine Capacity:            | 1497 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 195/60 R15       | Rear Tyre Size:  | 195/60 R15       |
| Front Left Side:  | Double Star 5 mm | Rear Left Side:  | Double Star 5 mm |
| Front Right Side: | Double Star 5 mm | Rear Right Side: | Double Star 5 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

|                             |                          |  |
|-----------------------------|--------------------------|--|
| Date of Assignment:         | 27/04/2020               |  |
| Date Inspected:             | 27/04/2020 Inspected At: | King Auto Air Conditioning Service (HQ)<br>BLK 176 SIN MING DRIVE, #02-10 SIN<br>MING AUTOCARE<br>Singapore 575721 |
| Estimated Period of Repair: | 6.0 days                 |  |

**Adjuster:** XING GUO QIANG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|-----------|------------|--------|
| 1   | 1   |          | *REAR NUMBER PLATE          | Scratched | 0.00 F     | *- F   |
| 2   | 1   |          | *REAR NUMBER PLATE BASE     | Scratched | 0.00 F     | *- F   |
| 3   | 1   |          | *REAR BUMPER                | Deformed  | 0.00 F     | *- F   |
| 4   | 1   |          | *REAR BUMPER CLIPS          | Necessary | 0.00 F     | *- F   |
| 5   | 2   |          | *REAR BUMPER SIDE RETAINER  | Deformed  | 0.00 F     | *- F   |
| 6   | 2   |          | *REAR BUMPER REFLECTOR      | Scratched | 0.00 F     | *- F   |
| 7   | 1   |          | *REVERSE SENSOR             | Damaged   | 0.00 F     | *- F   |
| 8   | 1   |          | *REAR END PANEL             | Bent      | 0.00 F     | *- F   |
| 9   | 1   |          | *REAR END PANEL TOP GARNISH | Deformed  | 0.00 F     | *- F   |
| 10  | 1   |          | *REAR LH TAILLAMP           | Cracked   | 0.00 F     | *- F   |
| 11  | 1   |          | *REAR RH TAILLAMP           | Cut       | 0.00 F     | *- F   |
| 12  | 1   |          | *BOOTLID                    | Bent      | 0.00 F     | *- F   |
| 13  | 3   |          | *BOOTLID EMBLEM             | Necessary | 0.00 F     | *- F   |
| 14  | 1   |          | *BOOTLID LOCK               | Bent      | 0.00 F     | *- F   |
| 15  | 1   |          | *BOOTLID RUBBER             | Twisted   | 0.00 F     | *- F   |
| 16  | 1   |          | *SPARE TYRE BOARD           | Deformed  | 0.00 F     | *- F   |
| 17  | 1   |          | *SPARE TYRE PANEL           | Repair    | 0.00 F     | *- F   |
| 18  | 1   |          | *REAR EXHAUST PIPE          | Repair    | 0.00 F     | *- F   |
| 19  | 2   |          | *SPARE TYRE SPONGE          | Deformed  | 0.00 F     | *- F   |

F=Franchise part.

|                          |             |             |
|--------------------------|-------------|-------------|
| <b>Total Parts (S\$)</b> | <b>0.00</b> | <b>0.00</b> |
|--------------------------|-------------|-------------|

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

**< END OF ESTIMATES >**