



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7163L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BONNET (CONSISTENT)	NOT NECESSARY	1,045.80	-
2	FRONT BONNET STOPPER @\$35.80 (CONSISTENT)	NOT NECESSARY	71.60	-
1	HEADLAMP RH (CONSISTENT)	CUT	2,160.80	2,160.80
1	HEADLAMPS LOWER BRACKET RH (CONSISTENT)	NOT NECESSARY	135.60	-
1	FRONT GRILLE @\$124.60 (CONSISTENT)	NOT NECESSARY	249.20	-
2	FRONT GRILLE OUTER GARNISH @\$125.80 (CONSISTENT)	NOT NECESSARY	251.60	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	745.30	745.30
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	NECESSARY	93.54	93.54
1	FRONT BUMPER WASHER COVER RH (CONSISTENT)	NOT NECESSARY	69.70	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	458.90	-
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	345.80	-
1	FRONT BUMPER TOWING COVER (CONSISTENT)	NOT NECESSARY	68.70	-
1	FRONT BUMPER FOGLAMP RH (CONSISTENT)	DEFORMED	456.30	456.30
1	FRONT BUMPER FOGLAMP COVER RH (CONSISTENT)	DEFORMED	95.70	95.70
1	FRONT FOGLAMP CHROME GARNISH RH (CONSISTENT)	CUT	85.20	85.20
1	FRONT SIGNAL LAMP RH (CONSISTENT)	NOT NECESSARY	165.30	-
1	FRONT BUMPER LOWER COVER (CONSISTENT)	NOT NECESSARY	298.70	-
1	FRONT FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	753.20	-
1	FRONT FENDER INNER COWLING RH (CONSISTENT)	NOT NECESSARY	168.90	-
1	FRONT RIM RH (CONSISTENT)	NOT NECESSARY	986.50	-
	LESS 10% DISCOUNT		-870.63	-
	LESS 20% DISCOUNT		-	-727.37
			7,835.71	2,909.47
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT HEADLAMP CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	20.00
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT BUMPER LOWER COVER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER INNER COWLING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			120.00	50.00
	<b>LABOUR</b>			
	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT,WELD ,REALIGN AND ALIGNE ALL PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH .		1,200.00	250.00
	TO RESPRAY AFFECTED AREAS .		1,200.00	400.00
	TO TUFFCOAT AFFECTED AREA.	NOT NECESSARY	200.00	-
	TO APPLY SEALANT TO AFFECTED AREA.	NOT NECESSARY	200.00	-
	TO CONDUCT WIRING CHECK ON FRONT HEADLAMP AND RESETTNG.		120.00	30.00
			2,920.00	680.00
<b>GRAND TOTAL</b>			<b>10,875.71</b>	<b>3,639.47</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,900.00</b>

Report Ref No. CC4/ASM20005402/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.