



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2003779
INV Date 11/05/2020
Reference CS/AGI20005432/Ktf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. FK 7780G
Insured Veh. SLV 4513C
Claim No. C10006211/KY
Policy No.
Accident Date 22/04/2020
Inspection Date 28/04/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20005432/Ktf3n2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 11-05-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 4513C	Veh. Inspected	FK 7780G
Policy No.		Coverage (\$)	0.00
Claim No.	C10006211/KY	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	27/04/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA CG 125	c.c	124
Engine No.	HIDDEN	Year of Reg.	1993
Chassis No.	CG1251645353	Colour	WHITE
Odometer	8069	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	2.75X18	BRIDGESTONE	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	3.50X18	ESTRON	7 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/04/2020	Inspection Date	28/04/2020
Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FK 7780G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	CLUTCH LEVER-LH	CRACKED	48.00	48.00
1	ENGINE COVER-LH (SILVER)	SERVICEABLE	98.00	-
1	FORK OIL SEAL-LH	NOT NECESSARY	38.00	-
1	FORK OIL SEAL-RH	NOT NECESSARY	38.00	-
1	FRONT FORK-LH	TWISTED	386.00	322.00
1	FRONT FORK-RH	TWISTED	386.00	322.00
1	FRONT FORK TUBE-LH	DISTORTED	222.00	222.00
1	FRONT FORK TUBE-RH	DISTORTED	222.00	222.00
1	FRONT WHEEL RIM	SERVICEABLE	365.00	-
1	GEAR PANEL	DISTORTED	52.00	52.00
1	HANDLE BAR	SERVICEABLE	165.00	-
1	HEAD LAMP	SERVICEABLE	280.00	-
1	IU UNIT	SERVICEABLE	180.00	-
1	REAR SIGNAL LAMP-LH	SERVICEABLE	84.00	-
1	SPEEDOMETER	SERVICEABLE	395.00	-
1	WING MIRROR-LH	SERVICEABLE	144.00	-
	LESS 10% DISCOUNT		-	-118.80
			3,103.00	1,069.20
<u>SPECIAL NETT ITEMS</u>				
1	FRONT FUEL TANK (LOCAL REPAIR)(SN)	DENTED	485.20	60.00
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	28.00	-
			513.20	60.00
<u>LABOUR</u>				
	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY.		800.00	180.00
	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		700.00	150.00
	TO ALIGN MAIN BODY FRAME.	NOT NECESSARY	280.00	-
	TO TOW VEHICLE TO WORKSHOP.		80.00	30.00
			1,860.00	360.00



GRAND TOTAL		5,476.20	1,489.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00

Report Ref No. CS/AGI20005432/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FK 7780G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FK 7780G

RE-INSPECTION

