

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005434/UGA3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900130787

Claimant
Vehicle No : FBJ737G **Insured Vehicle No :** SMN2956B

Date of Loss: 25/02/2020 Nature of Claim: TP Claim No: 5072035021SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ737G		
Make & Model:	YAMAHA JUPITER MX, 134cc HC	Engine No:	50C626051
Reg. Date:	23/12/2013 (Man. Year: 2013)	Chassis No:	MH350C004DK626121
Colour:	Red	Odometer:	47390 km
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/80-17	Rear Tyre Size:	90/80-17
Front Left Side:	Corsa 6 mm	Rear Left Side:	Corsa 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,100.70	1,793.30	1,307.40	42.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	510.00	285.00	225.00	44.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,610.70	2,078.30	1,532.40	42.44
Approved Total (Overridden) (\$\$)		1,650.00		
Nett Amount (\$\$)	3,610.70	1,650.00	1,960.70	54.30
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 27/04/2020

Date Inspected: 28/04/2020 Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Bent / Twisted	640.00 FL	*520.00 FL
2	1		*FRONT WHEEL RIM	Repair	280.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
4	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*- FL
5	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
6	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
7	1		*HANDLE -BAR	Bent	105.00 FL	*105.00 FL
8	1		*SET HAND GRIP	Not Necessary	55.00 FL	*- FL
9	2		*SIDE MIRRORS -R/L	Missing	110.00 FL	*110.00 FL
10	1		*CLUTCH LEVER	Scratched	30.00 FL	*30.00 FL
11	1		*FRONT SIGNALS	N/S Cracked	140.00 FL	*70.00 FL
12	1		*SET FAIRING ASSY	Cut / Cracked	535.00 FL	*535.00 FL
13	1		*CENTRE INNER PANEL	Cracked	145.00 FL	*145.00 FL
14	1		*FRONT FOOTREST BRACKETS	Bent	65.00 FL	*65.00 FL
15	1		*FRONT FOOTREST RUBBER -L/H	Torn	35.00 FL	*35.00 FL
16	1		*GEAR PEDAL	Bent	42.00 FL	*42.00 FL
17	1		*REAR FOOTREST- L/H	Serviceable	40.00 FL	*- FL
18	1		*REAR FOOTREST BRACKET- L/H	Not Necessary	78.00 FL	*- FL
19	1		*SIDE STAND	Not Necessary	75.00 FL	*- FL
20	1		*MAIN STAND	Not Necessary	95.00 FL	*- FL
21	1		*FRONT HORN COVER INNER	Not Necessary	75.00 FL	*- FL
22	1		*BALANCER	Scratched	45.00 FL	*45.00 FL
23	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
24	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
25	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
26	1		*SET STEERING CONE	Necessary	95.00 FS	*95.00 FS
27	1		*E.R.P IU	Serviceable	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,402.00	1,982.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	301.30	188.70
Total Parts (\$\$)	3,100.70	1,793.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	250.00
Gross Labour Cost (\$\$)			510.00	285.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >