

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20005436/KBA3Q2

Date:

14/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900117939

Claimant Vehicle No : SKL9192B**Insured Vehicle No :**

SDR3030B

Date of Loss: 04/04/2020

Nature of Claim:

TP

Claim No:

5414133031SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL9192B**
 Make & Model: MERCEDES-BENZ C200, 2.0 AMG (A)
 Reg. Date: 15/12/2017 (Man. Year: 2015)
 Colour: Metallic Pearl White
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 27492030484676
 Chassis No: WDD2050422R124820
 Odometer: 81595 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 275/30 R19
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,960.50	8,195.42	1,765.08	17.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,060.00	570.00	34.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,590.50	9,255.42	2,335.08	20.15
+ Car Rental (3.0 x S\$180.00/day) (S\$)		540.00		

Nett Liability (S\$)**9,795.42**INSPECTION

Date of Assignment: 27/04/2020

Date Inspected: 19/05/2020

Estimated Period of Repair: 4.0 days

Inspected At: Guan Motor Works (HQ)
176 Sin Ming Drive #02-03 Sin Ming Autocare
Singapore 575721**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (AMG)	Buckled / Mtg Cracked	1,951.00 FL	*1,951.00 FL
2	2		*FRONT BUMPER PARKING SENSOR	Dented / Shorted	612.00 FL	*570.00 FL
3	1		*FRONT BUMPER RH TOW COVER	Serviceable	51.00 FL	*- FL
4	1		*FRONT BUMPER RH FOG LAMP GRILLE	Serviceable	80.00 FL	*- FL
5	1		*FRONT BUMPER CENTRE GRILLE	Serviceable	151.00 FL	*- FL
6	1		*FRONT BUMPER NUMBER PLATE GARNISH	Dented	159.00 FL	*102.50 FL
7	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	92.00 FL	*92.00 FL
8	1		*FRONT BUMPER INNER REINFORCEMENT	Bent	489.00 FL	*392.30 FL
9	1		*FRONT BUMPER INNER FOAM	Cracked	192.00 FL	*192.00 FL
10	1		*RH HEADLAMP	Mtg Cracked	3,654.00 FL	*3,654.00 FL
11	1		*FRONT GRILLE	Dented / Cut	879.00 FL	*680.00 FL
12	1		*FRONT RH FENDER	Repair	1,035.00 FL	*- FL
13	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*45.00 FS
14	1		*FRONT BUMPER LOWER CARBON FIBER SKIRTING (AMG)	Cracked	1,500.00 FS	*1,280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,895.00	8,958.80
- List Item Discount on L Items 10.00/10.00% (\$)	934.50	763.38
Total Parts (\$)	9,960.50	8,195.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE/REFIT ,PANEL BEATING ,CUTTING WELDING AND REPLACEMENT OF DAMAGES	New	700.00	500.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	800.00	500.00
3	TO CHECK WIRING /REINSTALL & RESET FRONT PARKING SENSORS	New	80.00	60.00
4	TO APPLY ANTI RUST TREATMENT	New	50.00	0.00
Gross Labour Cost (\$\$)			1,630.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >