



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9647H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER	TO REPAIR SEE LABOUR	418.00	-
1	FRT BUMPER SIDE BRKT RH	NOT NECESSARY	28.00	-
1	FRT BUMPER BRKT RH	NOT NECESSARY	35.00	-
1	HEADLAMP RH	POLISH	1,993.65	-
1	FRT FENDER RH	DENTED	490.70	490.70
1	FRT FENDER BLUE DRIVE RH	NECESSARY	26.60	26.60
1	FRT WHEEL CAP RH	SCRATCHED	346.40	346.40
	LESS 20% DISCOUNT		-667.67	-172.74
			2,670.68	690.96
<u>NETT ITEMS</u>				
1	FRT DAVANTI TYRE RH (N)	NOT NECESSARY	216.00	-
1	FRT DOOR COMFORTDELGRO RH (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-29.10	-7.50
			261.90	67.50
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER.		600.00	480.00
	SPRAY PAINT CHARGE (POLISH HEADLAMP \$50.00).		750.00	650.00
	CHECK ALL LIGHTING.		40.00	30.00
	TUFF COAT ON AFFECTED PARTS.		60.00	50.00
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,570.00	1,210.00
GRAND TOTAL			4,502.58	1,968.46

RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,968.46
--	--	--	-----------------

Report Ref No. NS/INC20005460/Fyf3s2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.