Page 1 of 3 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005465/EYF3E2

Date: 18/05/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070061497 Claimant Vehicle SLL7997Y Insured Vehicle No: **GBD7638U**

Date of Loss: 24/04/2020 Nature of Claim: TP Claim No: 2519784501SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL7997Y**

Make & Model: **KIA FORTE K3, 1.6 (A)** Engine No: G4FGGH651268 Reg. Date: 10/03/2017 (Man. Year: 2017) Chassis No: KNAFJ411MH5708118

Colour: Odometer: 99590 km

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

195/65 R15 Front Tyre Size: 195/65 R15 Rear Tyre Size: Front Left Side: Rear Left Side: Kumho 5 mm Kumho 5 mm Rear Right Side: Front Right Side: Kumho 5 mm Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/04/2020

Date Inspected: 29/04/2020 Inspected At: Eclipse Auto Pte Ltd (HQ)

155 Kaki Bukit Avenue 1, Shun Li

Industrial Park #01-01 Singapore 416012

Estimated Period of Repair: 5.0 days

Manager: YVONNE WONG YIN CHENG CHEN TSUE YEE Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Cut	0.00 F	*- F
2	1		*REAR NUMBER PLATE GARNISH	Cut	0.00 F	*- F
3	1		*REAR BUMPER	Dented	0.00 F	*- F
4	1		*REAR BUMPER LOWER COVER, LH	Torn	0.00 F	*- F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT	Broken	0.00 F	*- F
8	3		*REAR BUMPER REINFORCEMENT BRACKET	Deformed	0.00 F	*- F
9	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F
10	1		*REVERSE SENSOR	Broken	0.00 F	*- F
11	1		*REAR END PANEL	Dented	0.00 F	*- F
12	1		*REAR END PANEL INNER TRIM	Deformed	0.00 F	*- F
13	1		*BOOTLID	Dented	0.00 F	*- F
14	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
15	1		*BOOTLID LAMP RH	Broken	0.00 F	*- F
16	1		*BOOTLID LOCK	Bent	0.00 F	*- F
17	1		*BOOTLID RUBBER	Torn	0.00 F	*- F
r=rra	anchise	рап.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >