11/4/22, 3:40 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20005468/KPA3Q2

**Date:** 04/11/2022

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993872

Claimant Vehicle SHD258H Insured Vehicle No: SMM560C

No: SINDESON INSURED VEHICLE NO. SININISONCE

Date of Loss: 27/04/2020 Nature of Claim: TP Claim No: 0479826315SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD258H

 Make & Model:
 RENAULT LATITUDE, 2.0 L (A)
 Engine No:
 M9R8839C002899

 Reg. Date:
 20/11/2015 (Man. Year: 2015)
 Chassis No:
 VF1ABL15AUC282299

Colour: Metallic White/Red Odometer: 559427 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Sailun 8 mm Rear Left Side: Sailun 8 mm
Front Right Side: Sailun 8 mm Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,985.61	2,101.63	27,883.98	92.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,860.00	890.00	17,970.00	95.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,845.61	2,991.63	45,853.98	93.88
Approved Total (Overridden) (S\$)		2,400.00		
(\$\$)	48,845.61	2,400.00	46,445.61	95.09
+ GST 7.00/7.00% (S\$)	3,419.19	168.00	3,251.19	95.09
Nett Amount (S\$)	52,264.80	2,568.00	49,696.80	95.09
Global Sum	Settlement (S\$)	0.00		

**INSPECTION** 

Date of Assignment: 28/04/2020

Trans Cab Auto Services Pte Ltd - Amk (HQ)

Date Inspected: 28/04/2020 Inspected At: No 2 Ang Mo Kio St 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	747.20 FL	*747.20 FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*-FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT RH	Distorted	101.40 FL	*101.40 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
8	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*-FL
9	1		*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
10 11	1		*HEADLAMP RANGLEDT BU	Mtg Cracked	743.60 FL	*743.60 FL *- FL
11 12	1		*HEADLAMP PANEL FRT RH  *FENDER PANEL FRT RH	Repair Bent	128.30 FL 437.10 FL	*437.10 FL
13	1			Distorted		*191.40 FL
13 14	1		*WHEELARCH FRT RH  *FENDER BRACKET LOWER RH	Serviceable	191.40 FL 11.80 FL	*-FL
15	1		*FENDER GRILL WING HOLDER RH	Serviceable	80.70 FL	*-FL
16	1		*FENDER BRACKET FRT RH	Repair	106.40 FL	
17	1		*FENDER INSULATOR RH	Serviceable	66.30 FL	*- FL
18	1		*TOW COVER FRT	Serviceable	60.90 FL	*- FL
19	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
20	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
21	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
22	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
23	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*- FL
 24	1		*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	*- FL
25	1		*BONNET	Repair	1,312.70 FL	*- FL
26	1		*BONNET INSULATOR	Serviceable	294.30 FL	*- FL
27	1		*BONNET STRUT RH	Serviceable	53.30 FL	*- FL
28	1		*BONNEY HINGE RH	Serviceable	237.40 FL	*- FL
29	1		*BONNET LOCK	Serviceable	152.80 FL	*- FL
30	1		*LOWER ARM RH L70Y	Serviceable	192.70 FL	*- FL
31	1		*KNUCKLE ARM RH L70Y	Serviceable	481.50 FL	*- FL
32	1		*ABSORBER FRT RH L70Y	Serviceable	203.50 FL	*- FL
33	1		*ABSORBER MOUNTING KIT FRT RH	Serviceable	273.60 FL	*- FL
34	1		*DRIVESHAFT RH	Serviceable	1,355.70 FL	*- FL
35	1		*STABILIZER BAR FRT	Serviceable	427.90 FL	*- FL
36	1		*KNUCKLE HUB+BEARING RH L70Y	Serviceable	272.30 FL	*-FL
37	1		*STEERING PINION RACK L70Y	Serviceable	3,765.30 FL	*-FL
38	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	*-FL
39	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*-FL
40	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	*- FL
41	1		*SUBFRAME OUTER FRT	Serviceable	1,094.20 FL	*- FL
42	1		*SUBFRAME BRACKET OUTER RH	Serviceable	49.00 FL	*- FL
43	1		*SUBFRAME INNER FRT L70Y	Serviceable	746.00 FL	*- FL
44	1		*SUBFRAME SUPPORT INNER L70Y	Serviceable	69.50 FL	*-FL
45 46	1		*SUBFRAME BRACKET INNER RH L70Y	Serviceable	101.00 FL	*-FL
46	1		*FENDER PANEL SUPPORT FRT RH	Serviceable	432.00 FL	*-FL
47 40	1		*FENDER PANEL INNER FRT RH	Serviceable	838.40 FL	*- FL
48 40	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*-FL
49 50	1		*ROCKER PANEL OUTER BH	Serviceable	1,024.79 FL	*- FL * EL
50 51	1		*ROCKER PANEL OUTER RH	Serviceable	1,184.99 FL	*-FL
51 52	1		*DOOR PANEL FRT RH	Serviceable	2,844.66 FL	*- FL * El
52 52	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
53 54	1		*DOOR HARNESS WIRE RH	Serviceable	2,670.00 FL	*- FL *- FL
54 55	1		*A/C CONDENSER	Serviceable	1,537.80 FL	
55	1		*BUMPER CLIP FRT	Necessary	68.00 FS	*68.00 FS

11/4/2	1/4/22, 3:40 PM Adjuster Report					
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	15.00 FS	*- FS
57	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	15.00 FS	*- FS
58	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
59	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
60	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	25.00 FS	*- FS
61	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
62	1		*WHEELARCH CLIP FRT RH	Necessary	35.00 FS	*35.00 FS
63	1		*FRONT RENAULT TYRE	Serviceable	300.00 FS	*- FS
64	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
65	1		*FRONT RENAULT TYRE RIM	Serviceable	380.00 FS	*- FS
66	1		*SET RADIATOR GRILLE SCREW	Not Necessary	20.00 FS	*- FS
67	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
68	1		*FRONT RENAULT TYRE RIM COVER	Serviceable	60.00 FS	*- FS
69	1		*FRONT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
70	1		*FRONT DOOR STICKER CLASSIC	Not Necessary	80.00 FS	*- FS
71	1		*WINDSCREEN MOULDING	Not Necessary	180.00 FS	*- FS
72	2		*FRONT WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
73 F=Fra	1 anchise	part. S=SpcN	*FRONT WINDSCREEN INNER SPONGE SEAL Nett. L=ListItemDisc.	Not Necessary	120.00 FS	*- FS
				Sub Total (S\$)	33,114.12	2,323.70
			- List Item Discount on L Ite	V ./	3,128.51	222.07
				Total Parts (S\$)	29,985.61	2,101.63
			Report was unsubmitted during th		29,985.61	2,101.63

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	440.00
2	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New ·	7,500.00	400.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
6	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
10	TO DISMANTLE AND REFIT ENGINE CROSS -MEMBER AND ENGINE MOUNTING	New	380.00	0.00
11	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
12	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
13	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
14	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
15	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
16	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
17	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
	Gross Labour Cost (S\$)		18,860.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >