Page 1 of 3 Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005480/ETF3E2

Date: 13/05/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070006478 Claimant Vehicle FBD5930M **Insured Vehicle No:** SMR7636X

Date of Loss: 19/04/2020 Nature of Claim: TP Claim No: 3518669622SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBD5930M

SUZUKI HAYATE, 125cc (M) Make & Model: Engine No: F494TH201979 Reg. Date: 12/05/2009 (Man. Year: 2008) Chassis No: CF4EATH201979

Colour: Odometer: 54264 km Black

**Engine Capacity:** 125 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

70/80-17 Front Tyre Size: Rear Tyre Size: 60/70-16 Front Left Side: Rear Left Side: Dunlop 5 mm Dunlop 5 mm

Rear Right Side: Front Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 29/04/2020

Date Inspected: GP MOTORING PTE LTD (HQ) 30/04/2020 Inspected At:

282 Macpherson Road Singapore 348607

Estimated Period of Repair: 4.0 days

**CHEN TSUE YEE** Manager: DENISE TAY KWEE CHENG Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	Cut	0.00 F	*-F
2	1		*STEERING CONE	Necessary	0.00 F	*- F
3	1		*HANDLE BAR	Bent	0.00 F	*- F
4	1		*HANDLE BAR GRIP	Cut	0.00 F	*- F
5	1		*BRAKE LEVER (LH)	Broken	0.00 F	*- F
6	2		*SIDE FAIRING	Broken	0.00 F	*- F
7	2		*FAIRING SHIELD (FRONT)	Cut	0.00 F	*- F
8	1		*REAR FAIRING	Broken	0.00 F	*- F
9	1		*FAIRING LOWER	Cut	0.00 F	*- F
10	1		*ENGINE COVER (RH)	Broken	0.00 F	*- F
11	1		*ENGINE FAN CLUTCH (RH)	Broken	0.00 F	*- F
12	1		*HANDLE BAR (REAR)	Cut	0.00 F	*- F
13	2		*REAR FOOT REST	Broken	0.00 F	*- F
14	2		*REAR FOOT REST BRACKET	Broken	0.00 F	*- F
15	1		*EXHAUST MUFFLER HEAT SHIELD	Missing	0.00 F	*- F
16	1		*EXHAUST MUFFLER ASSY	Dented	0.00 F	*- F
17	1		*REAR RH SHOCK ABSORBER	Bent	0.00 F	*- F
18	1		*REAR RIM	Cut	0.00 F	*- F
19	1		*SWING ARM (REAR)	Broken	0.00 F	*- F
20	1		*REAR TAILLAMP	Broken	0.00 F	*- F
21	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
F=Fra	anchise	part.		_		
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >