

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005492/KPA3Q2
Date: 05/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900154128
Claimant Vehicle No :	SLV1555B	Insured Vehicle No :	SMN7339A
Date of Loss:	28/04/2020	Nature of Claim:	TP
		Claim No:	6366112547SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV1555B		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5966958
Reg. Date:	22/12/2017 (Man. Year: 2017)	Chassis No:	RU31266937
Colour:	Metallic Silver	Odometer:	194980 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 7 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	181.20	0.00	181.20	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	700.00	280.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,161.20	700.00	461.20	39.72
+ GST 7.00/7.00% (S\$)	81.28	49.00	32.28	39.71
Nett Amount (S\$)	1,242.48	749.00	493.48	39.72
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
Nett Liability (S\$)		909.00		
Global Sum Settlement (S\$)		900.00		

INSPECTION

Date of Assignment:	11/05/2020	
Date Inspected:	11/05/2020 Inspected At:	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint Singapore 568047
Estimated Period of Repair:	2.0 days	

4/5/2021

Adjuster Report

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL ARCH EXTENSION COVER RH	Repair	180.10 FL	*- FL
2	8		*REAR BUMPER CLIPS	Not Necessary	46.40 FL	*- FL
3	1		*REAR SIDE BUMPER RH (NPA)	Repair	0.00 FL	*- FL
4	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					226.50	0.00
- List Item Discount on L Items 20.00/20.00% (S\$)					45.30	0.00
Total Parts (S\$)					181.20	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPAIR ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	400.00	250.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR SIDE BUMPER RH, REAR BUMPER & ETC	New	500.00	450.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR .TO EFFECT REPAIR OF REAR BUMPER	New	80.00	0.00
Gross Labour Cost (\$\$)			980.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >