Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005495/UKA3Q2

**Date:** 26/08/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant
Whitela No: SFH1269Y

Insured Vehicle No: SH9984J

Vehicle No: SPH 1209Y Insured Vehicle No: SH9984J

Date of Loss: 25/04/2020 Nature of Claim: TP Claim No: MCT20040233

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SFH1269Y

Make & Model: NISSAN SYLPHY, 1.6 (A) Engine No: HR16928819C

Reg. Date: 16/07/2018 (Man. Year: 2018) Chassis No: MNTBBAB17Z0032471

Colour: Silver Odometer: 38363 km

Engine Capacity: 1598 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm
Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,144.22	1,130.54	3,013.68	72.72
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,098.00	938.00	2,160.00	69.72
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	7,242.22	2,068.54	5,173.68	71.44
	+ GST 7.00/7.00% (S\$)	506.96	144.80	362.16	71.44
	Nett Amount (S\$)	7,749.18	2,213.34	5,535.84	71.44

+ Car Rental (3.0 x S\$110.00/day + 7.00% GST) (S\$) 353.10

Nett Liability (S\$) 2,566.44

**INSPECTION** 

Date of Assignment: 30/04/2020

Date Inspected: 08/05/2020 Inspected At: Autolution Industrial Pte Ltd (Ubi)

19 Ubi Road 4

Singapore 408623

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Khanchna Pothuraj

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jul 2020)

Parts: 143 NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFH1269Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

**Total Parts (S\$)** 

Repairer's

4,144.22

Amount

1,130.54

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts No. Qtv Part No. Particulars

2 1 *SUNDRIES	110.	Qty	i ait ito.	i ai ticulai s	Condition	Kepairer 3	Amount
3 1 *LH HEADLAMP Scratched 815.00 FN *815.00 FN 1 *RH HEADLAMP Not Necessary 815.00 FN * 5 1 *RADIATOR TOP MOULDING BRACKET Not Necessary 397.90 FN * 6 1 *RADIATOR GRILLE Not Necessary 796.80 FN * 7 1 *ENERGY ABSORBER Not Necessary 244.50 FN * 8 1 *INNER BRACKET FRONT BUMPER Not Necessary 210.70 FN * 9 1 *LH SIDE BRACKET FRT BUMPER Not Necessary 25.10 FN * 10 1 *LOWER GRILLE FRONT BUMPER Not Necessary 302.50 FN * 11 1 *TOW HOOK COVER FRT BUMPER Not Necessary 31.00 FN * 12 6 *CLIP FRONT BUMPER Necessary 7.80 FN *7.80 FN	1	1		*LH FOGLAMP	Not Necessary	600.80FS	*-FS
4       1       *RH HEADLAMP       Not Necessary       815.00 FN       *         5       1       *RADIATOR TOP MOULDING BRACKET       Not Necessary       397.90 FN       *         6       1       *RADIATOR GRILLE       Not Necessary       796.80 FN       *         7       1       *ENERGY ABSORBER       Not Necessary       244.50 FN       *         8       1       *INNER BRACKET FRONT BUMPER       Not Necessary       210.70 FN       *         9       1       *LH SIDE BRACKET FRT BUMPER       Not Necessary       25.10 FN       *         10       1       *LOWER GRILLE FRONT BUMPER       Not Necessary       302.50 FN       *         11       1       *TOW HOOK COVER FRT BUMPER       Not Necessary       31.00 FN       *         12       6       *CLIP FRONT BUMPER       Necessary       7.80 FN       *7.80         13       1       *FRT LH FOGLAMP GARNISH       Not Necessary       130.10 FN       *         14       1       *FRONT BMPER       Deformed / Cut       472.30 FS       *472.30 FS         F=Franchise part. S=SpcNett. N=NettItemDisc.       Sub Total (S\$)       4,899.50       1,295.10	2	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
5         1         *RADIATOR TOP MOULDING BRACKET         Not Necessary         397.90 FN         *           6         1         *RADIATOR GRILLE         Not Necessary         796.80 FN         *           7         1         *ENERGY ABSORBER         Not Necessary         244.50 FN         *           8         1         *INNER BRACKET FRONT BUMPER         Not Necessary         210.70 FN         *           9         1         *LH SIDE BRACKET FRT BUMPER         Not Necessary         25.10 FN         *           10         1         *LOWER GRILLE FRONT BUMPER         Not Necessary         302.50 FN         *           11         1         *TOW HOOK COVER FRT BUMPER         Not Necessary         31.00 FN         *           12         6         *CLIP FRONT BUMPER         Necessary         7.80 FN         *7.80           13         1         *FRT LH FOGLAMP GARNISH         Not Necessary         130.10 FN         *           14         1         *FRONT BMPER         Deformed / Cut         472.30 FS         *472.30           F=Franchise part. S=SpcNett. N=NettitemDisc.         *         *4,899.50         1,295.10	3	1		*LH HEADLAMP	Scratched	815.00 FN	*815.00 FN
6         1         *RADIATOR GRILLE         Not Necessary         796.80 FN         *           7         1         *ENERGY ABSORBER         Not Necessary         244.50 FN         *           8         1         *INNER BRACKET FRONT BUMPER         Not Necessary         210.70 FN         *           9         1         *LH SIDE BRACKET FRT BUMPER         Not Necessary         25.10 FN         *           10         1         *LOWER GRILLE FRONT BUMPER         Not Necessary         302.50 FN         *           11         1         *TOW HOOK COVER FRT BUMPER         Not Necessary         31.00 FN         *           12         6         *CLIP FRONT BUMPER         Necessary         7.80 FN         *7.80           13         1         *FRT LH FOGLAMP GARNISH         Not Necessary         130.10 FN         *           14         1         *FRONT BMPER         Deformed / Cut         472.30 FS         *472.30           F=Franchise part. S=SpcNett. N=NettltemDisc.         *United St         4,899.50         1,295.10	4	1		*RH HEADLAMP	Not Necessary	815.00 FN	*- FN
7         1         *ENERGY ABSORBER         Not Necessary         244.50 FN         *           8         1         *INNER BRACKET FRONT BUMPER         Not Necessary         210.70 FN         *           9         1         *LH SIDE BRACKET FRT BUMPER         Not Necessary         25.10 FN         *           10         1         *LOWER GRILLE FRONT BUMPER         Not Necessary         302.50 FN         *           11         1         *TOW HOOK COVER FRT BUMPER         Not Necessary         31.00 FN         *           12         6         *CLIP FRONT BUMPER         Necessary         7.80 FN         *7.80           13         1         *FRT LH FOGLAMP GARNISH         Not Necessary         130.10 FN         *           14         1         *FRONT BMPER         Deformed / Cut         472.30 FS         *472.30           F=Franchise part. S=SpcNett. N=NettItemDisc.         Sub Total (S\$)         4,899.50         1,295.10	5	1		*RADIATOR TOP MOULDING BRACKET	Not Necessary	397.90 FN	*- FN
8       1       *INNER BRACKET FRONT BUMPER       Not Necessary       210.70 FN       *         9       1       *LH SIDE BRACKET FRT BUMPER       Not Necessary       25.10 FN       *         10       1       *LOWER GRILLE FRONT BUMPER       Not Necessary       302.50 FN       *         11       1       *TOW HOOK COVER FRT BUMPER       Not Necessary       31.00 FN       *         12       6       *CLIP FRONT BUMPER       Necessary       7.80 FN       *7.80         13       1       *FRT LH FOGLAMP GARNISH       Not Necessary       130.10 FN       *         14       1       *FRONT BMPER       Deformed / Cut       472.30 FS       *472.30 FS         F=Franchise part. S=SpcNett. N=NettItemDisc.     **Sub Total (S\$) 4,899.50 1,295.10	6	1		*RADIATOR GRILLE	Not Necessary	796.80 FN	*- FN
9 1 *LH SIDE BRACKET FRT BUMPER Not Necessary 25.10 FN * 10 1 *LOWER GRILLE FRONT BUMPER Not Necessary 302.50 FN * 11 1 *TOW HOOK COVER FRT BUMPER Not Necessary 31.00 FN * 12 6 *CLIP FRONT BUMPER Necessary 7.80 FN *7.80	7	1		*ENERGY ABSORBER	Not Necessary	244.50 FN	*- FN
10       1       *LOWER GRILLE FRONT BUMPER       Not Necessary       302.50 FN       *         11       1       *TOW HOOK COVER FRT BUMPER       Not Necessary       31.00 FN       *         12       6       *CLIP FRONT BUMPER       Necessary       7.80 FN       *7.80	8	1		*INNER BRACKET FRONT BUMPER	Not Necessary	210.70 FN	*- FN
11       1       *TOW HOOK COVER FRT BUMPER       Not Necessary       31.00 FN       *         12       6       *CLIP FRONT BUMPER       Necessary       7.80 FN       *7.80 FN         13       1       *FRT LH FOGLAMP GARNISH       Not Necessary       130.10 FN       *         14       1       *FRONT BMPER       Deformed / Cut       472.30 FS       *472.30 FS         F=Franchise part. S=SpcNett. N=NettlitemDisc.         Sub Total (S\$)       4,899.50       1,295.10	9	1		*LH SIDE BRACKET FRT BUMPER	Not Necessary	25.10 FN	*- FN
12       6       *CLIP FRONT BUMPER       Necessary       7.80 FN       *7.80 FN         13       1       *FRT LH FOGLAMP GARNISH       Not Necessary       130.10 FN       *         14       1       *FRONT BMPER       Deformed / Cut       472.30 FS       *472.30 FS         F=Franchise part. S=SpcNett. N=NettlitemDisc.       Sub Total (S\$)       4,899.50       1,295.10	10	1		*LOWER GRILLE FRONT BUMPER	Not Necessary	302.50 FN	*- FN
13       1       *FRT LH FOGLAMP GARNISH       Not Necessary       130.10 FN       *         14       1       *FRONT BMPER       Deformed / Cut       472.30 FS       *472.30 FS         F=Franchise part. S=SpcNett. N=NettItemDisc.       Sub Total (S\$)       4,899.50       1,295.10	11	1		*TOW HOOK COVER FRT BUMPER	Not Necessary	31.00 FN	*- FN
14       1       *FRONT BMPER       Deformed / Cut       472.30 FS       *472.30 FS         F=Franchise part. S=SpcNett. N=NettItemDisc.       Sub Total (S\$)       4,899.50       1,295.10	12	6		*CLIP FRONT BUMPER	Necessary	7.80 FN	*7.80 FN
F=Franchise part. S=SpcNett. N=NettltemDisc.  Sub Total (S\$) 4,899.50 1,295.10	13	1		*FRT LH FOGLAMP GARNISH	Not Necessary	130.10 FN	*- FN
Sub Total (S\$) 4,899.50 1,295.10	14	1		*FRONT BMPER	Deformed / Cut	472.30 FS	*472.30 FS
	F=Fra	nchise	part. S=SpcI	Nett. N=NettItemDisc.	_		
- Nett Item Discount on N Items 20.00/20.00% (\$\$) 755.28 164.56					Sub Total (S\$)	4,899.50	1,295.10
				- Nett Item Discount on N Item	ns 20.00/20.00% (S\$)	755.28	164.56
					-		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	LABOR CHARGES TO REPAIR LH RADIATOR S FRT LH FENDER & BONNET RENEW FRT BUM		1,950.00	390.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,100.00	500.00
3	RENEW BOTH HEADLAMP AND FOCUS	New	48.00	48.00
	Gross Labour Cost (S\$)		3,098.00	938.00
	Report was unsub	mitted during this print-out.		

< END OF ESTIMATES >