

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005498/UGA3Q2

Date: 03/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900234794

Claimant Vehicle No : SJR8258H **Insured Vehicle No :** SDL6498Y

Date of Loss: 30/04/2020 Nature of Claim: TP Claim No: 5642131143SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR8258H		
Make & Model:	HONDA CIVIC, 1.8 L 5AT (A)	Engine No:	R18A14013282
Reg. Date:	15/07/2009 (Man. Year: 2008)	Chassis No:	JHMF16309S202163
Colour:	White	Odometer:	229385 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,626.80	5,394.48	7,232.32	57.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	2,360.00	1,510.00	39.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,496.80	7,754.48	8,742.32	52.99
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	16,496.80	6,200.00	10,296.80	62.42
+ GST 7.00/7.00% (S\$)	1,154.78	434.00	720.78	62.42
Nett Amount (S\$)	17,651.58	6,634.00	11,017.58	62.42
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,116.00		
Global Sum Settlement (S\$)		7,100.00		

INSPECTION

Date of Assignment: 30/04/2020

Date Inspected: 30/04/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	855.10 F	*690.20 FL
2	1		*BOOTLID REAR LOGO	Necessary	50.00 F	*50.00 FL
3	1		*BOOTLID MUGEN EMBLEM	Necessary	105.00 F	*105.00 FL
4	1		*BOOTLID RR EMBLEM	Necessary	98.00 F	*98.00 FL
5	1		*BOOTLID INNER LOCK	Twisted	99.00 F	*99.00 FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	218.00 F	*218.00 FL
7	2		*BOOTLID REFLECTORS	Cracked	681.00 F	*681.00 FL
8	1		*BOOTLID CIVIC EMBLEM	Not fitted	33.00 F	*- FL
9	1		*BOOTLID INNER TRIM	Not Necessary	295.00 F	*- FL
10	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
11	1		*REAR BUMPER	Dented / Deformed	688.00 F	*688.00 FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	70.00 F	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*REAR BUMPER GARNISH O/S	Cracked	35.00 F	*35.00 FL
15	1		*REAR END PANEL	Badly Dented	380.00 F	*380.00 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	245.00 F	*245.00 FL
17	1		*REAR FLOOR PANEL	Repair	990.10 F	*- FL
18	1		*REAR FLOOR PANEL TOP BOARD	Warped / Torn	450.00 F	*366.00 FL
19	2		*TAILLAMPS	Cracked	770.20 F	*770.20 FL
20	1		*TAILLAMP PANELS	O/S Bent	490.00 F	*245.00 FL
21	2		*REAR FENDERS	Repair	1,798.20 F	*- FL
22	2		*REAR FENDER INNER TRIM TRIMS	Deformed / Twisted	710.20 F	*710.20 FL
23	1		*REAR AIR VENT	Not Necessary	65.00 F	*- FL
24	1		*REAR WINDSCREEN MOULDING	Not Necessary	121.00 F	*- FL
25	1		*REAR BUMPER LOWER SKIRTING	Deformed / Torn	1,200.00 FS	*800.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
30	1		*REAR EXHAUST	Repair	1,500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,626.80	6,480.60
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,086.12
Total Parts (S\$)	12,626.80	5,394.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX EXHAUST	New	100.00	60.00
6	TO SPRAY RUST PROOFING	New	120.00	80.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	800.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,200.00
Gross Labour Cost (S\$)			3,870.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >