

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWER SINGAPORE 048583

INV No. AC2007818

INV Date 20/11/2020

Reference CC6/QBE20005507/Aba3q2

Code OBE

PROFESSIONAL SERVICE FEE

Vehicle No. SJJ 9171J

Insured Veh. SKV 2381R

Claim No. VC013677

Policy No. 8-V0025520-MVA

Accident Date 24/04/2020

Inspection Date 24/04/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LAM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
QBE	QBE INSURANCE (SINGAPORE) PTE LTD Ref: CC6/QBE20005507/Aba3q2				
	FFLES QUAY #29 ERSINGAPORE (Date: 20-11-2020 Code: QBE		
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SKV 2381R	Veh. Inspected	SJJ 9171J	
	Policy No.	8-V0025520-MVA	Coverage (\$)	0.00	
	Claim No.	VC013677	Excess (\$)	0.00	
	Assign From		Assign Date	24/04/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	HYUNDAI AVANTE	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	KMHD841CMKU879307	Colour	BLUE	
	Odometer	33049	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
	L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
	R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
	L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
4.		•	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	24/04/2020	Inspection Date	24/04/2020	
	Survey held at	ADVANCE AUTO GARAGE			
	23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933				
5a.			emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.					
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 9171J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	REAR NUMBER PLATE LAMP @\$55.50	NOT NECESSARY	111.00	-
1	REAR BUMPER	DEFORMED	654.30	654.30
1	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER @\$85.90	NECESSARY	171.80	171.80
1	REAR BUMPER LOWER GARNISH	CRACKED	496.30	496.30
2	REAR BUMPER REFLECTOR @\$305.70	CRACKED	611.40	611.40
1	REAR BUMPER REINFORCEMENT	CRACKED	345.40	345.40
3	REAR BUMPER REINFORCEMENT BRACKET @\$35.00	NOT NECESSARY	105.00	-
1	REAR END PANEL	DENTED	657.80	657.80
1	REAR END PANEL TOP GARNISH	CRACKED	175.90	175.90
1	REAR END PANEL ANTENNA SENSOR	DAMAGED	191.60	191.60
1	BOOTLID	DENTED	1,853.00	1,853.00
1	BOOTLID LOCK	NOT NECESSARY	145.70	-
1	BOOTLID WEATHERSTRIPE	NOT NECESSARY	145.60	-
1	HYUNDAI LOGO	NECESSARY	68.90	68.90
1	AVENTE WORDING	NECESSARY	80.30	80.30
1	ELITE EMBLEM	NECESSARY	45.40	45.40
2	TAILLAMP @\$545.60	NOT NECESSARY	1,091.20	-
1	SPARE TYRE PANEL TOP COVER	NOT NECESSARY	385.90	-
1	REAR EXHAUST PIPE	NOT NECESSARY	785.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	28.50	-
1	REAR LH UNDERCOVER	TORN	94.30	94.30
	LESS 20% DISCOUNT		-	-1,095.28
			8,274.30	4,381.12
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00
1	REAR NUMBER PLATE HOLDER (SN)	DEFORMED	30.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
			400.00	320.00

Report Ref No. CC6/QBE20005507/Aba3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		1,200.00	800.00
	SPRAY PAINTING.		1,000.00	800.00
	WIRING .		50.00	30.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO REMOVE UPHOLSTERY .		150.00	60.00
	TO UNDERSEAL .		150.00	60.00
	TO REMOVE EXHAUST PIPE .	NOT NECESSARY	150.00	-
	TO TRANSFER BOOTLID FITTINGS.		150.00	50.00
			2,950.00	1,850.00
	GRAND TOTAL		11,624.30	6,551.12

RECOMMENDED COST OF LUMP SUM REPAIRS		5,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/QBE20005507/Aba3q2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJJ 9171J

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315



