

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005511/R1SF3E2
Date: 12/05/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000001340
Claimant Vehicle No :	FZ8375H	Insured Vehicle No :	SMR4961B
Date of Loss:	27/04/2020	Nature of Claim:	TP
		Claim No:	5049005788SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FZ8375H	Engine No:	NC23E3000040
Make & Model:	HONDA CB400, 399cc	Chassis No:	JH2NC39975M100040
Reg. Date:	12/11/2005 (Man. Year: 2005)	Odometer:	348023 km
Colour:	Multi-colour		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60Z R17	Rear Tyre Size:	160/60Z R17
Front Left Side:	Metzeler 4 mm	Rear Left Side:	Metzeler 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	30/04/2020	
Date Inspected:	04/05/2020	Inspected At:
		Equipment Extreme (depot Lane) (HQ) BLK 4001 DEPOT ROAD DEPOT LANE #01-10 SINGAPORE 109755
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
2	1		*FRONT WING MIRROR	Scratched	0.00 F	*- F
3	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F
4	1		*METER ASSY	Cracked	0.00 F	*- F
5	1		*ERP UNIT	Scratched	0.00 F	*- F
6	1		*HANDLE BAR	Bent	0.00 F	*- F
7	1		*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
8	1		*FUEL TANK	Bent	0.00 F	*- F
9	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
10	1		*HAND BRAKE LEVER	Broken	0.00 F	*- F
11	1		*FAIRING LOWER	Scratched	0.00 F	*- F
12	1		*ENGINE CRASH BAR	Scratched	0.00 F	*- F
13	1		*FRONT FOOT REST	Scratched	0.00 F	*- F
14	1		*MAIN STAND	Scratched	0.00 F	*- F
15	1		*FOOT GEAR SHIFTER	Scratched	0.00 F	*- F
16	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >