

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 9402Z

	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
REPL	LACEMENT OF PARTS			
1 BUMP	PER STRIP (CONSISTENT)	NOT NECESSARY	489.00	-
1 RH FE	ENDER (CONSISTENT)	DENTED	1,785.00	744.00
1 RH SI	IDE MIRROR (CONSISTENT)	MISSING	1,200.00	652.00
1 UNDE	ER TRAY COVER (CONSISTENT)	NOT NECESSARY	350.00	-
1 RIM T	YRE (CONSISTENT)	NOT NECESSARY	360.00	-
1 RH HE	EADLAIGHT (CONSISTENT)	CUT	400.00	400.00
1 COND	DENSER (CONSISTENT)	NOT NECESSARY	450.00	-
1 RADIA	ATOR (CONSISTENT)	NOT NECESSARY	450.00	-
1 REINF	FORCEMENT BAR SPONGE (CONSISTENT)	NOT NECESSARY	450.00	-
1 RH DO	OOR REPLACE (CONSISTENT)	DENTED	1,072.00	1,072.00
LESS	25% DISCOUNT		-	-717.00
			7,006.00	2,151.00
LABO	<u>OUR</u>			
TOW.			200.00	60.00
CHEC	CKING OF WIRING,LIGHTING AND RESETTING.		400.00	30.00
REMO	OVE AND REFIT UNDERCARRIAGE.	NOT NECESSARY	500.00	-
WHEE	EL ALIGNMENT.	NOT NECESSARY	300.00	-
REMO	OVE AND REPLACE DAMAGED PARTS.		1,000.00	80.00
APPL` PANE	Y UNDERCOATING ON REPAIRED AND REPLACED :L.		800.00	30.00
PART	KMANSHIP TO DISMANTLE ABOVE DAMAGED 'S,REPAIRS INCLUDING CUT AND WELD,REALIGN 'STRUCTURE.		1,200.00	400.00
CHAN	PRAY INCLUDING POLISHING AND WAXING ON THE NGED BODY PARTS, REPAIRED PORTORTIONS RE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00
			5,400.00	1,000.00
GRAN	ND TOTAL		12,406.00	3,151.00

Report Ref No. CC4/ASM20005515/Eba3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,500.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM20005515/Eba3q2



**Automotive Assessor** 

Amonto

**HO LEONG CHUAN** 

**Automotive Assessor**