



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 2082Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR	BENT	1,381.50	1,381.50
1	FRONT DOOR TAPE-FRONT UPPER	NECESSARY	17.00	17.00
1	FRONT DOOR TAPE-FRONT REAR	NECESSARY	25.00	25.00
1	FRONT FENDER	BENT	650.00	650.00
1	FRONT LOWER ARM	DISTORTED	544.00	341.20
1	FRONT ABSORBER	BENT	480.00	355.80
2	SPORTS RIMS @\$600.00	DENTED	1,200.00	1,160.00
	LESS 10% DISCOUNT		-429.75	-
	LESS 20% DISCOUNT		-	-786.10
			3,867.75	3,144.40
<u>LABOUR</u>				
	WHEEL ALIGNMENT.		50.00	50.00
	LABOUR TO RENEW BODY PARTS.		600.00	540.00
	UNDERCARRIAGE REPAIR.		250.00	160.00
	SPRAY PAINTING.		700.00	600.00
			1,600.00	1,350.00
GRAND TOTAL			5,467.75	4,494.40
RECOMMENDED COST OF REPAIRS				4,494.40

Report Ref No. CS/UOI20005525/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.