

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20005527/KKA3Q2

**Date:** 17/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900170816

### Claimant

**Vehicle No :** SJJ4446A

**Insured Vehicle No :** GBG8504A

**Date of Loss:** 01/05/2020

**Nature of Claim:** TP

**Claim No:** 2578140338SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SJJ4446A

**Make & Model:** HONDA CIVIC, 1.6 L VTI (A)

**Engine No:** R16A13006983

**Reg. Date:** 12/09/2008 (Man. Year: 2008)

**Chassis No:** JHMF46208S202451

**Colour:** White

**Odometer:** 47445 km

**Engine Capacity:** 1595 cc

**Market Value/New Car**

**Price:** N/A

**Sum Insured (\$):** Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 205/55 R16

**Rear Tyre Size:** 205/55 R16

**Front Left Side:** Yokohama 8 mm

**Rear Left Side:** Yokohama 8 mm

**Front Right Side:** Yokohama 8 mm

**Rear Right Side:** Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,853.18	1,715.94	2,137.24	55.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,300.00	1,270.00	49.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>6,423.18</b>	<b>3,015.94</b>	<b>3,407.24</b>	<b>53.05</b>
<b>Approved Total (Overridden) (\$)</b>		<b>2,400.00</b>		
<b>(\$)</b>	6,423.18	2,400.00	4,023.18	62.64
<b>+ GST 7.00/7.00% (\$)</b>	449.62	168.00	281.62	62.64
<b>Nett Amount (\$)</b>	<b>6,872.80</b>	<b>2,568.00</b>	<b>4,304.80</b>	<b>62.64</b>
<b>+ Car Rental (7.0 x \$100.00/day) (\$)</b>		700.00		
<b>+ Doc/Search Fee (\$)</b>		2.00		
<b>Nett Liability (\$)</b>		<b>3,270.00</b>		
<b>Global Sum Settlement (\$)</b>		<b>3,250.00</b>		

### INSPECTION

**Date of Assignment:** 04/05/2020

**Date Inspected:** 04/05/2020 Inspected At:

Kgc Workshop Pte Ltd (HQ)  
176 SIN MING DRIVE, SIN MING  
AUTOCARE #02-04  
Singapore 575721

**Estimated Period of Repair:** 5.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	638.00 FL	*638.00 FL
2	2		*REAR BUMPER RETAINER	Serviceable	29.20 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT (NPA)	No such part	0.00 FL	*- FL
4	1		*REAR BUMPER SPONGE (NPA)	No such part	0.00 FL	*- FL
5	1		*REAR END PANEL	Bent	320.50 FL	*320.50 FL
6	1		*REAR END PANEL GARNISH	Serviceable	66.60 FL	*- FL
7	1		*BOOTLID	Buckled	610.70 FL	*610.70 FL
8	1		*TAILGATE GARNISH	Serviceable	121.60 FL	*- FL
9	1		*TAILGATE HINGE	Repair	48.60 FL	*- FL
10	1		*TAILGATE ABSORBER	Serviceable	120.00 FL	*- FL
11	2		*TAILGATE STOPPER (BIG)	Serviceable	20.00 FL	*- FL
12	2		*TAILGATE STOPPER (SMALL)	Serviceable	16.00 FL	*- FL
13	1		*TAILGATE WEATHERSTRIP	Serviceable	97.60 FL	*- FL
14	1		*TAILGATE LOCK	Dented	194.50 FL	*194.50 FL
15	1		*TAILGATE LOCK (KEY)	Serviceable	97.20 FL	*- FL
16	2		*NUMBER PLATE LAMP	Serviceable	56.00 FL	*- FL
17	2		*TAIL LAMP LED (BODY)	Serviceable	452.40 FL	*- FL
18	1		*TAIL LAMP LED (TAILGATE)	N/S Cut	369.20 FL	*184.60 FL
19	2		*REAR FENDER SHIELD	Serviceable	38.00 FL	*- FL
20	1		*EXHAUST PIPE	Repair	535.00 FL	*- FL
21	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
22	10		*TAILGATE HINGE CLIPS	Not Necessary	35.00 FS	*- FS
23	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
24	1		*NO PLATE WIT CASING	Serviceable	80.00 FS	*- FS
25	1		*EMBLEM HONDA LOGO	Necessary	28.70 FS	*28.70 FS
26	1		*EMBLEM CIVIC	Necessary	29.10 FS	*29.10 FS
27	1		*EMBLEM I-VTEC 1.6	Necessary	49.50 FS	*49.50 FS
28	1		*SPARE TYRE BOX	Serviceable	316.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,619.40</b>	<b>2,105.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	766.22	389.66
<b>Total Parts (\$\$)</b>	<b>3,853.18</b>	<b>1,715.94</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS- MENTION REPAIR PARTS ,INCLUSIVE OF REPLACEMENT PARTS	New	1,200.00	600.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	1,000.00	600.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	120.00	50.00
4	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	120.00	20.00
5	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	30.00
6	TO REMOVE AND REFIT EXHAUST PIPE	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,570.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >