

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20005529/KSF3E2

**Date:** 05/06/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

**Claimant Vehicle No :** SJR895X

**Insured Vehicle No :** SLQ6303E

Date of Loss: 28/04/2020

Nature of Claim: TP

Claim No: 623667

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR895X**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FC9U662542

Reg. Date: 09/06/2009 (Man. Year: 2009)

Chassis No: KMHU41BR9U772144

Colour: Metallic Silver

Odometer: 121131 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size:

185/65 R15

Front Left Side: Hankook 8 mm

Rear Left Side:

HIFLY 6 mm

Front Right Side: Hankook 8 mm

Rear Right Side:

HIFLY 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,378.16	4,721.33	656.83	12.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	2,680.00	300.00	10.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,358.16</b>	<b>7,401.33</b>	<b>956.83</b>	<b>11.45</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,850.00</b>		
<b>(S\$)</b>	8,358.16	5,850.00	2,508.16	30.01
<b>+ GST 7.00/7.00% (S\$)</b>	585.07	409.50	175.57	30.01
<b>Nett Amount (S\$)</b>	<b>8,943.23</b>	<b>6,259.50</b>	<b>2,683.73</b>	<b>30.01</b>

### INSPECTION

Date of Assignment: 30/04/2020

Date Inspected: 05/05/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 8.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Jun 2020)

**Parts:** 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJR895X)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	489.10 FL	*489.10 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	270.00 FL	*270.00 FL
3	1		*REAR BUMPER SPONGE	Cracked	109.90 FL	*109.90 FL
4	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*REAR BOOT	Buckled	1,305.00 FL	*1,305.00 FL
6	1		*REAR BOOT LOGO	Necessary	16.05 FL	*16.05 FL
7	1		*REAR BOOT EMBLEM AVANTE	Necessary	31.20 FL	*31.20 FL
8	1		*REAR BOOT INNER LOCK	Dented	118.30 FL	*118.30 FL
9	1		*REAR BOOT INNER RUBBER (\$79.30) (50%)	Distorted / Dented	63.44 FS	*39.65 FS
10	1		*LH TAIL LAMP	Cracked	403.10 FL	*403.10 FL
11	1		*REAR PANEL	Bent	493.80 FL	*493.80 FL
12	1		*REAR VOOT INNER TOP GARNISH	Dented	34.40 FL	*34.40 FL
13	1		*FRONT BUMPER	Mtg Distorted	461.40 FL	*461.40 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	254.10 FL	*254.10 FL
15	1		*FRONT BUMPER SPONGE	Cracked	113.40 FL	*113.40 FL
16	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
17	1		*FRONT GRILLE	Dented	366.00 FL	*366.00 FL
18	1		*HORN	Dented	59.70 FL	*59.70 FL
19	1		*FRONT SUPPORT PANEL	Repair	791.30 FL	*- FL
20	1		*AIR-CON CONDENSOR	Punctured	990.90 FL	*990.90 FL
21	1		*FRONT NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
22	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,648.09</b>	<b>5,833.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,269.93	1,111.67
<b>Total Parts (\$\$)</b>	<b>5,378.16</b>	<b>4,721.33</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMP, REAR BOOT AND ATTACHMENT. TO CUTTING, WELDING AND RENEW REAR PANEL, KNOCK AND REPAIR REAR SPARE TYRE COMPARTMENT AND REALIGN THE SAME	New	800.00	700.00
2	PUTTY AND RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR BUMPER, REAR PANEL	New	850.00	800.00
3	REMOVE AND REFIX FRONT BUMPER ASSY, HEAD LAMP, RADIATOR AND MOTOR, FRONT SUPPORT PANEL AND REALIGN THE SAME	New	700.00	600.00
4	PUTTY AND RESPRAY ON FRONT BUMPER, BONNET	New	500.00	450.00
5	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00	100.00
6	RUSTPROOFING	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,980.00</b>	<b>2,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >