

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd  
 300 Beach Road, #17-04/07 The Concourse  
 Singapore 199555

**Our File No:** CS/LPC20005531/EQF3E2

**Date:** 18/05/2020

### REFERENCE

Insured/Claimant:	OH BENG GEE	Policy No:	Z20VP05025924
Date of Loss:	30/04/2020	Nature of Claim:	OD
		Claim No:	20/20/20/VP05/023330

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SCY8642C</b>		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Dual VVT-i (A)	Engine No:	1ZRX575084
Reg. Date:	22/02/2017 (Man. Year: 2016)	Chassis No:	MR053REH104551371
Colour:	Silver	Odometer:	58941 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$62,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	540.50	184.00	356.50	65.96
Miscellaneous Items	780.00	435.50	344.50	44.17
Labour	930.00	880.00	50.00	5.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,250.50</b>	<b>1,499.50</b>	<b>751.00</b>	<b>33.37</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	157.54	104.97	52.57	33.37
<b>Nett Amount (\$\$)</b>	<b>2,408.04</b>	<b>1,604.47</b>	<b>803.57</b>	<b>33.37</b>

### INSPECTION

Date of Assignment:	04/05/2020	Present Location:	Kan Fook Sing Motor Workshop (Defu)
Date Inspected:	04/05/2020	Inspected At:	Kan Fook Sing Motor Workshop (Defu)
			No. 61 Defu Lane 12
			Singapore 539147
Estimated Period of Repair:	5.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2020)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 Dual VVT-i (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SCY8642C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*OIL FILTER</b> (WCP)	Necessary	10.00 F	*10.00 F
2	1		<b>*AIR FILTER</b> (WCP)	Not Necessary	20.00 F	*- F
3	1		<b>*AIR CON FILTER</b> (WCP)	Necessary	70.00 F	*10.00 F
4	1		<b>*FRONT BUMPER FOGLAMP RH</b> (WCP)	Not Necessary	100.00 F	*- F
5	1		<b>*FRONT BUMPER FOGLAMP LH</b> (WCP)	Not Necessary	100.00 F	*- F
6	10		<b>*FRONT BUMPER CLIP</b> (WCP)	Not Necessary	15.00 F	*- F
7	1		<b>*REAR SPARE TYRE BOARD</b> (WCP)	Contaminated	140.00 F	*140.00 F
8	10		<b>*REAR BUMPER CLIP</b> (WCP)	Not Necessary	15.00 F	*- F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>470.00</b>	<b>160.00</b>
<b>+ Margin on L,N Items 15.00/15.00% (\$\$)</b>	70.50	24.00
<b>Total Parts (\$\$)</b>	<b>540.50</b>	<b>184.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	<b>AUTO TRANSMISSION FLUID</b> (NECESSARY)	160.00	120.00
2	1	<b>ENGINE OIL</b> (NECESSARY)	120.00	120.00
3	1	<b>FRONT DOOR SPEAKER LH</b> (NOT NECESSARY)	100.00	0.00
4	1	<b>FRONT DOOR SPEAKER RH</b> (NOT NECESSARY)	100.00	0.00
5	1	<b>REAR REVERSE SENSOR</b> (SHORTED) (WCP) (\$170.00) (15%)	300.00	195.50
<b>Sub Total (\$\$)</b>			<b>780.00</b>	<b>435.50</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	<b>TO CHECK WIRING SYSTEM</b>	New	30.00	30.00
2	<b>TO DRAIN AND REFILL ENGINE AND AFT OIL</b>	New	150.00	100.00
3	<b>TO REMOVE/REFIT CARPET AND CUSHION SEATS</b>	New	150.00	150.00
4	<b>TO CLEAN AND SHAMPOO CARPET AND CUSHION SEATS</b>	New	600.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>930.00</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >