

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20005536/FQF3E2

Date: 14/05/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MU005887

Claimant Vehicle No : SHC1712L

Insured Vehicle No : SLN7206L

Date of Loss: 30/04/2020

Nature of Claim: TP Claim No: M2002595

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC1712L**

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDHU731306

Reg. Date: 20/12/2017 (Man. Year: 2016)

Chassis No: KMHLB41UMHU100045

Colour: Blue

Odometer: 297850 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,272.32	316.88	955.44	75.09
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,820.00	1,470.00	350.00	19.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,103.32	1,797.88	1,305.44	42.07
+ GST 7.00/7.00% (S\$)	217.23	125.85	91.38	42.07
Nett Amount (S\$)	3,320.55	1,923.73	1,396.82	42.07

INSPECTION

Date of Assignment: 04/05/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 04/05/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1712L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Repair	1,106.00 FL	-	*- FL
2	1		*REAR BUMPER MAT	Not Necessary	50.00 F	-	*- F
3	1		*REAR WESTLAKE TYRE RH (CUT)	Cut	216.00 F	-	*151.20 FS
4	1		*REAR WHEEL CAP RH	Scratched	107.10 FL	-	*107.10 FL
5	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	-	*- FL
6	1		*REAR DOOR APPS STICKER RH	Necessary	80.00 F	-	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,581.10	338.30
- List Item Discount on L Items 25.00/20.00% (\$)	308.78	21.42
Total Parts (\$)	1,272.32	316.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	560.00
2	SPRAY PAINTING - REAR FENDER RH / REAR DOOR RH / ROCKER PANEL GARNISH ETC	New	1,000.00	850.00
3	TUFF KOTE	New	100.00	0.00
4	R/I REVERSE SENSOR	New	120.00	60.00
Gross Labour Cost (\$\$)			1,820.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >