

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20005541/KBA3Q2

**Date:** 19/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900101182  
**Claimant**  
**Vehicle No :** SLQ3172K **Insured Vehicle No :** SML1343L  
**Date of Loss:** 06/04/2020 **Nature of Claim:** TP **Claim No:** 8950574697SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SLQ3172K  
**Make & Model:** TOYOTA AQUA HYBRID, 1.5 E S CVT (A) **Engine No:** 1NZR518939  
**Reg. Date:** 04/07/2017 (Man. Year: 2017) **Chassis No:** NHP106598524  
**Colour:** Metallic Pearl White **Odometer:** 178071 km  
**Engine Capacity:** 1496 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (\$\$):** **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 175/65 R15 **Rear Tyre Size:** 175/65 R15  
**Front Left Side:** SUNWIDE 9 mm **Rear Left Side:** KAPSEN 6 mm  
**Front Right Side:** SUNWIDE 9 mm **Rear Right Side:** KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts  | 899.18            | 540.38            | 358.80            | 39.90         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour   | 880.00            | 470.00            | 410.00            | 46.59         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing   | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (\$\$)</b>                        | <b>1,779.18</b>   | <b>1,010.38</b>   | <b>768.80</b>     | <b>43.21</b>  |
| <b>+ GST 7.00/7.00% (\$\$)</b>                   | 124.54            | 70.73             | 53.81             | 43.21         |
| <b>Nett Amount (\$\$)</b>                        | <b>1,903.72</b>   | <b>1,081.11</b>   | <b>822.61</b>     | <b>43.21</b>  |
| <b>+ Loss of Use (2.0 x S\$70.00/day) (\$\$)</b> |                   | 140.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (\$\$)</b>                     |                   | <b>1,223.11</b>   |                   |               |
| <b>Global Sum Settlement (\$\$)</b>              |                   | <b>1,200.00</b>   |                   |               |

### INSPECTION

**Date of Assignment:** 05/05/2020  
**Date Inspected:** 05/05/2020 **Inspected At:** Optima Werkz Pte Ltd (HQ)  
 9A Serangoon North Ave 5  
 Singapore 554500  
**Estimated Period of Repair:** 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                  | Condition         | Repairer's | Amount     |
|-----|-----|----------|------------------------------|-------------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                 | Buckled / Cracked | 608.31 FL  | *608.31 FL |
| 2   | 1   |          | *REAR BUMPER SIDE BRACKET LH | Distorted         | 68.20 FL   | *68.20 FL  |
| 3   | 1   |          | *REAR BUMPER REINFORCEMENT   | Repair            | 478.40 FL  | *- FL      |
| 4   | 8   |          | *REAR BUMPER CLIPS           | Necessary         | 44.00 FL   | *44.00 FL  |
| 5   | 1   |          | *REAR END PANEL (NPA)        | Repair            | 0.00 FL    | *- FL      |

F=Franchise part. L=ListItemDisc.

|  |                 |               |
|--|-----------------|---------------|
| <b>Sub Total (\$\$)</b>                                    | <b>1,198.91</b> | <b>720.51</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 299.73          | 180.13        |
| <b>Total Parts (\$\$)</b>                                  | <b>899.18</b>   | <b>540.38</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars   | Lab.Type | Repairer's    | Amount        |
|-------------------------------|---|----------|---------------|---------------|
| <b><u>Labour Items</u></b>    |   |          |               |               |
| 1                             | LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC                             | New      | 300.00        | 200.00        |
| 2                             | LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSR & ETC TO EFFECT REPLACE OF REAR BUMPER         | New      | 80.00         | 50.00         |
| 3                             | LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ,REAR END PANEL & ETC | New      | 500.00        | 220.00        |
| <b>Gross Labour Cost (\$)</b> |   |          | <b>880.00</b> | <b>470.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >