



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2003925
INV Date 15/05/2020
Reference CS/SMO20005542/Kqf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SLU 666B
Insured Veh. GBF 5486T
Claim No. CMTD2001529/SYH
Policy No.
Accident Date 30/04/2020
Inspection Date 05/05/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20005542/Kqf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 15-05-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 5486T	Veh. Inspected	SLU 666B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2001529/SYH	Excess (\$)	0.00
	Assign From	GARCE TEO	Assign Date	04/05/2020
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES E250 (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDD2130452A298626	Colour	METALLIC BLACK
	Odometer	52624	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 ZR19	MICHELIN	8 mm
	L/H Front Tyre	245/40 ZR19	MICHELIN	8 mm
	R/H Rear Tyre	275/35 ZR19	MICHELIN	7 mm
	L/H Rear Tyre	275/35 ZR19	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/04/2020	Inspection Date	05/05/2020
	Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 666B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	BENT	2,550.00	2,240.00
1	REAR BOOT LID "E250" EMBLEM	NECESSARY	118.00	118.00
1	REAR BOOT LID "AMG" EMBLEM	NECESSARY	139.60	139.60
1	REAR BOOT LID CHROME MOULDING	CRACKED	156.70	156.70
1	REAR BOOT LID LOGO EMBLEM	NECESSARY	75.00	75.00
1	REAR BUMPER	BUCKLED	2,422.00	1,956.00
8	REAR BUMPER CLIPS @\$6.20	NECESSARY	49.60	49.60
1	REAR BUMPER REINFORCEMENT	BENT	929.00	835.00
1	REAR BUMPER INNER CENTER GUIDE	CRACKED	196.40	196.40
1	REAR BUMPER UPPER BRACKET LH	TO REPAIR SEE LABOUR	75.00	-
1	REAR BUMPER UPPER BRACKET RH	TO REPAIR SEE LABOUR	75.00	-
1	REAR BUMPER LOWER LIP COVER	CRACKED	545.00	269.00
1	REAR BUMPER LOWER LIP COVER CHROME MOULDING	DENTED	362.00	315.00
1	REAR TAIL LAMP LH	SERVICEABLE	855.70	-
1	REAR SAFETY BELT ASSY LH	JAMMED	1,232.00	650.00
1	REAR SAFETY BELT ASSY RH	JAMMED	1,232.00	650.00
1	FRONT SAFETY BELT ASSY RH	JAMMED	1,565.00	860.00
1	AIR BAG CONTROL UNIT	NECESSARY	1,360.00	570.00
1	REAR AIR BAG IMPACT SENSOR LH	NECESSARY	272.00	272.00
1	REAR AIR BAG IMPACT SENSOR RH	NECESSARY	272.00	272.00
1	FRONT AIR BAG IMPACT SENSOR RH	NECESSARY	272.00	272.00
1	REAR TAIL LAMP UPPER COVER LH	DISTORTED	78.20	78.20
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER INNER GUIDE LH	CRACKED	142.60	142.60
	LESS 10% DISCOUNT		-1,497.48	-1,011.71
			13,477.32	9,105.39

Report Ref No. CS/SMO20005542/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER UPPER BRACKET LH,REAR BUMPER UPPER BRACKET RH AND REAR END PANEL.		1,200.00	600.00
	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC.TO EFFECT REPLACE OF REAR BUMPER & ETC.		90.00	60.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR SAFETY BELT LH & RH,REAR SEAT ASSY,FRONT SAFETY BELT RH ASSY & ETC.		250.00	200.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT LID,REAR END PANEL,REAR BUMPER & ETC.		900.00	600.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.	NOT NECESSARY	200.00	-
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		80.00	20.00
	TO RESET AIR BAG CONTROL UNIT & ETC BACK TO ORIGINAL OPERATIONS.		120.00	120.00
	TO DIAGNOSIS FAULTY CODE & RESET MEMORY.		180.00	150.00
			3,020.00	1,750.00
	GRAND TOTAL		16,497.32	10,855.39
RECOMMENDED COST OF REPAIRS				10,855.39

Report Ref No. CS/SMO20005542/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 666B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 666B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

