

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20005544/R1YF3E2

**Date:** 28/07/2020

### REFERENCE

|                       |                                               |                      |                   |                                    |
|-----------------------|-----------------------------------------------|----------------------|-------------------|------------------------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMPCSN30502419000 |                                    |
| Claimant Vehicle No : | SKD8974K                                      | Insured Vehicle No : | SGJ3072L          |                                    |
| Date of Loss:         | 15/04/2020                                    | Nature of Claim:     | TP                | Claim No: SNM20D201788/C02/TANGHL2 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                        |             |                   |  |
|-----------------------------|----------------------------------------|-------------|-------------------|--|
| Reg No:                     | SKD8974K                               |             |                   |  |
| Make & Model:               | MERCEDES-BENZ C180, 1.6 Kompressor (A) | Engine No:  | 27191031351764    |  |
| Reg. Date:                  | 17/01/2012 (Man. Year: 2011)           | Chassis No: | WDD2040452A664912 |  |
| Colour:                     | Grey                                   | Odometer:   | 133787 km         |  |
| Engine Capacity:            | 1597 cc                                |             |                   |  |
| Market Value/New Car Price: | N/A                                    |             |                   |  |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>      |             |                   |  |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 225/45 R17  | Rear Tyre Size:  | 225/45 R17  |
| Front Left Side:  | Dunlop 6 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                    | 8,219.50         | 7,353.70        | 865.80          | 10.53        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00            |              |
| Labour                                   | 1,820.00         | 1,540.00        | 280.00          | 15.38        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00            |              |
| Towing                                   | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>10,039.50</b> | <b>8,893.70</b> | <b>1,145.80</b> | <b>11.41</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>7,100.00</b> |                 |              |
| <b>(S\$)</b>                             | 10,039.50        | 7,100.00        | 2,939.50        | 29.28        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 702.77           | 497.00          | 205.77          | 29.28        |
| <b>Nett Amount (S\$)</b>                 | <b>10,742.27</b> | <b>7,597.00</b> | <b>3,145.27</b> | <b>29.28</b> |

### INSPECTION

|                             |                          |                                                                                                               |
|-----------------------------|--------------------------|---------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 21/05/2020               |                                                                                                               |
| Date Inspected:             | 19/05/2020 Inspected At: | Mova Automotive Pte Ltd (Bukit Merah)<br>Blk 1008, #01-04/06/08/94, Bukit Merah<br>Lane 3<br>Singapore 159722 |
| Estimated Period of Repair: | 6.0 days                 |                                                                                                               |

---

**Adjuster:** MOHD RASUL**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                         |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 28 Jul 2020)                           |
| <b>Parts:</b>        | 143                                                                                                                                                                          | MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                       |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKD8974K)                                                                                                                                    |                                                                         |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                         |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                         |

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition   | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------|-------------|-------------|--------------|
| 1   | 1   |          | *FRONT GRILLE ASSY                 | Cracked     | 790.00 FL   | *790.00 FL   |
| 2   | 1   |          | *FRONT GRILLE BRACKET              | Serviceable | 35.00 FL    | *- FL        |
| 3   | 1   |          | *FRONT BUMPER                      | Deformed    | 1,350.00 FL | *1,350.00 FL |
| 4   | 1   |          | *FRONT NUMBER PLATE GARNISH        | Cut         | 145.00 FL   | *145.00 FL   |
| 5   | 2   |          | *FRONT BUMPER CHROME LH & RH       | Necessary   | 224.00 FL   | *224.00 FL   |
| 6   | 1   |          | *FRONT BUMPER LOWER GRILLE         | Deformed    | 135.00 FL   | *135.00 FL   |
| 7   | 1   |          | *FRONT BUMPER SPONGE               | Serviceable | 135.00 FL   | *- FL        |
| 8   | 1   |          | *BOOTLID                           | Bent        | 1,755.00 FL | *1,755.00 FL |
| 9   | 1   |          | *BOOTLID LOGO                      | Necessary   | 55.00 FL    | *55.00 FL    |
| 10  | 1   |          | *BOOT EMBLEM - C180                | Necessary   | 90.00 FL    | *90.00 FL    |
| 11  | 1   |          | *BOOT EMBLEM - KOMPRESSOR          | Necessary   | 115.00 FL   | *115.00 FL   |
| 12  | 1   |          | *TAILLAMP - RH                     | Serviceable | 668.00 FL   | *- FL        |
| 13  | 2   |          | *TAILLAMP GARNISH - LH & RH        | Serviceable | 70.00 FL    | *- FL        |
| 14  | 2   |          | *TAILLAMP LOWER BRACKET LH & RH    | Cracked     | 156.00 FL   | *156.00 FL   |
| 15  | 1   |          | *REAR BUMPER                       | Deformed    | 1,365.00 FL | *1,365.00 FL |
| 16  | 1   |          | *REAR BUMPER CHROME CTR            | Cut         | 198.00 FL   | *198.00 FL   |
| 17  | 2   |          | *REAR BUMPER CHROME LH & RH        | Necessary   | 290.00 FL   | *290.00 FL   |
| 18  | 1   |          | *REAR BUMPER TOW COVER RH          | Serviceable | 54.00 FL    | *- FL        |
| 19  | 1   |          | *REAR BUMPER REINFORCEMENT         | Bent        | 735.00 FL   | *735.00 FL   |
| 20  | 2   |          | *REAR BUMPER SIDE RETAINER LH & RH | Necessary   | 90.00 FL    | *90.00 FL    |
| 21  | 1   |          | *HEADLAMP RH (NPA)                 | Serviceable | 0.00 FL     | *- FL        |
| 22  | 1   |          | *FRONT BUMPER REINFORCEMENT (NPA)  | Serviceable | 0.00 FL     | *- FL        |
| 23  | 1   |          | *END PANEL (NPA)                   | Repair      | 0.00 FL     | *- FL        |
| 24  | 1   |          | *FRONT NUMBER PLATE                | Bent        | 40.00 FS    | *40.00 FS    |
| 25  | 1   |          | *REAR PARKING SENSOR               | Cut         | 300.00 FS   | *300.00 FS   |
| 26  | 1   |          | *REAR BUMPER CTR BRACKET           | Cracked     | 178.00 FL   | *178.00 FL   |
| 27  | 2   |          | *REAR BUMPER LOWER BRACKET LH & RH | Cracked     | 70.00 FL    | *70.00 FL    |
| 28  | 10  |          | *BOOTLID STOP BUFFER               | Necessary   | 20.00 FL    | *20.00 FL    |
| 29  | 8   |          | *BOOTLID RIVET NUT                 | Necessary   | 32.00 FL    | *32.00 FL    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>9,095.00</b> | <b>8,133.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 875.50          | 779.30          |
| <b>Total Parts (\$\$)</b>                                  | <b>8,219.50</b> | <b>7,353.70</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                                               |          |                 |                 |
| 1                              | TO INSPECT FRONT & REAR LIGHTING MECHANISM                                    | New      | 80.00           | 40.00           |
| 2                              | TO REPLACE REAR PARKING SENSOR & DIAGNOSE FUNCTION                            | New      | 80.00           | 60.00           |
| 3                              | TO REPAIR ON END PANEL, TO REMOVE & REPLACE DAMAGED ITEMS. REALIGN CONNECTION | New      | 500.00          | 500.00          |
| 4                              | TO REMOVE & REPLACE FRONT DAMAGED ITEMS. REALIGN CONNECTION                   | New      | 280.00          | 200.00          |
| 5                              | TO RUST PROOF ON REPAIRED AREAS                                               | New      | 80.00           | 40.00           |
| 6                              | TO SPRAY PAINT ON REPAIRED AREAS                                              | New      | 800.00          | 700.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                               |          | <b>1,820.00</b> | <b>1,540.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >