

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20005547/AGA3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800094517

**Claimant**  
**Vehicle No :** SFE6238U **Insured Vehicle No :** SME151S

Date of Loss: 03/05/2020 Nature of Claim: TP Claim No: 4015836483SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFE6238U</b>		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2228547A
Reg. Date:	22/01/2016 (Man. Year: 2015)	Chassis No:	SJNFEAJ11U1571203
Colour:	Grey	Odometer:	41458 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,439.15	3,935.92	2,503.23	38.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,260.00	1,070.00	45.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,769.15</b>	<b>5,195.92</b>	<b>3,573.23</b>	<b>40.75</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,150.00</b>		
<b>(S\$)</b>	8,769.15	4,150.00	4,619.15	52.68
<b>+ GST 7.00/7.00% (S\$)</b>	613.84	290.50	323.34	52.67
<b>Nett Amount (S\$)</b>	<b>9,382.99</b>	<b>4,440.50</b>	<b>4,942.49</b>	<b>52.68</b>
<b>+ Loss of Use (7.0 x S\$50.00/day) (S\$)</b>		350.00		
<b>(S\$)</b>		4,790.50		
<b>Liabie Amount (50.00%) (S\$)</b>		<b>2,395.25</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,397.25</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,390.00</b>		

### INSPECTION

Date of Assignment: 04/05/2020

Date Inspected: 04/05/2020 Inspected At:

Kang Car Repairers Pte Ltd (HQ)  
No 1 Kaki Bukit Ave 6, #02-06  
AutoBay@Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 5.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Dented	685.10 FN	*685.10 FN
2	1		*FRT FENDER COWLING RH	Deformed	122.40 FN	*122.40 FN
3	1		*FRT WHEEL ARCH GARNISH RH	Cut	483.00 FN	*483.00 FN
4	1		*HEADLAMP RH	Cracked	612.00 FN	*612.00 FN
5	1		*HEADLAMP RETAINER RH	Not Necessary	54.70 FN	*- FN
6	1		*BONNET	Repair	961.40 FN	*- FN
7	1		*FRT BUMPER	Deformed	674.60 FN	*674.60 FN
8	1		*FRT BUMPER REINFORCEMENT	Not Necessary	675.40 FN	*- FN
9	1		*FRT BUMPER SPONGE	Not Necessary	89.40 FN	*- FN
10	1		*FRT BUMPER RETAINER RH	Necessary	36.70 FN	*36.70 FN
11	1		*FRT WIPER TANK	Not Necessary	201.90 FN	*- FN
12	1		*FRT GRILLE	Cracked	493.30 FN	*493.30 FN
13	1		*FRT FOG LAMP RH	Cracked	327.00 FN	*327.00 FN
14	1		*SET FRT PARKING SENSOR	Damaged	220.00 FN	*220.00 FN
15	1		*FRT FOG LAMP COVER RH	Deformed	74.70 FN	*74.70 FN
16	1		*FRT SPORT RIM RH	Cut	1,108.71 FS	*500.00 FS
17	1		*SET FRT FENDER COWLING CLIPS RH	Necessary	50.00 FS	*30.00 FS
18	1		*SET FRT WHEEL ARCH GARNISH CLIPS RH	Necessary	40.00 FS	*20.00 FS
19	1		*SET FRT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
20	1		*SET FRT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,010.31</b>	<b>4,308.80</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	571.16	372.88
<b>Total Parts (\$\$)</b>	<b>6,439.15</b>	<b>3,935.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS	New	1,000.00	500.00
2	TO SPRAY PAINTING	New	1,000.00	600.00
3	TO SPRAY UNDERSEAL	New	80.00	0.00
4	TO REPLACE FRT PARKING SENSOR	New	80.00	50.00
5	TO CHECK WIRING	New	50.00	30.00
6	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,330.00</b>	<b>1,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >