

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 May 2020 18:54 Sendback Est	04 May 2020 19:01 S\$2,165.42	05 May 2020 09:53 Edit Adj Rpt	S\$750.00 Edit Estimates	S\$750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CCPL , Co. Reg. No.: 199303839G									
Main Claimant: CCPL									
Vehicle Reg. No.:	SHB3389D	Date of Loss:	01/05/2020 18:00 - :59 [68 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M2002612	Policy/Cover Note No.:	MI001160 (Comprehensive) Coverage: 18/07/2019 - 17/07/2020						
Vehicle Reg. No. (Insured):	SLG6624G	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 15/05/2020]								
Adj Asg. Remarks:	** PLS NOTE:INSURED CLAIMED TAXI HAVE OLD DAMAGE NOT CONSISTENT TO THE ACCIDENT. PLS. CHECK AND REFER TO OUR INSURED GIA REPORT PLS.INFORM FIONA ON THE OUTCOME.THANKS.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHB3389D (M2002612)
[SLG6624G]
TP
CCPL
May 1 2020 6:00PM
[CCPL]
ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video					
			1 per page		
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	05/05/20 15:58	Video - Accident From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load MP4	
Assessment Reports					
			1 per page		
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	04/05/20 19:01	Repairer Estimates		Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	05/05/20 09:52	Accident Statement From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load HTM	
Photos/Images					
			3 per page		
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
2	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
3	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
4	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
5	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
6	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
7	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
8	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
9	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
10	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
11	05/05/20 09:52	Accident Photo From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/05/20 12:14	General View		Load JPG	
2	05/05/20 12:14	General View		Load JPG	
3	05/05/20 12:14	General View		Load JPG	
4	05/05/20 12:14	General View		Load JPG	
5	05/05/20 12:14	General View		Load JPG	
6	05/05/20 12:14	General View		Load JPG	
7	05/05/20 12:14	General View		Load JPG	
8	05/05/20 12:14	General View		Load JPG	
9	05/05/20 12:14	General View		Load JPG	
10	05/05/20 12:14	General View		Load JPG	
11	05/05/20 12:14	General View		Load JPG	
12	05/05/20 12:14	General View		Load JPG	
13	05/05/20 12:14	General View		Load JPG	
14	05/05/20 12:14	General View		Load JPG	
15	05/05/20 12:14	General View		Load JPG	
16	05/05/20 12:15	General View		Load JPG	

Video				1 per page	☒
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
17	05/05/20 12:15	General View		Load JPG	☒
18	05/05/20 12:15	General View		Load JPG	☒
19	05/05/20 12:15	General View		Load JPG	☒
20	05/05/20 12:15	General View		Load JPG	☒
21	05/05/20 12:15	General View		Load JPG	☒
22	05/05/20 12:15	General View		Load JPG	☒
23	05/05/20 12:15	General View		Load JPG	☒
24	05/05/20 12:15	General View		Load JPG	☒
25	05/05/20 12:15	General View		Load JPG	☒
26	05/05/20 12:15	General View		Load JPG	☒
27	05/05/20 12:15	General View		Load JPG	☒
28	05/05/20 12:15	General View		Load JPG	☒
29	05/05/20 12:15	General View		Load JPG	☒
30	05/05/20 12:15	General View		Load JPG	☒
31	05/05/20 12:15	General View		Load JPG	☒
32	05/05/20 12:15	General View		Load JPG	☒
33	05/05/20 12:15	General View		Load JPG	☒
34	05/05/20 12:15	General View		Load JPG	☒
35	05/05/20 12:15	General View		Load JPG	☒
36	05/05/20 12:15	General View		Load JPG	☒
37	05/05/20 12:15	General View		Load JPG	☒
38	05/05/20 12:15	General View		Load JPG	☒
39	05/05/20 12:15	General View		Load JPG	☒
40	05/05/20 12:15	General View		Load JPG	☒
41	05/05/20 12:15	General View		Load JPG	☒
42	05/05/20 12:15	General View		Load JPG	☒
43	05/05/20 12:15	General View		Load JPG	☒
44	05/05/20 12:15	General View		Load JPG	☒
45	05/05/20 12:15	General View		Load JPG	☒
46	10/06/20 10:26	Reinspection Photo		Load JPG	☒
47	10/06/20 10:26	Reinspection Photo		Load JPG	☒
48	10/06/20 10:26	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print
1	25/06/20 10:11	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee		Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	04/05/20 19:02	E-filed GIA report		Load PDF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	05/05/20 09:44	preli advice		Load PDF	
2	05/05/20 09:52	Sketch Plan From:SC - Reg. No: SLG6624G, Claimant: AUTO EXCHANGE LEASING PTE LTD		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI20005549/FVF3S2**Date:** 29/06/2020REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI001160
Claimant Vehicle No :	SHB3389D	Insured Vehicle No :	SLG6624G
Date of Loss:	01/05/2020	Nature of Claim:	TP
		Claim No:	M2002612

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3389D	Engine No:	D4FDDU391407
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMEU058668
Reg. Date:	07/08/2014 (Man. Year: 2014)	Odometer:	506776 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,434.42	952.40	482.02	33.60
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	720.00	540.00	180.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,165.42	1,503.40	662.02	30.57
Approved Total (Overridden) (S\$)		750.00		
(S\$)	2,165.42	750.00	1,415.42	65.36
+ GST 7.00/7.00% (S\$)	151.58	52.50	99.08	65.36
Nett Amount (S\$)	2,317.00	802.50	1,514.50	65.36

INSPECTION

Date of Assignment:	05/05/2020	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	04/05/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: PARASURAM SHANMUGAM**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB3389D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Deformed	1,106.00 FL	-	*1,106.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR BUMPER LOWER COVER	Not Necessary	228.00 FL	-	*- FL
4	1		*REAR BUMPER BRACKET LH	Not Necessary	35.60 FL	-	*- FL
5	1		*REAR FENDER SHIELD LH	Not Necessary	169.30 FL	-	*- FL
6	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 F	-	*- F
7	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	-	*50.00 FS
					Sub Total (\$\$)	1,746.60	1,178.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	312.18	225.60
					Total Parts (\$\$)	1,434.42	952.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	280.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	REMOVE/REFIX REVESRE SENSOR	New	120.00	60.00
Gross Labour Cost (\$\$)			720.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >