

VICOM LTD
SURVEY REPORT
Annex A: Adjustment on Spare Parts

Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustm (S\$)
1	Charge Air Cooler;Cool.Unit Xr ^	Bent/Replace	1148.00	1148.00
1	Exterior Rr O/S Corner;F/Glass	Cracked/Replace	732.00	732.00
2	Door Retainer Slam Lock	Bent/Replace	29.00	29.00
1	Door Microswitch-Adjustable;Rr Eng Dr	Bent/Replace	78.00	78.00
1	Sealed Lever Latch;Os/Ns;Rr Side Dr	Necessary/Replace	68.00	34 68.00
1	Hydraulic Oil Cooler;Cooling Unit	Bent/Replace	309.00	309.00
2	Ss 4 X4 X3mm 5 Joint Butt Hinge	Bent/Replace	113.00	113.00
1	O/S Lower Eng Access Door;Sheetmetal	Bent/Replace	1626.00	1626.00
1	Radiator Flyscreen;O/S Lower Eng Access	Bent/Replace	386.00	386.00
0	Sika 552 White 600ml Sausage	Necessary/Replace	84.00	84.00
1	Clamp;Charge Air-Cooler To Eng	Necessary/Replace	32.00	32.00
2	Hose 1040mm;Hyd.Eqpt.	No Visible Damaged	61.00	0.00
3	Sealing Ring;Charge-Air Coolers	Necessary/Replace	4.00	4.00
4	Hydraulic Hose;Hyd.Motor;Fan Dr	Intact	151.00	0.00
5	Rear Reverse Lamp;B9tl Eu5	Cracked/Replace	81.00	81.00
6	Reflex Reflector	Cracked/Replace	1.00	1.00
7	Led Stop/Tail Light 24v;30541713 1 Led	Cracked/Replace	65.00	65.00
8	Led Indicator Light 24v;30541714 1 Led	Cracked/Replace	65.00	65.00
9	Profile.Eng Module	No Visible Damaged	821.00	0.00
Subtotal			5854.00	4821.00
TOTAL			5854.00	4821.00

TOTAL FOR SPARE PARTS

: 5854.00

~~4821.00~~

3932

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

Job Description	Workshop Estimate (S\$)	VAC Adjustm (S\$)
Assesement of bus (contractor repairs)	188.00	150 188.00
Contractor's repair charges	5328.60	1800 2400.00
TOTAL FOR LABOUR AND SPRAY PAINTING	5516.60	2588.00
		1950

Summary

Description	Workshop Estimate (S\$)	VAC Adjustm (S\$)
TOTAL FOR SPARE PARTS	: 5854.00	4821.00
TOTAL FOR LABOUR AND SPRAY PAINTING	: 5516.60	2588.00
TOTAL REPAIR COST	: 11370.60	7409.00
	3932	
	1950	
	<u>5882</u>	
	<u>6 days</u>	