

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005559/KKA3Q2

Date: 16/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900264448

Claimant
Vehicle No : SMS3716U **Insured Vehicle No :** SMR3852P

Date of Loss: 03/05/2020 Nature of Claim: TP Claim No: 7018957341SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS3716U		
Make & Model:	NISSAN NOTE, 1.2 (A)	Engine No:	HR12046561K
Reg. Date:	24/02/2020 (Man. Year: 2019)	Chassis No:	E12628839
Colour:	Metallic Blue	Odometer:	1277 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,535.60	4,265.46	3,270.14	43.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	1,780.00	2,180.00	55.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,495.60	6,045.46	5,450.14	47.41
+ GST 7.00/7.00% (S\$)	804.69	423.18	381.51	47.41
Nett Amount (S\$)	12,300.29	6,468.64	5,831.65	47.41
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		107.00		
Nett Liability (S\$)		7,326.64		
Global Sum Settlement (S\$)		7,300.00		

INSPECTION

Date of Assignment: 05/05/2020

Date Inspected: 06/05/2020 Inspected At:

MBM Wheelpower Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-15, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	939.00 FL	*534.90 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	55.00 FL	*55.00 FL
3	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	55.00 FL	*55.00 FL
4	1		*FRONT BUMPER LOWER RH COVER	Serviceable	57.00 FL	*- FL
5	1		*FRONT BUMPER LOWER LH COVER	Distorted	57.00 FL	*57.00 FL
6	1		*FRONT BUMPER SPONGE	Cracked	236.00 FL	*152.10 FL
7	1		*FRONT REINFORCEMENT	Repair	406.00 FL	*- FL
8	1		*RADIATOR GRILLE ASSY	Distorted / Dented	475.00 FL	*376.30 FL
9	1		*RADIATOR GRILLE TOP COVER	Mtg Cracked	324.00 FL	*276.50 FL
10	1		*FRONT LH FENDER	Repair	604.00 FL	*- FL
11	1		*FRONT LH FENDER INNER SHIELD	Distorted	140.00 FL	*140.00 FL
12	1		*FRONT RH FENDER	Repair	604.00 FL	*- FL
13	1		*FRONT RH FENDER INNER SHIELD	Distorted	140.00 FL	*140.00 FL
14	1		*HEAD LAMP RH	Mtg Broken	1,836.00 FL	*1,416.30 FL
15	1		*HEAD LAMP LH	Mtg Broken	1,836.00 FL	*1,416.30 FL
16	10		*BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
17	10		*FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*60.00 FL
18	2		*DISTANCE SENSOR	Serviceable	400.00 FL	*- FL
19	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,364.00	4,739.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	828.40	473.94
Total Parts (\$\$)	7,535.60	4,265.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	600.00
2	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	100.00	0.00
3	TO RESET ENGINE WARNING LIGHT (ABS ,SRS ,ECU MEMORY & ETC)	New	250.00	0.00
4	TO APPLY ANTI RUST COATING	New	150.00	0.00
5	TO REMOVE ,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
6	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	60.00
7	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
8	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,500.00	800.00
9	TO CONDUCT RE-ALIGNMENT OF FRONT CHASSIS ON (CAR-O-LINER)	New	350.00	250.00
10	TOWING	New	120.00	50.00
Gross Labour Cost (\$)			3,960.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >