



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 1452E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	TORN	1,250.00	1,050.00
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	BROKEN	28.70	28.70
1	RH FRONT HEADLAMP (CONSISTENT)	CUT	950.00	950.00
1	RH FRONT FENDER (CONSISTENT)	DENTED	511.90	460.00
1	RH FRONT FENDER INNER COWLING (CONSISTENT)	DEFORMED	145.00	145.00
1	RH FRONT WHEEL CAP (CONSISTENT)	CUT	195.00	150.00
1	RH FRONT DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	757.20	-
1	RH FRONT WIND MIRROR (CONSISTENT)	NOT NECESSARY	527.50	-
1	RH FRONT FRONT WIND MIRROR COVER (CONSISTENT)	NOT NECESSARY	67.30	-
1	RH ROCKER PANEL GARNISH (CONSISTENT)	NOT NECESSARY	593.20	-
1	RH FRONT FENDER EMBLEM HYBRID (CONSISTENT)	NECESSARY	90.10	60.00
	LESS 20% DISCOUNT		-1,023.18	-568.74
			4,092.72	2,274.96
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	80.00	30.00
1	SET RH FRONT FENDER INNER COWLING CLIPS (SN) (CONSISTENT)	NECESSARY	80.00	20.00
1	SET RH ROCKER PANEL GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	RH ROCKER PANEL GARNISH SEAL (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	MISCELLANEOUS (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
			400.00	50.00
<b><u>LABOUR</u></b>				
	TO CHECK ELECTRICAL WIRING .		80.00	30.00
	REMOVE AND TRANSFER ALL RH FRONT DOOR FITTING.	NOT NECESSARY	150.00	-
	TO RESPRAY UNDERCOATING .	NOT NECESSARY	100.00	-
	APPLY ANTI RUST ON AFFECTED AREAS .		150.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS .		800.00	600.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF RH FRONT DOOR .		800.00	500.00
			2,080.00	1,160.00
GRAND TOTAL			6,572.72	3,484.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CC4/ASM20005568/Eba3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.