



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM20005568/Eba3q2 Date: 14/05/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMA 1500H	Veh. Inspected	SML 1452E
	Policy No.	GA478755/1	Coverage (\$)	0.00
	Claim No.	S0M02NHJ	Excess (\$)	0.00
	Assign From		Assign Date	05/05/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP72009063	Colour	GREY
	Odometer	74734 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	WEST LAKE	5 mm
	L/H Front Tyre	185/60 R15	WEST LAKE	5 mm
	R/H Rear Tyre	185/60 R15	WEST LAKE	5 mm
	L/H Rear Tyre	185/60 R15	WEST LAKE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/04/2020	Inspection Date	05/05/2020
	Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	