Adjuster Report Page 1 of 4

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005572/KBA3Q2

**Date:** 22/09/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant
Whitela No: SMN1822K

Insured Vehicle No: SHD4343T

Vehicle No: Sivin 1022N Insured Vehicle No. Ship 43431

Date of Loss: 04/05/2020 Nature of Claim: TP Claim No: MCT18050958

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMN1822K

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB7112247
Reg. Date: 26/07/2019 (Man. Year: 2019) Chassis No: GP72009807
Colour: Metallic Dark Blue Odometer: 52897 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Windforce 4 mm Rear Left Side: Yokohama 3 mm
Front Right Side: Windforce 4 mm Rear Right Side: Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,604.00	0.00	1,604.00	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,620.00	600.00	1,020.00	62.96
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	3,224.00	600.00	2,624.00	81.39
	+ GST 7.00/7.00% (S\$)	225.68	42.00	183.68	81.39
	Nett Amount (S\$)	3,449.68	642.00	2,807.68	81.39

+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$) 385.20

Nett Liability (\$\$) 1,027.20

Global Sum Settlement (\$\$) 1,000.00

\_\_\_\_

**INSPECTION** 

Date of Assignment: 06/05/2020

Date Inspected: 12/08/2020 Inspected At: MBM Wheelpower Pte Ltd (Sin Ming)

176 Sin Ming Drive #01-15, Sin Ming

AutoCare

Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 31 Aug 2020)

Parts: N/A HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMN1822K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT RH DOOR	Repair	1,154.00 FL	*- FL	
2	1		*FRONT RH DOOR HINGE UPP	Repair	78.00 FL	*-FL	
3	1		*FRONT RH DOOR HINGE LOWER	Repair	78.00 FL	*-FL	
4	1		*RH SIDE SKIRT	Serviceable	535.00 FL	*- FL	
5	1		*SET FRONT RH DOOR TAPE	Not Necessary	60.00 FL	*- FL	
6	1		*BODY SEALANT	Not Necessary	80.00 FS	*-FS	
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.				
				Sub Total (S\$)	1,985.00	0.00	
	- List Item Discount on L Items 20.00/20.00% (S\$)			381.00	0.00		
				Total Parts (S\$)	1,604.00	0.00	

C = = = 111 = =

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	700.00	200.00				
2	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	100.00	0.00				
3	TO REMOVE & REPLACE BUMPER SENSORS	New	40.00	0.00				
4	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	0.00				
5	TO SPRAY PAINT ON THE AFFECTED AREAS	New	700.00	400.00				
	Gross Labour Cost (S\$)		1,620.00	600.00				

< END OF ESTIMATES >

Report was unsubmitted during this print-out.