

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005579/T1RS3Q2

Date: 27/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900190072

Claimant Vehicle No : SFA1604A **Insured Vehicle No :** SMP7011J

Date of Loss: 04/05/2020 Nature of Claim: TP Claim No: 5593284050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFA1604A	Engine No:	CDN296616
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Chassis No:	WAUZZZ4G2DN043978
Reg. Date:	31/10/2012 (Man. Year: 2012)	Odometer:	129864 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,369.56	3,893.22	476.34	10.90
Miscellaneous Items	11.77	11.77	0.00	0.00
Labour	128.00	128.00	0.00	0.00
Paintwork Labour	1,216.00	416.00	800.00	65.79
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,725.33	4,448.99	1,276.34	22.29
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	5,725.33	3,500.00	2,225.33	38.87
+ GST 7.00/7.00% (S\$)	400.77	245.00	155.77	38.87
Nett Amount (S\$)	6,126.10	3,745.00	2,381.10	38.87
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Car Rental (2.0 x S\$140.00/day) (S\$)		280.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		4,256.00		

INSPECTION

Date of Assignment: 06/05/2020 Present Location:

Date Inspected: 05/05/2020 Inspected At:

Ryder Auto Pte Ltd (HQ)

Ryder Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2, #02-19 AutoHub

@ Kaki Bukit

Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ECO-DISPOSAL FEE BUMPER	Necessary	-	*30.00 FS
2	1	NA	*L/R OUT BUMPER GUIDE	Not Necessary	40.65 F	*- F
3	1	NA	*L/SCREW	Necessary	20.00 F	*20.00 F
4	1	NA	*R/R OUT BUMPER GUIDE	Not Necessary	40.65 F	*- F
5	1	NA	*R/SCREW	Necessary	18.00 F	*18.00 F
6	1	NA	*REAR BUMPER	Deformed	1,921.40 F	*1,921.40 F
7	1	NA	*REAR BUMPER GUARD	Cut	255.95 F	*255.95 F
8	1	NA	*RR BUMP IMPACT SUPP	Bent	754.00 F	*754.00 F
9	1	NA	*RR CTR BUMPER GUIDE	Not Necessary	90.65 F	*- F
10	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 F	*- F
11	1	NA	*3m sticker 3m sticker	Necessary	500.00 F	*300.00 FS
					Sub Total (\$\$)	3,641.30 3,299.35
					+ Margin on L,N Items 20.00/20.00% (\$\$)	728.26 593.87
					Total Parts (\$\$)	4,369.56 3,893.22

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.77	11.77
Sub Total (\$\$)			11.77	11.77

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	216.00	216.00
2	Total Paint Materials	New	1,000.00	200.00
Labour Items				
3	Total Panel/Mechanical Labour	New	128.00	128.00
Gross Labour Cost (\$\$)			1,344.00	544.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >