

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 INV No. AC2003949

INV Date 15/05/2020

Reference CS/FCI20005608/Gsf3n2

Code FCI2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SMG 1093J

Insured Veh. SHD 3638A

Claim No. D20002043MFSH

Policy No.

Accident Date 03/05/2020

Inspection Date 08/05/2020

Description	Total
Survey Inspection	341.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	341.00
GST (7%)	23.87
Grand Total	364.87

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile							
MS F	IRST CAPITAL IN	SURANCE LTD	Ref : CS/FCI20005608/G	Gsf3n2				
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 15-05-2020 Code: FCI2						
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SHD 3638A	Veh. Inspected	SMG 1093J				
	Policy No.		Coverage (\$)	0.00				
	Claim No.	D20002043MFSH	Excess (\$)	0.00				
	Assign From	RACHEL WU	Assign Date	06/05/2020				
2.		Vehicle Partic	ulars & Condition					
	Make & Model	TOYOTA NOAH 1.8X	c.c	1797				
	Engine No.	HIDDEN	Year of Reg.	2018				
	Chassis No.	ZWR800352179	Colour	BLACK				
	Odometer	105135	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	SPORTS RIM				
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm				
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm				
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm				
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm				
4.		Description	on of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.					
	DAMAGES SEE DI	ETAILS.						
5.		General	Information					
	Accident Date	03/05/2020	Inspection Date	08/05/2020				
	Survey held at	E M SOLUTION PTE LTD						
		BLK 17 SIN MING IND. ESTATE SECTOR A #01-59 SINGAPORE 575675						
5a.	1	Re	emarks					
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	Estimate Days of Repair							
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	5 Working Days					



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 1093J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	688.60	688.60
1	REAR BUMPER TOW HOOD COVER	NOT NECESSARY	44.10	-
2	REAR BUMPER REFLECTORS @\$71.90	NOT NECESSARY	143.80	-
2	REAR BUMPER SIDE RETAINERS @\$125.30	N/S CRACKED / O/S NOT NECESSARY	250.60	99.00
1	TAIL GATE	BUCKLED	1,885.90	1,712.85
1	TAIL GATE "HYBRID SYNERGY DRIVE" BADGE	NECESSARY	67.80	67.80
1	TAIL GATE OUTER CHROME GARNISH	NOT NECESSARY	682.90	-
1	TAIL GATE EMBLEM	NOT NECESSARY	69.70	-
2	TAIL GATE NUMBER PLATE LAMPS @\$76.70	NOT NECESSARY	153.40	-
1	TAIL GATE RUBBER	TWISTED	396.50	368.00
1	TAIL GATE WIPER MOTOR	NOT NECESSARY	661.90	-
1	TAIL GATE INNER TRIM	NOT NECESSARY	679.84	-
1	TAIL GATE INNER PULL HANDLE	NOT NECESSARY	52.90	-
1	TAIL GATE INNER LOCK	CUT	386.95	386.95
1	REAR LOCK SENSOR	NOT NECESSARY	162.20	-
1	REAR END PANEL	BUCKLED	768.90	530.00
1	REAR END PANEL TOP GARNISH	DEFORMED	235.00	235.00
1	REAR FLOOR PANEL	NOT NECESSARY	798.40	-
1	REAR FLOOR COVER	NOT NECESSARY	821.95	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	922.60	-
2	REAR EXHAUST MOUNTINGS @\$49.70	NOT NECESSARY	99.40	-
	LESS 25% DISCOUNT		-2,493.34	-1,022.05
			7,480.00	3,066.15
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	45.00	20.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REVERSE SENSOR (SN)	DAMAGED	270.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	480.00	-

Report Ref No. CS/FCI20005608/Gsf3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,800.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	TAIL GATE INNER TRIM CLIPS (SN)	NECESSARY	40.00	20.00
			895.00	280.00
	<u>LABOUR</u>			
	CHECK WIRINGS AND HEADLAMP FOCUS.	NOT NECESSARY	60.00	-
	RENEW REVERSE SENSOR.		80.00	40.00
	RENEW REVERSE CAMERA.		80.00	40.00
	REMOVE OUT & REFIT REAR WINDSCREEN.		150.00	100.00
	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS.		980.00	600.00
	SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS.		980.00	600.00
	RENEW REAR EXHAUST SILENCER.	NOT NECESSARY	100.00	-
	RUST PROOFING ON ACCIDENT AFFECTED PORTIONS.		80.00	60.00
			2,510.00	1,440.00
	GRAND TOTAL		10,885.00	4,786.15

Report Ref No. CS/FCI20005608/Gsf3n2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

8

**XING GUO QIANG** 

M.MATAI, AMSAE-A
Automotive Assessor

X:2.

**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMG 1093J

### INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMG 1093J

RE-INSPECTION





