Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AXA16009808/KKA3Q2-1

Date: 24/11/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: GA053527

Claimant Vehicle No: Insured Vehicle No: EX999H

Date of Loss: 24/05/2016 Nature of Claim: TP Claim No: C0385417

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5956Z

 Make & Model:
 RENAULT LATITUDE, 2.0 D dCi (A)
 Engine No:
 M9R8839C002508

 Reg. Date:
 23/03/2015 (Man. Year: 2015)
 Chassis No:
 VF1ABL15AUC281473

Colour: Metallic White/Red Odometer: 143216 km

Engine Capacity: 1995 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Rovelo 6 mm Rear Left Side: Rovelo 4 mm
Front Right Side: Rovelo 6 mm Rear Right Side: Rovelo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,730.78	2,002.94	24,727.84	92.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,790.00	480.00	12,310.00	96.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	39,520.78	2,482.94	37,037.84	93.72
+ GST 7.00/7.00% (S\$)	2,766.45	173.81	2,592.64	93.72
Nett Amount (S\$)	42,287.23	2,656.75	39,630.48	93.72
+ Loss of Use (3.5 x \$	S\$50.00/day) (S\$)	175.00		
+ Car Rental (3.5 x S	\$132.68/day) (S\$)	464.38		
	(S\$)	3,296.13		
Liable Amo	1,648.07			
+ Doc/Search Fee (S\$)		6.00		
1	Nett Liability (S\$)	1,654.07		
Global Sum Settlement (S\$)		1,650.00		

INSPECTION

Date of Assignment: 27/05/2016

Date Inspected: 26/05/2016 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111 Adjuster Report Page 2 of 5

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference					
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2018)			
Parts:	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	(Unsubmitted, no print-code for SHC5956Z)				
Validity:	Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.					

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR (CONSISTENT)	Buckled / Cracked	852.66 FL	*852.66 FL
2	1		*BUMPER LOWER REAR (CONSISTENT)	Dented / Cut	591.41 FL	*591.41 FL
3	1		*BUMPER BRACKET CTR REAR (CONSISTENT)	Serviceable	87.29 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR (TAILLAMP LOWER)(CONSISTENT)	Serviceable	104.59 FL	*- FL
5	1		*BUMPER RETAINER RH REAR (CONSISTENT)	Serviceable	34.61 FL	*-FL
6	1		*BUMPER REFLECTOR RH (CONSISTENT)	Serviceable	33.55 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER)(CONSISTENT)	Serviceable	104.59 FL	*-Fl
8	1		*BUMPER RETAINER LH REAR (CONSISTENT)	Serviceable	34.61 FL	
9	1		*BUMPER REFLECTOR LH (CONSISTENT)	Serviceable	33.55 FL	*- FL
10	1		*BUMPER BEAM REAR (CONSISTENT)	Bent	598.09 FL	*598.09 FL
11	1		*BUMPER BEAM BRACKET LH REAR (CONSISTENT)	Repair	173.81 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR (CONSISTENT)	Repair	173.81 FL	*-FL
13	1		*BOOT REAR (CONSISTENT)	Repair	2,209.75 FL	*- FL
14	1		*BOOT FINISHER (MOULDING) (CONSISTENT)	Serviceable	429.90 FL	*-FL
15	1		*BOOT WEATHERSTRIP (CONSISTENT)	Serviceable	248.50 FL	*- FL
16	1		*BOOT REFLECTOR LAMP RH (CONSISTENT)	Serviceable	379.50 FL	*- FL
17	1		*BOOT REFLECTOR LAMP LH (CONSISTENT)	Serviceable	379.50 FL	*- FL
18	1		*BOOT BADGE RENAULT (CONSISTENT)	Not Necessary	173.35 FL	*- FL
19	1		*BOOT BADGE (CONSISTENT)	Not Necessary	173.35 FL	*- FL
20	1		*BOOT STRUT (SPRING) (CONSISTENT)	Serviceable	212.36 FL	*- FL
21	1		*BOOT HINGE LH (CONSISTENT)	Repair	282.96 FL	
22	1		*BOOT HINGE RH (CONSISTENT)	Repair	282.96 FL	
23	1		*BOOT INNER TRIM (CONSISTENT)	Serviceable	586.45 FL	*- FL
24	1		*BOOT SWITCH (CONSISTENT)	Serviceable	107.78 FL	
25 26	1		*BOOT LOCK (CONSISTENT)	Repair	155.90 FL	*- FL *- FL
	1		*BOOT LOCK CATCH (CONSISTENT)	Repair	72.00 FL 170.63 FL	
27 28	2		*BOOT RUBBER PLUG (CONSISTENT) *FENDER PANEL REAR LH (CONSISTENT)	Serviceable Repair	2,537.80 FL	*- FL
20 29	1		*FENDER WHEELARCH REAR LH (LINNER)	Serviceable	418.06 FL	*-FL
29 30	1		(CONSISTENT) *FENDER INNER TRIM LH (CONSISTENT)	Serviceable	430.42 FL	- r i *- F l
30 31	1		*FENDER PANEL REAR RH (CONSISTENT)		2,537.80 FL	
31 32	1		*FENDER WHEELARCH REAR RH (LINNER)	Repair Serviceable	418.06 FL	*- FL *- FL
	1		(CONSISTENT)			
33	1		*FENDER INNER TRIM RH (CONSISTENT)	Serviceable	430.42 FL	*- FL
34	1		*TAILLAMP RH (CONSISTENT)	Serviceable	425.04 FL	
35	1		*TAILLAMP PANEL RH (CONSISTENT)	Repair	759.00 FL	*- FL
36	1		*TAILLAMP LH (CONSISTENT)	Serviceable	425.04 FL	
37	1		*TAILLAMP PANEL LH (CONSISTENT)	Repair	759.00 FL	
38	1			Repair	1,684.52 FL	*- FL

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)			
39	1		*SPARE WHEEL PANEL TRIM (CONSISTENT)	Serviceable	470.93 FL	*-FL
40	1		*OUTER PANEL REAR (END PANEL) (CONSISTENT)	Repair	1,132.13 FL	*- FL
41	1		*OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	Serviceable	311.20 FL	*-FL
42	1		*EXHAUST REAR (CONSISTENT)	Repair	5,760.00 FL	*- FL
43	1		*EXHAUST CAP REAR (CONSISTENT)	Repair	177.30 FL	*- FL
44	1		*SET PARKING AID (CONSISTENT)	Serviceable	600.00 FS	*-FS
45	1		*SET REAR BUMPER CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
46	1		*SET BUMPER BRACKET CTR CLIP (CONSISTENT)	Necessary	33.00 FS	*33.00 FS
47	1		*SET BUMPER BRACKET SIDE CLIP RH RR (CONSISTENT)	Not Necessary	10.00 FS	*-FS
48	1		*SET BUMPER RETAINER RH CLIP RR (CONSISTENT)	Not Necessary	20.00 FS	*-FS
49	1		*SET BUMPER BRACKET SIDE CLIP LH RR (CONSISTENT)	Not Necessary	10.00 FS	
50	1		*SET BUMPER RETAINER CLIP LH RR (CONSISTENT)	Not Necessary	20.00 FS	*-FS
51	1		*SET BUMPER LOWER REAR CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
52	1		*EXHAUST MOUNTING REAR (CONSISTENT)	Serviceable	17.82 FS	*-FS
53	1		*SET BOOT FINISHER CLIP (CONSISTENT)	Not Necessary	24.20 FS	*-FS
54	1		*BOOT STICKER TRANS-CAB (CONSISTENT)	Not Necessary	30.00 FS	*-FS
55	1		*BOOT STICKER 6555-3333 (CONSISTENT)	Not Necessary	30.00 FS	*-FS
56	1		*BOOT INNER TRIM CLIP (CONSISTENT)	Not Necessary	45.00 FS	*-FS
57	1		*SET FENDER WHEELARCH REAR RH CLIP (CONSISTENT)	Not Necessary	35.00 FS	*-FS
58	1		*SET FENDER WHEELARCH REAR LH CLIP (CONSISTENT)	Not Necessary	35.00 FS	*-FS
59	1		*FENDER INNER TRIM CLIP LH (CONSISTENT)	Not Necessary	28.00 FS	
60	1		*FENDER INNER TRIM CLIP LH (CONSISTENT)	Not Necessary	28.00 FS	
61	1		*TAILLAMP CLIP RH (CONSISTENT)	Not Necessary	5.00 FS	
62	1		*TAILLAMP CLIP LH (CONSISTENT)	Not Necessary	5.00 FS	
63	2		*REAR WINDSCREEN SEALANT (CONSISTENT)	Not Necessary	80.00 FS	*-FS
64	1		*WINDSCREEN MOULDING (CONSISTENT)	Serviceable	100.00 FS	
65	1		*REAR WINDSCREEN INNER SPONGE SEAL (CONSISTENT)	Not Necessary	100.00 FS	*-FS
66	1		*SPARE TYRE RIM (ROUE 7J 16H 2547) (CONSISTENT	Serviceable	385.00 FS	*-FS
67 F=Fra	1 anchise	part. S=	*SPARE TYRE (CONSISTENT) SpcNett. L=ListItemDisc.	Serviceable	330.00 FS	*-FS
				Sub Total (S\$)		2,207.16
			- List Item Discount on L Items 1	0.00/10.00% (S\$)	2,736.42	204.22
				Total Parts (S\$)	26,730.78	2,002.94

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	5,400.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	5,600.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
7	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
8	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
	Gross Labou	r Cost (S\$)	12,790.00	480.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >