

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC3/AXA16008447/KGA3Q2-1  
**Date:** 06/07/2022

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: GA061929  
**Claimant Vehicle No :** SHF710H **Insured Vehicle No :** SKP4291K  
 Date of Loss: 04/05/2016 Nature of Claim: TP Claim No: C0382818

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF710H**  
 Make & Model: RENAULT LATITUDE, 2.0 CVT ABS (A) Engine No: M9R8839C002362  
 Reg. Date: 31/12/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC281197  
 Colour: Metallic White/Red Odometer: 141872 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
 Front Left Side: Goodyear 4 mm Rear Left Side: Falken 7 mm  
 Front Right Side: Goodyear 4 mm Rear Right Side: Falken 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,615.73	75.00	7,540.73	99.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	540.00	3,260.00	85.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,415.73</b>	<b>615.00</b>	<b>10,800.73</b>	<b>94.61</b>
<b>+ GST 7.00/7.00% (S\$)</b>	799.10	43.05	756.05	94.61
<b>Nett Amount (S\$)</b>	<b>12,214.83</b>	<b>658.05</b>	<b>11,556.78</b>	<b>94.61</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$132.68/day) (S\$)</b>		398.04		
<b>(S\$)</b>		1,206.09		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>603.05</b>		
<b>+ Doc/Search Fee (S\$)</b>		6.00		
<b>Nett Liability (S\$)</b>		<b>609.05</b>		
<b>Global Sum Settlement (S\$)</b>		<b>600.00</b>		

INSPECTION

Date of Assignment: 10/05/2016  
 Date Inspected: 06/05/2016 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
 2, Ang Mo Kio Street 63  
 Singapore 569111  
 Estimated Period of Repair: 1.0 days

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jun 2017)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHF710H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT (CONSISTENT)	Serviceable	968.78 FL	*- FL
2	1		*BUMPER ABSORBER FRT (CONSISTENT)	Serviceable	303.60 FL	*- FL
3	1		*BUMPER FOG LAMP GRILLE RH (CONSISTENT)	Serviceable	159.40 FL	*- FL
4	1		*BUMPER RETAINER FRT RH (CONSISTENT)	Serviceable	116.47 FL	*- FL
5	1		*BUMPER SUPPORT FRT RH (CONSISTENT)	Serviceable	18.37 FL	*- FL
6	1		*FENDER PANEL FRT RH (CONSISTENT)	Repair	602.95 FL	*- FL
7	1		*FENDER WHEELARCH FRT RH (CONSISTENT)	Serviceable	107.33 FL	*- FL
8	1		*HEADLAMP RH (CONSISTENT)	Serviceable	911.10 FL	*- FL
9	1		*DOOR MIRROR RH (CONSISTENT)	Serviceable	1,141.08 FL	*- FL
10	1		*DOOR PANEL FRT RH (CONSISTENT)	Repair	2,188.20 FL	*- FL
11	1		*DOOR SEAL FRT RH (CONSISTENT)	Serviceable	52.83 FL	*- FL
12	1		*ROCKER PANEL OUTER RH (CONSISTENT)	Serviceable	759.61 FL	*- FL
13	1		*SET FRONT BUMPER CLIP (CONSISTENT)	Not Necessary	66.00 FS	*- FS
14	1		*SET WHEELARCH CLIP RH (CONSISTENT)	Not Necessary	66.00 FS	*- FS
15	1		*CAP HUB RH FRT (CONSISTENT)	Serviceable	35.00 FS	*- FS
16	1		*RIM RH FRT (CONSISTENT)	Serviceable	385.00 FS	*- FS
17	1		*TYRE RH FRT (CONSISTENT)	Serviceable	330.00 FS	*- FS
18	1		*DOOR SEAL CLIP FRT RH (CONSISTENT)	Not Necessary	4.68 FS	*- FS
19	1		*DOOR STICKER TRANS-CAB (CONSISTENT)	Necessary	80.00 FS	*60.00 FS
20	1		*DOOR STICKER CLASSIC (CONSISTENT)	Necessary	30.00 FS	*15.00 FS
21	1		*SET BUMPER SUPPORT FRT CLIP RH (CONSISTENT)	Not Necessary	9.80 FS	*- FS
22	1		*SET BUMPER RETAINER FRT CLIP RH (CONSISTENT)	Not Necessary	12.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,348.70</b>	<b>75.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	732.97	0.00
<b>Total Parts (\$\$)</b>	<b>7,615.73</b>	<b>75.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,500.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,400.00	100.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	-
4	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
6	TO TRANSFER OF DOOR FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
<b>Gross Labour Cost (\$\$)</b>			<b>3,800.00</b>	<b>540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >