

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AXA16004071/KEA3Q2-1

**Date:** 01/04/2021

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA041467

**Claimant**

**Vehicle No :** SHB9644C

**Insured Vehicle No :**

SKD4222Z

Date of Loss: 01/03/2016

Nature of Claim:

TP

Claim No: C0374251

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SHB9644C**

Make & Model:

RENAULT LATITUDE, 2.0 CVT ABS (A)

Engine No:

M9R8839C001915

Reg. Date:

30/09/2014 (Man. Year: 2014)

Chassis No:

VF1ABL15AUC279415

Colour:

Red/White

Odometer:

178113 km

Engine Capacity:

1995 cc

Market Value/New Car

N/A

Price:

Sum Insured (\$\$):

**Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side:

Rovelo 8 mm

Rear Left Side:

Goodyear 5 mm

Front Right Side:

Rovelo 8 mm

Rear Right Side:

Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	49,976.07	7,559.24	42,416.83	84.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	41,470.00	1,580.00	39,890.00	96.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>91,446.07</b>	<b>9,139.24</b>	<b>82,306.83</b>	<b>90.01</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>6,401.22</b>	<b>639.75</b>	<b>5,761.47</b>	<b>90.01</b>
<b>Nett Amount (\$\$)</b>	<b>97,847.29</b>	<b>9,778.99</b>	<b>88,068.30</b>	<b>90.01</b>
<b>+ Loss of Use (7.0 x S\$50.00/day) (\$\$)</b>		350.00		
<b>+ Car Rental (7.0 x S\$132.68/day) (\$\$)</b>		928.76		
<b>+ Doc/Search Fee (\$\$)</b>		6.00		
<b>Nett Liability (\$\$)</b>		<b>11,063.75</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>11,060.00</b>		

### INSPECTION

Date of Assignment: 03/03/2016

Date Inspected: 01/03/2016 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 5.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2017)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB9644C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*BUMPER COVER FRT (BROKEN)</b>	Not Consistent With The Impact	968.79 FL	*- FL
2	1		<b>*BUMPER SPOILER FRT (Serviceable)</b>	Not Consistent With The Impact	139.81 FL	*- FL
3	1		<b>*BUMPER ABSORBER FRT (Cracked)</b>	Not Consistent With The Impact	303.60 FL	*- FL
4	1		<b>*BUMPER RETAINER FRT LH (Serviceable)</b>	Not Consistent With The Impact	116.47 FL	*- FL
5	1		<b>*BUMPER SUPPORT FRT LH (HEADLAMP LOWER) (Serviceable)</b>	Not Consistent With The Impact	18.37 FL	*- FL
6	1		<b>*BUMPER RETAINER FRT RH (Distorted)</b>	Not Consistent With The Impact	115.98 FL	*- FL
7	1		<b>*BUMPER SUPPORT FRT RH (HEADLAMP LOWER) (Serviceable)</b>	Not Consistent With The Impact	18.37 FL	*- FL
8	1		<b>*BUMPER UNDERTRAY FRT (Serviceable)</b>	Not Consistent With The Impact	363.71 FL	*- FL
9	1		<b>*BUMPER GRILLE LOWER FRT (Serviceable)</b>	Not Consistent With The Impact	205.23 FL	*- FL
10	1		<b>*BUMPER FOG LAMP GRILLE LH (Serviceable)</b>	Not Consistent With The Impact	159.39 FL	*- FL
11	1		<b>*BUMPER FOG LAMP GRILLE RH (Serviceable)</b>	Not Consistent With The Impact	159.39 FL	*- FL
12	1		<b>*BUMPER BEAM FRT (Repair)</b>	Not Consistent With The Impact	703.14 FL	*- FL
13	1		<b>*RADIATOR GRILLE (Cracked)</b>	Not Consistent With The Impact	1,313.68 FL	*- FL
14	1		<b>*RADIATOR GRILLE BADGE RENAULT (Necessary)</b>	Not Consistent With The Impact	173.36 FL	*- FL
15	1		<b>*RADIATOR GRILLE FRAME (Cracked)</b>	Not Consistent With The Impact	1,041.35 FL	*- FL
16	1		<b>*FRAME FULL SUPPORT PANEL (Cracked)</b>	Not Consistent With The Impact	473.77 FL	*- FL
17	1		<b>*FRAME FULL SUPPORT BRACKET (Repair)</b>	Not Consistent With The Impact	69.07 FL	*- FL
18	1		<b>*FRONT BRACE PANEL (Repair)</b>	Not Consistent With The Impact	136.32 FL	*- FL
19	1		<b>*SUBFRAME OUTER FRT (Serviceable)</b>	Not Consistent With The Impact	2,040.34 FL	*- FL
20	1		<b>*HORN BRACKET (Repair)</b>	Not Consistent With The Impact	31.12 FL	*- FL
21	1		<b>*HEADLAMP LH (Serviceable)</b>	Not Consistent With The Impact	911.10 FL	*- FL
22	1		<b>*HEADLAMP PANEL FRT LH (Repair)</b>	Not Consistent With The Impact	134.59 FL	*- FL
23	1		<b>*HEADLAMP RH (Mtg Cracked)</b>	Not Consistent With The Impact	911.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	1		*HEADLAMP PANEL FRT RH (Repair)	Not Consistent With The Impact	134.59 FL	*- FL
25	1		*BONNET (Repair)	Not Consistent With The Impact	1,493.56 FL	*- FL
26	1		*BONNET INSULATOR (Serviceable)	Not Consistent With The Impact	312.10 FL	*- FL
27	1		*BONNET HINGE LH (Repair)	Not Consistent With The Impact	267.93 FL	*- FL
28	1		*BONNET HINGE RH (Repair)	Not Consistent With The Impact	267.93 FL	*- FL
29	1		*BONNET LOCK (Repair)	Not Consistent With The Impact	234.99 FL	*- FL
30	1		*FENDER PANEL FRT LH (Repair)	Not Consistent With The Impact	602.95 FL	*- FL
31	1		*FENDER PANEL FRT RH (Repair)	Not Consistent With The Impact	602.95 FL	*- FL
32	1		*FENDER WHEELARCH FRT LH (LINER) (Serviceable)	Not Consistent With The Impact	107.32 FL	*- FL
33	1		*FENDER WHEELARCH FRT RH (LINER) (CONSISTENT)	Serviceable	214.49 FL	*- FL
34	1		*RADIATOR (CONSISTENT)	Serviceable	924.77 FL	*- FL
35	1		*ENGINE UNDERTRAY (CONSISTENT)	Serviceable	434.60 FL	*- FL
36	1		*A/C CONDENSER (CONSISTENT)	Serviceable	1,554.13 FL	*- FL
37	1		*TEANSMISSION COOLER (CONSISTENT)	Serviceable	852.66 FL	*- FL
38	1		*DOOR PANEL FRT LH (CONSISTENT)	Repair	2,188.20 FL	*- FL
39	1		*DOOR MIRROR LH (CONSISTENT)	Serviceable	1,141.08 FL	*- FL
40	1		*DOOR PANEL FRT RH (CONSISTENT)	Repair	2,188.20 FL	*- FL
41	1		*DOOR MIRROR RH (Serviceable)	Not Consistent With The Impact	1,141.08 FL	*- FL
42	1		*BUMPER COVER REAR (CONSISTENT)	Bent	852.66 FL	*852.66 FL
43	1		*BUMPER BRACKET CTR REAR (CONSISTENT)	Cracked	87.29 FL	*87.29 FL
44	1		*BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER) (CONSISTENT)	Serviceable	34.61 FL	*- FL
45	1		*BUMPER RETAINER LH REAR (CONSISTENT)	Serviceable	104.59 FL	*- FL
46	1		*BUMPER BRACKET SIDE RH REAR (TAILLAMP LOWER) (CONSISTENT)	Serviceable	34.61 FL	*- FL
47	1		*BUMPER RETAINER RH REAR (CONSISTENT)	Serviceable	104.59 FL	*- FL
48	1		*BUMPER LOWER REAR (CONSISTENT)	Bent	591.41 FL	*591.41 FL
49	1		*BUMPER BEAM REAR (CONSISTENT)	Bent	598.08 FL	*598.08 FL
50	1		*BUMPER BEAM BRACKET LH REAR (CONSISTENT)	Bent	173.81 FL	*173.81 FL
51	1		*BUMPER BEAM BRACKET RH REAR (CONSISTENT)	Bent	173.81 FL	*173.81 FL
52	1		*BUMPER REFLECTOR LH (CONSISTENT)	Cracked	33.55 FL	*33.55 FL
53	1		*BUMPER REFLECTOR RH (CONSISTENT)	Serviceable	33.55 FL	*- FL
54	1		*BOOT REAR (CONSISTENT)	Bent	2,209.75 FL	*2,209.75 FL
55	1		*BOOT FINISHER (CONSISTENT)	Serviceable	361.58 FL	*- FL
56	1		*BOOT LOCK (CONSISTENT)	Repair	155.90 FL	*- FL
57	1		*BOOT LOCK CATCH (CONSISTENT)	Repair	57.23 FL	*- FL
58	1		*BOOT WEATHERSTRIP (CONSISTENT)	Distorted /Dented	248.50 FL	*248.50 FL
59	1		*BOOT REFLECTOR LAMP LH (CONSISTENT)	Cracked	379.50 FL	*379.50 FL
60	1		*BOOT REFLECTOR LAMP RH (CONSISTENT)	Serviceable	379.50 FL	*- FL
61	1		*BOOT BADGE RENAULT (CONSISTENT)	Necessary	173.35 FL	*173.35 FL
62	1		*BOOT BADGE (CONSISTENT)	Necessary	173.35 FL	*173.35 FL
63	1		*BOOT STRUT LH (CONSISTENT)	Serviceable	212.36 FL	*- FL
64	1		*BOOT STRUT RH (CONSISTENT)	Serviceable	212.36 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
65	1		*BOOT HINGE LH (CONSISTENT)	Repair	282.96 FL	*- FL
66	1		*BOOT HINGE RH (CONSISTENT)	Repair	282.96 FL	*- FL
67	2		*LICENCE PLATE LAMP (CONSISTENT)	Serviceable	84.00 FL	*- FL
68	2		*BOOT RUBBER PLUG (CONSISTENT)	Serviceable	170.63 FL	*- FL
69	1		*TAILLAMP LH (CONSISTENT)	Mtg Cracked	425.04 FL	*425.04 FL
70	1		*TAILLAMP PANEL LH (CONSISTENT)	Repair	759.00 FL	*- FL
71	1		*TAILLAMP RH (CONSISTENT)	Serviceable	425.04 FL	*- FL
72	1		*TAILLAMP PANEL RH (CONSISTENT)	Repair	759.00 FL	*- FL
73	1		*FENDER PANEL REAR LH (CONSISTENT)	Repair	2,537.80 FL	*- FL
74	1		*FENDER PANEL REAR RH (CONSISTENT)	Repair	2,537.80 FL	*- FL
75	1		*FENDER WHEELARCH REAR LH (LINNER) (CONSISTENT)	Serviceable	418.06 FL	*- FL
76	1		*FENDER WHEELARCH REAR RH (LINNER) (CONSISTENT)	Serviceable	418.06 FL	*- FL
77	1		*AIR VENT RH (CONSISTENT)	Serviceable	74.83 FL	*- FL
78	1		*FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	Serviceable	516.50 FL	*- FL
79	1		*FENDER PANEL INNER TRIM REAR LH (CONSISTENT)	Serviceable	516.50 FL	*- FL
80	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	Repair	1,684.52 FL	*- FL
81	1		*SPARE WHEEL PANEL TRIM (LUGGAGE FLOOR PANEL) (CONSISTENT)	Serviceable	470.93 FL	*- FL
82	1		*OUTER PANEL REAR (END PANEL) (CONSISTENT)	Bent	1,132.13 FL	*1,132.13 FL
83	1		*OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	Buckled / Dented	308.48 FL	*308.48 FL
84	1		*EXHAUST REAR (CONSISTENT)	Repair	5,760.00 FL	*- FL
85	1		*EXHAUST CAP REAR (CONSISTENT)	Repair	177.30 FL	*- FL
86	1		*SET RADIATOR GRILLE FRAME CLIP (Necessary)	Not Consistent With The Impact	52.00 FS	*- FS
87	1		*SET BUMPER CLIP FRT (Necessary)	Not Consistent With The Impact	66.00 FS	*- FS
88	1		*BUMPER BRACKET CLIP FRT LH (Not Necessary)	Not Consistent With The Impact	12.00 FS	*- FS
89	1		*BUMPER SUPPORT CLIP FRT LH (Not Necessary)	Not Consistent With The Impact	10.50 FS	*- FS
90	1		*BUMPER BRACKET CLIP FRT RH (Not Necessary)	Not Consistent With The Impact	12.00 FS	*- FS
91	1		*BUMPER SUPPORT CLIP FRT RH (Not Necessary)	Not Consistent With The Impact	10.50 FS	*- FS
92	1		*TOW COVER FRT (Serviceable)	Not Consistent With The Impact	14.50 FS	*- FS
93	1		*SET RADIATOR GRILLE SCREW (Not Necessary)	Not Consistent With The Impact	16.00 FS	*- FS
94	1		*SET BUMPER GRILLE LOWER CLIP (Not Necessary)	Not Consistent With The Impact	69.00 FS	*- FS
95	1		*SET FRAME FULL SUPPORT PANEL CLIP (Necessary)	Not Consistent With The Impact	70.00 FS	*- FS
96	2		*FRAME FULL SUPPORT PANEL NUT (Not Necessary)	Not Consistent With The Impact	20.00 FS	*- FS
97	2		*FRAME FULL SUPPORT PANEL STUD (Not Necessary)	Not Consistent With The Impact	30.00 FS	*- FS
98	1		*SET WHEELARCH CLIP FRT LH (Not Necessary)	Not Consistent With The Impact	30.50 FS	*- FS
99	1		*SET WHEELARCH CLIP FRT RH (Not Necessary)	Not Consistent With The Impact	29.40 FS	*- FS
100	2		*BONNET CABLE CLIP (Not Necessary)	Not Consistent With The Impact	6.40 FS	*- FS
101	1		*SET BUMPER RR RIVET (CONSISTENT)	Necessary	28.60 FS	*28.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
102	1		*SET BUMPER RR CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
103	1		*SET BUMPER BEAM BOLT (CONSISTENT)	Serviceable	22.22 FS	*- FS
104	1		*SET REFLECTOR SCREW LH (CONSISTENT)	Serviceable	25.00 FS	*- FS
105	1		*SET PARKING AID (CONSISTENT)	Shorted	600.00 FS	*600.00 FS
106	1		*BUMPER BRACKET CLIP CTR REAR (CONSISTENT)	Not Necessary	15.00 FS	*- FS
107	1		*BUMPER BRACKET SIDE CLIP LH REAR (CONSISTENT)	Not Necessary	12.00 FS	*- FS
108	1		*BUMPER RETAINER CLIP LH REAR (CONSISTENT)	Not Necessary	10.40 FS	*- FS
109	1		*BUMPER BRACKET SIDE CLIP RH REAR (CONSISTENT)	Not Necessary	12.00 FS	*- FS
110	1		*BUMPER RETAINER CLIP RH REAR (CONSISTENT)	Not Necessary	10.40 FS	*- FS
111	1		*SET FENDER WHEELARCH CLIP LH RR (CONSISTENT)	Not Necessary	32.34 FS	*- FS
112	1		*SET FENDER WHEELARCH CLIP RH RR (CONSISTENT)	Not Necessary	32.34 FS	*- FS
113	1		*SPARE TYRE RIM (ROUE 7J 16H 2547) (CONSISTENT)	Serviceable	385.00 FS	*- FS
114	1		*SPARE TYRE (CONSISTENT)	Serviceable	330.00 FS	*- FS
115	1		*SET BOOT FINISHER CLIP (CONSISTENT)	Not Necessary	25.10 FS	*- FS
116	1		*REAR BOOT STICKER TRANS-CAB (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
117	1		*REAR BOOT STICKER 6555-3333 (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
118	1		*FENDER PANEL INNER TRIM CLIP REAR RH (CONSISTENT)	Not Necessary	22.00 FS	*- FS
119	1		*FENDER PANEL INNER TRIM CLIP REAR LH (CONSISTENT)	Not Necessary	22.00 FS	*- FS
120	2		*REAR WINDSCREEN SEALANT (CONSISTENT)	Not Necessary	80.00 FS	*- FS
121	1		*WINDSCREEN MOULDING (CONSISTENT)	Not Necessary	100.00 FS	*- FS
122	1		*REAR WINDSCREEN INNER SPONGE SEAL (CONSISTENT)	Not Necessary	100.00 FS	*- FS
123	1		*EXHAUST MOUNTING REAR (CONSISTENT)	Serviceable	65.50 FS	*- FS
124	1		*SET FRONT LICENCE PLATE WITH HOLDER (Necessary)	Not Consistent With The Impact	80.00 FS	*- FS
125	1		*SET REAR LICENCE PLATE WITH HOLDER (CONSISTENT)	Serviceable	80.00 FS	*- FS
126	1		*DOOR STICKER TRANS-CAB LH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
127	1		*DOOR STICKER CLASSIC LH (CONSISTENT)	Not Necessary	30.00 FS	*- FS
128	1		*DOOR STICKER TRANS-CAB RH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
129	1		*DOOR STICKER CLASSIC RH (CONSISTENT)	Not Necessary	30.00 FS	*- FS
130	1		*EXHAUST BRACKET REAR (CONSISTENT)	Serviceable	22.22 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 55,205.98 8,315.31**  
**- List Item Discount on L Items 10.00/10.00% (\$\$) 5,229.91 756.07**

**Total Parts (\$\$) 49,976.07 7,559.24**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	16,800.00	600.00
2	TOWING FEES	New	120.00	0.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	18,000.00	660.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
8	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO CHECK ABS BRAKE ,EFFICIENCY,FINAL CHECKING AND TESTING	New	380.00	0.00
12	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR	New	380.00	0.00
13	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
14	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
16	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
17	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
18	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
19	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
20	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
21	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
22	TO TRANSFER OF REAR WINDSCREEN FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
23	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
24	TO DROP REAR EXHAUST BOX,RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE }	New	280.00	60.00
25	TO REPAIR AND REALIGN REAR EXHAUST PIPE }	New	170.00	0.00
26	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
27	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY ,REMOVE AND RENEWAL OF PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>41,470.00</b>	<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >