

15/5/2010

INS. CASE OWNER:

Vale

CC 3 / AXA1600

11071, Kyg34

LKK:

IDAC:

ASSIGNMENT

Surveyor:

Kenneth

DOI:

11/3/16

Date / Time:

11/3/16

Registered in Merimen:

31/3/16

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKD 4222Z

Name of Insured:

Lai Fook Ming

Insured Tel No.:

HP:

96155168

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

D.O.A.: 11/3/16

Claim No.:

C0374251

Policy No.:

GA041467

Make / Model:

Nissan Sylphy-1.5 (M)

Place of Accident:

AYE 7 MCE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

SHB9644C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans-cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

3/3/16

Jus

09/03/2016 @

SHB9644C - CC 3 / AXA1600 / 05 / CM? n2 09/11/16

11:25am spoke to OI Lai Fook Ming
agreed accident detail but do not
agree if the amount of the taxi
claim if it is high. Refer to to
OI and file pay to OA. Lym.
to cancel with OI if any job. OI should
inform OI of TP

25-11-16

IF TP CANNOT PROVE THAT THERE WAS ANOTHER FRONT TAXI
INVOLVED, WE WOULD CONSIDER ONLY THE REAR PORTION
DAMAGE, PLS REMEMBER TO HIGHLIGHT TO TP IN THE COMING
BULK SETTLEMENT.

28-04-17

SINCE TP AGREED, GIVE THEM ANOTHER COUPLE OF WEEKS TO
PROVIDE, OTHERWISE TO PAY FOR REAR PORTION DAMAGE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 09/03/2016

After call ltr to OI: Lym

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Email

Call

Repair Cost:

SS

days Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

If NO or B 28, Ass. Lia:

Final Liability:

SS

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

SS

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

(\$ x days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

Legal Cost

SS

Total:

SS

Global Sum SS:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$250/-

REF: AAA

ASS. REC. BY:

ASSIGNMENTKenneth

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05 days

Res.: Yes or No

Lum Sum: _____

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SHB 9644CYr Regn: 09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renaultc.c. 1995Colour: White / Red

A/C: Insured / Std / NI / NA

Sp. Reading: 178113

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIAB215AUC279415

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Rovalo 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 2 mmR/Bal. 5 mmL/Bal. 2 mmL/Bal. 5 mmD.O.A. 1/3/16D.O.I. 1/3/16

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/3Est not ready2/3File pass to Cathrine\$9,139.24No finalised.Red C\$82,306.82 (90%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE SINGAPORE PTE LTD

Ref : CC3/AXA16004071/Kyg3

8 SHENTON WAY #27-01 SINGAPORE 068811

Date : 02-03-2016



Code : AXA2

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SKD 4222Z	Veh. Inspected	SHB 9644C
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	02/03/2016

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.	Accident Date	01/03/2016	Inspection Date	01/03/2016
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

Remarks

5a.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Date: 03 Mar 2016

Attn: Vale Oh

Preliminary Advice

Insured Vehicle No	: SKD4222Z	Accident Date	: 01/03/2016
TP Vehicle No	: SHB9644C	Assignment Date	: 03/03/2016
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 7 /Days
Date of Inspection	: 01/03/2016		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesRear & Front... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	91,446.06
Revised Amount	:S\$	15,253.71
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,253.71
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 9644C - AXA

ROEL

Not Notation
1.B.1
1.1

Resurvey By paint

SHB 9644C - ROEL
 VF1ABL15AUC279415
 RENAULT
 LATITUDE
 01.03.16
AXA

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Br</i> 968.79 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 139.81 X
3	1	BUMPER ABSORBER FRT	\$	<i>CRA</i> 303.60 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 116.47 X
5	1	BUMPER SUPPORT FRT LH (Headlamp lower)	\$	<i>Sn</i> 18.37 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 115.98 ✓
7	1	BUMPER SUPPORT FRT RH (Headlamp lower)	\$	<i>Sn</i> 18.37 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 363.71 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 205.23 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 159.39 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 159.39 X
12	1	BUMPER BEAM FRT	\$	<i>R</i> 703.14 X
13	1	RADAIOR GRILLE	\$	<i>CRA</i> 1,313.68 ✓
14	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>R</i> 173.36 ✓
15	1	RADAIOR GRILLE FRAME	\$	<i>CRA</i> 1,041.35 ✓
16	1	FRAME FULL SUPPORT PANEL	\$	<i>CRA</i> 473.77 ✓
17	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 69.07 X
18	1	FRONT BRACE PANEL	\$	<i>R</i> 136.32 X
19	1	SUBFRAME OUTER FRT	\$	<i>Sn</i> 2,040.34 X
20	1	HORN BRACKET	\$	<i>R</i> 31.12 X
21	1	HEADLAMP LH	\$	<i>Sn</i> 911.10 X
22	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 134.59 X
23	1	HEADLAMP RH	\$	<i>Mj CRA</i> 911.10 ✓
24	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 134.59 X
25	1	BONNET	\$	<i>R</i> 1,493.56 X
26	1	BONNET INSULATOR	\$	<i>Sn</i> 312.10 X
27	1	BONNET HINGE LH	\$	<i>R</i> 267.93 X
28	1	BONNET HINGE RH	\$	<i>R</i> 267.93 X
29	1	BONNET LOCK	\$	<i>R</i> 234.99 X
30	1	FENDER PANEL FRT LH	\$	<i>R</i> 602.95 X
31	1	FENDER PANEL FRT RH	\$	<i>R</i> 602.95 X
32	1	FENDER WHEELARCH FRT LH (Linner)	\$	<i>Sn</i> 107.32 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 9644C - AXA**ROEL**

33	1	FENDER WHEELARCH FRT RH (Linner)	\$	Sm 214.49 X
34	1	RADIATOR	\$	Sm 924.77 X
35	1	ENGINE UNDERTRAY	\$	Sm 434.60 X
36	1	A/C CONDENSER	\$	Sm 1,554.13 X
37	1	TRANSMISSION COOLER	\$	Sm 852.66 X
38	1	DOOR PANEL FRT LH	\$	R 2,188.20 X
39	1	DOOR MIRROR LH	\$	Sm 1,141.08 X
40	1	DOOR PANEL FRT RH	\$	R 2,188.20 X
41	1	DOOR MIRROR RH	\$	Sm 1,141.08 X
42	1	BUMPER COVER REAR	\$	B 852.66 ✓
43	1	BUMPER BRACKET CTR REAR	\$	CR 87.29 ✓
44	1	BUMEPR BRACKET SIDE LH REAR (Taillamp low)	\$	Sm 34.61 X
45	1	BUMEPR RETAINER LH REAR	\$	Sm 104.59 X
46	1	BUMEPR BRACKET SIDE RH REAR (Taillamp low)	\$	Sm 34.61 X
47	1	BUMEPR RETAINER RH REAR	\$	Sm 104.59 X
48	1	BUMPER LOWER REAR	\$	B 591.41 ✓
49	1	BUMPER BEAM REAR	\$	R 598.08 ✓
50	1	BUMPER BEAM BRACKET LH REAR	\$	R 173.81 ✓
51	1	BUMPER BEAM BRACKET RH REAR	\$	B 173.81 ✓
52	1	BUMPER REFLECTOR LH	\$	CR 33.55 ✓
53	1	BUMPER REFLECTOR RH	\$	Sm 33.55 X
54	1	BOOT REAR	\$	B 2,209.75 ✓
55	1	BOOT FINISHER	\$	Sm 361.58 X
56	1	BOOT LOCK	\$	R 155.90 X
57	1	BOOT LOCK CATCH	\$	R 57.23 X
58	1	BOOT WHEATERSTRIP	\$	Dis/Pl 248.50 ✓
59	1	BOOT REFLECTOR LAMP LH	\$	CR 379.50 ✓
60	1	BOOT REFLECTOR LAMP RH	\$	Sm 379.50 X
61	1	BOOT BADGE 'RENAULT'	\$	Sm 173.35 ✓
62	1	BOOT BADGE	\$	Sm 173.35 ✓
63	1	BOOT STRUT LH	\$	Sm 212.36 X
64	1	BOOT STRUT RH	\$	Sm 212.36 X
65	1	BOOT HINGE LH	\$	R 282.96 X
66	1	BOOT HINGE RH	\$	R 282.96 X
67	2	LICENCE PLATE LAMP	\$	Sm 84.00 X
68	2	BOOT RUBBER PLUG	\$	Sm 170.63 X
69	1	TAILLAMP LH	\$	MS/CR 425.04 ✓
70	1	TAILLAMP PANEL LH	\$	R 759.00 X
71	1	TAILLAMP RH	\$	Sm 425.04 X
72	1	TAILLAMP PANEL RH	\$	R 759.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 9644C - AXA**ROEL**

73	1	FENDER PANEL REAR LH	\$	R 2,537.80 X
74	1	FENDER PANEL REAR RH	\$	R 2,537.80 X
75	1	FENDER WHEELARCH REAR LH (Linner)	\$	Sm 418.06 X
76	1	FENDER WHEELARCH REAR RH (Linner)	\$	Sm 418.06 X
77	1	AIR VENT RH	\$	Sm 74.83 X
78	1	FENDER PANEL INNER TRIM REAR RH	\$	Sm 516.50 ✓
79	1	FENDER PANEL INNER TRIM REAR LH	\$	Sm 516.50 X
80	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 1,684.52 X
81	1	SPARE WHEEL PANEL TRIM (Luggage Floor Pan)	\$	Sm 470.93 X
82	1	OUTER PANEL REAR (End Panel)	\$	R 1,132.13 ✓
83	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sm 308.48 ✓
84	1	EXHAUST REAR	\$	R 5,760.00 X
85	1	EXHAUST CAP REAR	\$	R 177.30 X

TOTAL	\$	52,299.05
10%	\$	5,229.90
	\$	47,069.14

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	Sm 52.00 ✓
2	1SET	BUMPER CLIP FRT	\$	Sm 66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	Sm 12.00 X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	Sm 10.50 X
5	1	BUMPER BRACKET CLIP FRT RH	\$	Sm 12.00 X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	Sm 10.50 X
7	1	TOW COVER FRT	\$	Sm 14.50 X
8	1SET	RADAIOR GRILLE SCREW	\$	Sm 16.00 X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	Sm 69.00 X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Sm 70.00 ✓
11	2	FRAME FULL SUPPORT PANEL NUT	\$	Sm 20.00 X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	Sm 30.00 X
13	1SET	WHEELARCH CLIP FRT LH	\$	Sm 30.50 X
14	1SET	WHEELARCH CLIP FRT RH	\$	Sm 29.40 X
15	2	BONNET CABLE CLIP	\$	Sm 6.40 X
16	1SET	BUMPER RR RIVET	\$	Sm 28.60 ✓
17	1SET	BUMPER RR CLIP	\$	Sm 66.00 ✓
18	1SET	BUMPER BEAM BOLT	\$	Sm 22.22 X
19	1SET	REFLECTOR SCREW LH	\$	Sm 25.00 X
20	1SET	PARKING AID	\$	Short 600.00 ✓
21	1	BUMPER BRACKET CLIP CTR REAR	\$	Sm 15.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 9644C - AXA

22	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	12.00 X
23	1	BUMEPR RETAINER CLIP LH REAR	\$	10.40 ✓
24	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	12.00 X
25	1	BUMEPR RETAINER CLIP RH REAR	\$	10.40 X
26	1SET	FENDER WHEELARCH CLIP LH RR	\$	32.34 X
27	1SET	FENDER WHEELARCH CLIP RH RR	\$	32.34 X
28	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00 X
29	1	SPARE TYRE	\$	330.00 X
30	1SET	BOOT FINISHER CLIP	\$	25.10 X
31	1	Rear boots sticker "trans-cab"	\$	30.00 ✓
32	1	Rear boots sticker "6555-3333"	\$	30.00 ✓
33	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	22.00 X
34	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	22.00 X
35	2	Rear windscreen sealant	\$	80.00 X
36	1	Windscreen moulding	\$	100.00 X
37	1	Rear Windscreen Inner Sponge Seal	\$	100.00 X
38	1	EXHAUST MOUNTING REAR	\$	65.50 X
39	1	EXHAUST BRACKET REAR	\$	22.22 X
40	1SET	Front licence plate with holder	\$	80.00 80.00
41	1SET	Rear licence plate with holder	\$	80.00 X
42	1	DOOR STICKER "Trans-cab" LH	\$	80.00 X
43	1	DOOR STICKER "Classic" LH	\$	30.00 X
42	1	DOOR STICKER "Trans-cab" RH	\$	80.00 X
43	1	DOOR STICKER "Classic" RH	\$	30.00 X

TOTAL \$ 2,906.92**TOTAL PARTS \$ 49,976.06**

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 16,800.00 ~~1200~~ ⁶⁰⁰

Towing Fees.

\$ 120.00 ~~500~~ ⁵⁰⁰ X

To apply paint protection system (PPS) maintain
and enhancement

\$ 380.00 X

Putty and spray painting of the affected portion.

\$ 18,000.00 ⁶⁶⁰⁰ ~~1400~~

To rust-proofing of the affected areas.

\$ 170.00 ⁶⁰⁰

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

ROEL

SHB 9644C - AXA

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>bol</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>Repair nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>Repair nn</i> 170.00 X
To check ABS brake efficiency, final checking and testing.	\$	<i>nn</i> 380.00 X
To remove and refit ABS pump relay to enable repair.	\$	<i>nn</i> 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 X
To Check Electrical Lighting Concerned.	\$	<i>20</i> 170.00 <i>bol</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>bol</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>Repair nn</i> 380.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>bol</i>

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

ROEL**SHB 9644C - AXA**

To transfer of rear windscreen fittings, attachments and perform water seepage test.

\$ *nr* 380.00 *X*

To reinstall rear bumper parking sensor.

\$ *Hyundai* 170.00 *X*

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.

\$ 280.00 *600*

To repair and realign rear exhaust pipe.

\$ 170.00

To dismantle and refit rear undercarriage parts, final checking and testing.

\$ *nr* 380.00 *X*

To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.

\$ *nr* 380.00 *X***TOTAL \$ 41,470.00****Over All Total \$ 91,446.06**

< parts by parts > Repair Days

30 DAYS*5 Days*



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHB9644C

Vehicle to be
Exported: Yes

Intended De-
registration Date: 01 Mar 2016

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C001915

Chassis No.: VF1ABL15AUC279415

Maximum Power
Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration
Date: 30 Sep 2014

First Registration
Date: 30 Sep 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility
Expiry Date: 29 Sep 2022

PARF Rebate
Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2022

COE Category: A - Car (up to 1600cc & 97kW (130bhp))

COE Period(Years): 8

PQP Paid: \$50,704.00

COE Rebate
Amount: \$40,563.00

**Total Rebate
Amount: \$49,936.00**

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Mar 2016



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

9 March 2016

LAI FOOK MING
BLK 163 YUNG PING ROAD
#07-82
SINGAPORE 610163

Dear Sir/Madam,

OUR REF : CC3/AXA16004071/Kyg3

YOUR REF : SKD 4222Z

**ACCIDENT INVOLVING SKD 4222Z AND SHB 9644C ALONG AYE (CTE) ON
01.03.2016**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s TRANS-CAB AUTO SERVICES PTE LTD acting on behalf of the owner of SHB 9644C against your motor insurance policy.

Basing on the circumstances of the accident reported that your vehicle had rear ended the third party vehicle SHB 9644C. As such, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to cs-a@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

Accident Photo



Print Sent Message

This mail is associated with :

***SHB9644C (C0374251)**
[SKD4222Z]

TP
TRANS-CAB SERVICES PTE LTD
Mar 1 2016 6:00AM
[LAI, FOOK MING]
Trans-cab Auto Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 31/05/2017 15:40 PM.
To vale.oh@axa.com.sg
CC jaskhine@lkkauto.com; olivialau@lkkauto.com; AXA_SG
Subject NO FURTHER DEVELOPMENT AND WILL CLOSE THE MATTER TEMPORARY

Dear Vale,

We refer to the above matter.

TP driver reported that total 3 vehicles involved in chain collision and his vehicle was second. However, TP driver unable to provide the first vehicle number.

OI reported that this is a head to rear collision and he stand firm that only 2 vehicles involved in this accident.

Therefore, our surveyor would like to finalise cost of repair with TP repairer only rear portion. However, TP repairer did not accept and want to confirm with their hirer again.

Our latest discussion with TP repairer @ their office on 20/04/2017 during the bulk settlement meeting and TP repairer still unable to provide the first vehicle number.

Since there is no further development, we will close the file temporary and will submit our wp report to your good office.

Thank you.

Best Regards,

Jas Khine | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Mar 2016		03 Mar 2016 09:34 Edit Adj Rpt	S\$9,139.24 Edit Estimates	S\$9,139.24 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LAI, FOOK MING, ID: S1570393H, Tel: +6596155168, Email: LAIFM7@GMAIL.COM		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHB9644C	Date of Loss:	01/03/2016 06:00 - :59
Claim Type:	TP / C0374251	Policy/Cover Note No.:	GA041467 (Comprehensive)
Vehicle Reg. No. (Insured):	SKD4222Z	Policy No. (Claimant):	VPX/P1680520
	Excess:	S\$0.00	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Vale Oh - 6880 4897]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/03/2016]		
Driver/Custodian (Insured):	LAI, FOOK MING (), NRIC: S1570393H, Tel: +6596155168		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AXA_SG (12/10/2016): PLS ADVISE STATUS OF THE ABOVE MATTER, TKS-VO-12/10/16
- AXA_SG (03/03/2016): New TP Assignment - C0374251/GA041467

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB9644C (C0374251)**
[SKD4222Z]
TP
TRANS-CAB SERVICES PTE LTD
Mar 1 2016 6:00AM
[LAI, FOOK MING]
Trans-cab Auto Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer ▼	
Assessment Reports				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/03/16 14:24	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/03/16 09:53	LKKPhotosInspection		Load PDF	
Documentation				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	03/03/16 09:05	EMAIL_ABS		Load PDF	
2	03/03/16 09:05	SHB9644C TP GIA_ABS		Load PDF	
3	03/03/16 09:05	SKD4222Z INS GIA_ABS		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/03/16 14:25	TP ESTIMATE - MARKED		Load PDF	
2	09/03/16 11:52	Letter to OI		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid #ccc; height: 100px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AXA16004071/KYG3Q2

Date: 03/07/2017

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA041467
Claimant Vehicle No :	SHB9644C	Insured Vehicle No :	SKD4222Z
Date of Loss:	01/03/2016	Nature of Claim:	TP
		Claim No:	C0374251

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9644C	Engine No:	M9R8839C001915
Make & Model:	RENAULT LATITUDE, 2.0 CVT ABS (A)	Chassis No:	VF1ABL15AUC279415
Reg. Date:	30/09/2014 (Man. Year: 2014)	Odometer:	178113 km
Colour:	Red/White		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Rovelo 8 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Rovelo 8 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,976.07	7,559.24	42,416.83	84.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	41,470.00	1,580.00	39,890.00	96.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	91,446.07	9,139.24	82,306.83	90.01
+ GST 7.00/7.00% (S\$)	6,401.22	639.75	5,761.47	90.01
Nett Amount (S\$)	97,847.29	9,778.99	88,068.30	90.01

INSPECTION

Date of Assignment:	03/03/2016	
Date Inspected:	01/03/2016	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2017)	
Parts: 143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SHB9644C)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT (BROKEN)	Not Consistent With The Impact	968.79 FL	*- FL
2	1		*BUMPER SPOILER FRT (Serviceable)	Not Consistent With The Impact	139.81 FL	*- FL
3	1		*BUMPER ABSORBER FRT (Cracked)	Not Consistent With The Impact	303.60 FL	*- FL
4	1		*BUMPER RETAINER FRT LH (Serviceable)	Not Consistent With The Impact	116.47 FL	*- FL
5	1		*BUMPER SUPPORT FRT LH (HEADLAMP LOWER) (Serviceable)	Not Consistent With The Impact	18.37 FL	*- FL
6	1		*BUMPER RETAINER FRT RH (Distorted)	Not Consistent With The Impact	115.98 FL	*- FL
7	1		*BUMPER SUPPORT FRT RH (HEADLAMP LOWER) (Serviceable)	Not Consistent With The Impact	18.37 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT (Serviceable)	Not Consistent With The Impact	363.71 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT (Serviceable)	Not Consistent With The Impact	205.23 FL	*- FL
10	1		*BUMPER FOG LAMP GRILLE LH (Serviceable)	Not Consistent With The Impact	159.39 FL	*- FL
11	1		*BUMPER FOG LAMP GRILLE RH (Serviceable)	Not Consistent With The Impact	159.39 FL	*- FL
12	1		*BUMPER BEAM FRT (Repair)	Not Consistent With The Impact	703.14 FL	*- FL
13	1		*RADIATOR GRILLE (Cracked)	Not Consistent With The Impact	1,313.68 FL	*- FL
14	1		*RADIATOR GRILLE BADGE RENAULT (Necessary)	Not Consistent With The Impact	173.36 FL	*- FL
15	1		*RADIATOR GRILLE FRAME (Cracked)	Not Consistent With The Impact	1,041.35 FL	*- FL
16	1		*FRAME FULL SUPPORT PANEL (Cracked)	Not Consistent With The Impact	473.77 FL	*- FL
17	1		*FRAME FULL SUPPORT BRACKET (Repair)	Not Consistent With The Impact	69.07 FL	*- FL
18	1		*FRONT BRACE PANEL (Repair)	Not Consistent With The Impact	136.32 FL	*- FL
19	1		*SUBFRAME OUTER FRT (Serviceable)	Not Consistent With The Impact	2,040.34 FL	*- FL
20	1		*HORN BRACKET (Repair)	Not Consistent With The Impact	31.12 FL	*- FL
21	1		*HEADLAMP LH (Serviceable)	Not Consistent With The Impact	911.10 FL	*- FL
22	1		*HEADLAMP PANEL FRT LH (Repair)	Not Consistent With The Impact	134.59 FL	*- FL
23	1		*HEADLAMP RH (Mtg Cracked)	Not Consistent With The Impact	911.10 FL	*- FL
24	1		*HEADLAMP PANEL FRT RH (Repair)	Not Consistent With The Impact	134.59 FL	*- FL
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*BONNET (Repair)	Impact Not Consistent With The Impact	1,493.56 FL	*- FL
26	1		*BONNET INSULATOR (Serviceable)	Not Consistent With The Impact	312.10 FL	*- FL
27	1		*BONNET HINGE LH (Repair)	Not Consistent With The Impact	267.93 FL	*- FL
28	1		*BONNET HINGE RH (Repair)	Not Consistent With The Impact	267.93 FL	*- FL
29	1		*BONNET LOCK (Repair)	Not Consistent With The Impact	234.99 FL	*- FL
30	1		*FENDER PANEL FRT LH (Repair)	Not Consistent With The Impact	602.95 FL	*- FL
31	1		*FENDER PANEL FRT RH (Repair)	Not Consistent With The Impact	602.95 FL	*- FL
32	1		*FENDER WHEELARCH FRT LH (LINNER) (Serviceable)	Not Consistent With The Impact	107.32 FL	*- FL
33	1		*FENDER WHEELARCH FRT RH (LINNER) (CONSISTENT)	Serviceable	214.49 FL	*- FL
34	1		*RADIATOR (CONSISTENT)	Serviceable	924.77 FL	*- FL
35	1		*ENGINE UNDERTRAY (CONSISTENT)	Serviceable	434.60 FL	*- FL
36	1		*A/C CONDENSER (CONSISTENT)	Serviceable	1,554.13 FL	*- FL
37	1		*TEANSMISSION COOLER (CONSISTENT)	Serviceable	852.66 FL	*- FL
38	1		*DOOR PANEL FRT LH (CONSISTENT)	Repair	2,188.20 FL	*- FL
39	1		*DOOR MIRROR LH (CONSISTENT)	Serviceable	1,141.08 FL	*- FL
40	1		*DOOR PANEL FRT RH (CONSISTENT)	Repair	2,188.20 FL	*- FL
41	1		*DOOR MIRROR RH (Serviceable)	Not Consistent With The Impact	1,141.08 FL	*- FL
42	1		*BUMPER COVER REAR (CONSISTENT)	Bent	852.66 FL	*852.66 FL
43	1		*BUMPER BRACKET CTR REAR (CONSISTENT)	Cracked	87.29 FL	*87.29 FL
44	1		*BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER) (CONSISTENT)	Serviceable	34.61 FL	*- FL
45	1		*BUMPER RETAINER LH REAR (CONSISTENT)	Serviceable	104.59 FL	*- FL
46	1		*BUMPER BRACKET SIDE RH REAR (TAILLAMP LOWER) (CONSISTENT)	Serviceable	34.61 FL	*- FL
47	1		*BUMPER RETAINER RH REAR (CONSISTENT)	Serviceable	104.59 FL	*- FL
48	1		*BUMPER LOWER REAR (CONSISTENT)	Bent	591.41 FL	*591.41 FL
49	1		*BUMPER BEAM REAR (CONSISTENT)	Bent	598.08 FL	*598.08 FL
50	1		*BUMPER BEAM BRACKET LH REAR (CONSISTENT)	Bent	173.81 FL	*173.81 FL
51	1		*BUMPER BEAM BRACKET RH REAR (CONSISTENT)	Bent	173.81 FL	*173.81 FL
52	1		*BUMPER REFLECTOR LH (CONSISTENT)	Cracked	33.55 FL	*33.55 FL
53	1		*BUMPER REFLECTOR RH (CONSISTENT)	Serviceable	33.55 FL	*- FL
54	1		*BOOT REAR (CONSISTENT)	Bent	2,209.75 FL	*2,209.75 FL
55	1		*BOOT FINISHER (CONSISTENT)	Serviceable	361.58 FL	*- FL
56	1		*BOOT LOCK (CONSISTENT)	Repair	155.90 FL	*- FL
57	1		*BOOT LOCK CATCH (CONSISTENT)	Repair	57.23 FL	*- FL
58	1		*BOOT WEATHERSTRIP (CONSISTENT)	Distorted /Dented	248.50 FL	*248.50 FL
59	1		*BOOT REFLECTOR LAMP LH (CONSISTENT)	Cracked	379.50 FL	*379.50 FL
60	1		*BOOT REFLECTOR LAMP RH (CONSISTENT)	Serviceable	379.50 FL	*- FL
61	1		*BOOT BADGE RENAULT (CONSISTENT)	Necessary	173.35 FL	*173.35 FL
62	1		*BOOT BADGE (CONSISTENT)	Necessary	173.35 FL	*173.35 FL
63	1		*BOOT STRUT LH (CONSISTENT)	Serviceable	212.36 FL	*- FL
64	1		*BOOT STRUT RH (CONSISTENT)	Serviceable	212.36 FL	*- FL
65	1		*BOOT HINGE LH (CONSISTENT)	Repair	282.96 FL	*- FL
66	1		*BOOT HINGE RH (CONSISTENT)	Repair	282.96 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
67	2		*LICENCE PLATE LAMP (CONSISTENT)	Serviceable	84.00 FL	*- FL
68	2		*BOOT RUBBER PLUG (CONSISTENT)	Serviceable	170.63 FL	*- FL
69	1		*TAILLAMP LH (CONSISTENT)	Mtg Cracked	425.04 FL	*425.04 FL
70	1		*TAILLAMP PANEL LH (CONSISTENT)	Repair	759.00 FL	*- FL
71	1		*TAILLAMP RH (CONSISTENT)	Serviceable	425.04 FL	*- FL
72	1		*TAILLAMP PANEL RH (CONSISTENT)	Repair	759.00 FL	*- FL
73	1		*FENDER PANEL REAR LH (CONSISTENT)	Repair	2,537.80 FL	*- FL
74	1		*FENDER PANEL REAR RH (CONSISTENT)	Repair	2,537.80 FL	*- FL
75	1		*FENDER WHEELARCH REAR LH (LINER) (CONSISTENT)	Serviceable	418.06 FL	*- FL
76	1		*FENDER WHEELARCH REAR RH (LINER) (CONSISTENT)	Serviceable	418.06 FL	*- FL
77	1		*AIR VENT RH (CONSISTENT)	Serviceable	74.83 FL	*- FL
78	1		*FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	Serviceable	516.50 FL	*- FL
79	1		*FENDER PANEL INNER TRIM REAR LH (CONSISTENT)	Serviceable	516.50 FL	*- FL
80	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	Repair	1,684.52 FL	*- FL
81	1		*SPARE WHEEL PANEL TRIM (LUGGAGE FLOOR PANEL) (CONSISTENT)	Serviceable	470.93 FL	*- FL
82	1		*OUTER PANEL REAR (END PANEL) (CONSISTENT)	Bent	1,132.13 FL	*1,132.13 FL
83	1		*OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	Buckled / Dented	308.48 FL	*308.48 FL
84	1		*EXHAUST REAR (CONSISTENT)	Repair	5,760.00 FL	*- FL
85	1		*EXHAUST CAP REAR (CONSISTENT)	Repair	177.30 FL	*- FL
86	1		*SET RADIATOR GRILLE FRAME CLIP (Necessary)	Not Consistent With The Impact	52.00 FS	*- FS
87	1		*SET BUMPER CLIP FRT (Necessary)	Not Consistent With The Impact	66.00 FS	*- FS
88	1		*BUMPER BRACKET CLIP FRT LH (Not Necessary)	Not Consistent With The Impact	12.00 FS	*- FS
89	1		*BUMPER SUPPORT CLIP FRT LH (Not Necessary)	Not Consistent With The Impact	10.50 FS	*- FS
90	1		*BUMPER BRACKET CLIP FRT RH (Not Necessary)	Not Consistent With The Impact	12.00 FS	*- FS
91	1		*BUMPER SUPPORT CLIP FRT RH (Not Necessary)	Not Consistent With The Impact	10.50 FS	*- FS
92	1		*TOW COVER FRT (Serviceable)	Not Consistent With The Impact	14.50 FS	*- FS
93	1		*SET RADIATOR GRILLE SCREW (Not Necessary)	Not Consistent With The Impact	16.00 FS	*- FS
94	1		*SET BUMPER GRILLE LOWER CLIP (Not Necessary)	Not Consistent With The Impact	69.00 FS	*- FS
95	1		*SET FRAME FULL SUPPORT PANEL CLIP (Necessary)	Not Consistent With The Impact	70.00 FS	*- FS
96	2		*FRAME FULL SUPPORT PANEL NUT (Not Necessary)	Not Consistent With The Impact	20.00 FS	*- FS
97	2		*FRAME FULL SUPPORT PANEL STUD (Not Necessary)	Not Consistent With The Impact	30.00 FS	*- FS
98	1		*SET WHEELARCH CLIP FRT LH (Not Necessary)	Not Consistent With The Impact	30.50 FS	*- FS
99	1		*SET WHEELARCH CLIP FRT RH (Not Necessary)	Not Consistent With The Impact	29.40 FS	*- FS
100	2		*BONNET CABLE CLIP (Not Necessary)	Not Consistent With The Impact	6.40 FS	*- FS
101	1		*SET BUMPER RR RIVET (CONSISTENT)	Necessary	28.60 FS	*28.60 FS
102	1		*SET BUMPER RR CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
103	1		*SET BUMPER BEAM BOLT (CONSISTENT)	Serviceable	22.22 FS	*- FS
104	1		*SET REFLECTOR SCREW LH (CONSISTENT)	Serviceable	25.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
105	1		*SET PARKING AID (CONSISTENT)	Shorted	600.00 FS	*600.00 FS
106	1		*BUMPER BRACKET CLIP CTR REAR (CONSISTENT)	Not Necessary	15.00 FS	*- FS
107	1		*BUMPER BRACKET SIDE CLIP LH REAR (CONSISTENT)	Not Necessary	12.00 FS	*- FS
108	1		*BUMPER RETAINER CLIP LH REAR (CONSISTENT)	Not Necessary	10.40 FS	*- FS
109	1		*BUMPER BRACKET SIDE CLIP RH REAR (CONSISTENT)	Not Necessary	12.00 FS	*- FS
110	1		*BUMPER RETAINER CLIP RH REAR (CONSISTENT)	Not Necessary	10.40 FS	*- FS
111	1		*SET FENDER WHEELARCH CLIP LH RR (CONSISTENT)	Not Necessary	32.34 FS	*- FS
112	1		*SET FENDER WHEELARCH CLIP RH RR (CONSISTENT)	Not Necessary	32.34 FS	*- FS
113	1		*SPARE TYRE RIM (ROUE 7J 16H 2547) (CONSISTENT)	Serviceable	385.00 FS	*- FS
114	1		*SPARE TYRE (CONSISTENT)	Serviceable	330.00 FS	*- FS
115	1		*SET BOOT FINISHER CLIP (CONSISTENT)	Not Necessary	25.10 FS	*- FS
116	1		*REAR BOOT STICKER TRANS-CAB (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
117	1		*REAR BOOT STICKER 6555-3333 (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
118	1		*FENDER PANEL INNER TRIM CLIP REAR RH (CONSISTENT)	Not Necessary	22.00 FS	*- FS
119	1		*FENDER PANEL INNER TRIM CLIP REAR LH (CONSISTENT)	Not Necessary	22.00 FS	*- FS
120	2		*REAR WINDSCREEN SEALANT (CONSISTENT)	Not Necessary	80.00 FS	*- FS
121	1		*WINDSCREEN MOULDING (CONSISTENT)	Not Necessary	100.00 FS	*- FS
122	1		*REAR WINDSCREEN INNER SPONGE SEAL (CONSISTENT)	Not Necessary	100.00 FS	*- FS
123	1		*EXHAUST MOUNTING REAR (CONSISTENT)	Serviceable	65.50 FS	*- FS
124	1		*SET FRONT LICENCE PLATE WITH HOLDER (Necessary)	Not Consistent With The Impact	80.00 FS	*- FS
125	1		*SET REAR LICENCE PLATE WITH HOLDER (CONSISTENT)	Serviceable	80.00 FS	*- FS
126	1		*DOOR STICKER TRANS-CAB LH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
127	1		*DOOR STICKER CLASSIC LH (CONSISTENT)	Not Necessary	30.00 FS	*- FS
128	1		*DOOR STICKER TRANS-CAB RH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
129	1		*DOOR STICKER CLASSIC RH (CONSISTENT)	Not Necessary	30.00 FS	*- FS
130	1		*EXHAUST BRACKET REAR (CONSISTENT)	Serviceable	22.22 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 55,205.98 8,315.31
 - List Item Discount on L Items 10.00/10.00% (\$\$) 5,229.91 756.07

Total Parts (\$\$) 49,976.07 7,559.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	16,800.00	600.00
2	TOWING FEES	New	120.00	0.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	18,000.00	660.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
8	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO CHECK ABS BRAKE ,EFFICIENCY,FINAL CHECKING AND TESTING	New	380.00	0.00
12	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR	New	380.00	0.00
13	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
14	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
16	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
17	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
18	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
19	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
20	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
21	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
22	TO TRANSFER OF REAR WINDSCREEN FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
23	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
24	TO DROP REAR EXHAUST BOX,RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE }	New	280.00	60.00
25	TO REPAIR AND REALIGN REAR EXHAUST PIPE }	New	170.00	0.00
26	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report

No	Particulars	Lab.Type	Repairer's	Amount
27	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY ,REMOVE AND RENEWAL OF PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
Gross Labour Cost (S\$)			41,470.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >