Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG16001735/KGA3Q2-1

Date: 15/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte.

Policy No: 2100326794-

Claimant

Ltd.

Insured Vehicle

03000

Vehicle No :

SHB7998U

No:

SJM4309Y

Date of Loss:

24/01/2016

Nature of Claim: TP

Odometer:

7610158947SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB7998U

Make & Model: CHEVROLET EPICA, 2.0 (A) Engine No: Reg. Date: 29/01/2013 (Man. Year: 2011) Chassis No:

Engine No: Z20S1458477K Chassis No: KL1LA69RJBB122287

346431 km

Claim

No:

Colour: Red/White Engine Capacity: 1991 cc

Engine Capacity: Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Rovelo 7 mm Rear Left Side: Falken 5 mm
Front Right Side: Rovelo 7 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,987.06	1,487.68	7,499.38	83.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	470.00	3,130.00	86.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,587.06	1,957.68	10,629.38	84.45
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	12,587.06	1,550.00	11,037.06	87.69
+ GST 7.00/7.00% (S\$)	881.09	108.50	772.59	87.69
Nett Amount (S\$)	13,468.15	1,658.50	11,809.65	87.69
+ Loss of Use (1.5 x S\$	50.00/day) (S\$)	75.00		
+ Car Rental (1.5 x S\$113.42/day) (S\$) (S\$) Liable Amount (50.00%) (S\$) + Doc/Search Fee (S\$) Nett Liability (S\$)		170.13		
		1,903.63		
		951.82		
		6.00		
		957.82		
Global Sum S	950.00			

INSPECTION

Adjuster Report Page 2 of 4

Date of Assignment: 25/01/2016

Date Inspected: 25/01/2016 Inspected At: Trans-cab Auto Services Pte Ltd (HQ)

No. 42 Sungei Kadut St 1 Singapore 729346

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	1,202.00 FL	*1,202.00 FL
2	1		*REAR BUMPER BEAM	Repair	239.94 FL	*- FL
3	1		*REAR BUMPER CENTRE ABSORBER	Serviceable	260.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Distorted	68.76 FL	*68.76 FL
5	1		*REAR BUMPER REFLECTORS RH	Serviceable	119.74 FL	*- FL
6	1		*REAR BUMPER TOW HOOK COVER	Serviceable	93.00 FL	*-FL
7	1		*REAR END PANEL OUTER	Repair	623.76 FL	*-FL
8	1		*REAR END PANEL INNER TRIM	Serviceable	263.84 FL	*- FL
9	1		*BOOTLID	Repair	973.00 FL	*- FL
10	1		*BOOTLID INNER TRIM BOARD	Serviceable	400.00 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Serviceable	344.28 FL	*- FL
12	1		*BOOTLID LOCK -TOP	Repair	466.56 FL	*- FL
13	1		*BOOTLID CHEVROLET BADGE	Not Necessary	120.62 FL	*- FL
14	1		*BOOTLID LOGO	Not Necessary	138.84 FL	*- FL
15	1		*BOOTLID EPICA LT BADGE	Not Necessary	119.84 FL	*- FL
16	1		*BOOTLID REFLECTOR CENTRE	Serviceable	217.97 FL	*- FL
17	1		*BOOTLID REFLECTOR RH	Serviceable	128.40 FL	*- FL
18	1		*REAR TAIL LAMP RH	Serviceable	479.30 FL	*- FL
19	1		*REAR TAIL LAMP PANEL RH	Repair	359.00 FL	*- FL
20	1		*REAR EXHAUST BOX (MUFFLER A-EXH,RR)	Repair	1,110.00 FL	*-FL
21	1		*REAR FENDER RH (DENTED)	Not Consistent With The Impact	1,145.00 FL	*-FL
22	1		*REAR FENDER INNER TRIM RH	Serviceable	418.44 FL	*- FL
23	1		*SET REAR BUMPER PARKING SENSOR	Dented / Scratched	300.00 FS	*300.00 FS
24	1		*SET REAR BUMPER FASTENER CLIP	Necessary	44.00 FS	*44.00 FS
25	1		*SET REAR FENDER INNER TRIM CLIP RH	Not Necessary	30.00 FS	*-FS
26	1		*REAR BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
27	1		*REAR BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS
28	1		*REAR EXHAUST MOUNTING	Serviceable	10.00 FS	*-FS
29	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
30	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
F=Fra	nchise	part. S=S	SpcNett. L=ListItemDisc.	'		
			- List Item Discount o	Sub Total (S\$) on L Items 10.00/10.00% (S\$)	9,916.29 929.23	1,614.76 127.08
				Total Parts (S\$)	8,987.06	1,487.68

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	200.00				
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00				
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00				
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED	New	1,350.00	200.00				
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00				
6	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00				
7	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WHEEL ALIGNMENT	New	170.00	0.00				
	Gross Labour Cost (S\$)		3,600.00	470.00				

< END OF ESTIMATES >

Report was unsubmitted during this print-out.