

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20005613/UGA3Q2

Date: 18/08/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0002376
Claimant Vehicle No :	SLX1470B	Insured Vehicle No :	GBB9223E
Date of Loss:	06/05/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0000924

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX1470B	Engine No:	27682430690829
Make & Model:	MERCEDES-BENZ S320, 3.2 (A)	Chassis No:	WDD2221622A349514
Reg. Date:	09/03/2018 (Man. Year: 2017)	Odometer:	34863 km
Colour:	Black		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R18	Rear Tyre Size:	245/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,670.73	29,818.60	23,852.13	44.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	2,690.00	1,640.00	37.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	58,000.73	32,508.60	25,492.13	43.95
Approved Total (Overridden) (S\$)		26,000.00		
Nett Amount (S\$)	58,000.73	26,000.00	32,000.73	55.17
+ Loss of Use (10.0 x S\$120.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		27,327.45		
Global Sum Settlement (S\$)		27,300.00		

INSPECTION

Date of Assignment:	08/05/2020	
Date Inspected:	08/05/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	8.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2020)
Parts:	143	MERCEDES-BENZ S320 3.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX1470B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Bent	4,255.12 FL	*3,390.00 FL
2	1		*BONNET LOGO	Not Necessary	215.00 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	366.00 FL	*- FL
4	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 FL	*- FL
5	1		*BONNET LOCK O/S	Twisted	145.00 FL	*145.00 FL
6	1		*FRONT GRILLE	Scratched / Cracked	1,025.00 FL	*1,025.00 FL
7	1		*FRONT BUMPER	Distorted	2,650.00 FL	*2,055.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Torn	488.00 FL	*488.00 FL
9	1		*FRONT BUMPER SIDE GRILLE O/S INNER	Torn	215.00 FL	*215.00 FL
10	1		*FRONT BUMPER CHROME MOULDING	Broken	650.00 FL	*566.22 FL
11	1		*FRONT BUMPER PDC SENSORS (2 PCS)	Shorted (1 PCS ONLY)	626.00 FL	*266.15 FL
12	1		*FRONT BUMPER SPONGE	Torn	288.20 FL	*240.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	1,065.30 FL	*815.20 FL
14	1		*FRONT BUMPER REINFORCEMENT BRACKET O/	Twisted	265.00 FL	*265.00 FL
15	1		*FRONT BUMPER REINFORCEMENT SIDE HOLDER O/S	Bent	62.50 FL	*62.50 FL
16	1		*FRONT BUMPER LOWER COVER	Cracked	422.30 FL	*422.30 FL
17	1		*FRONT BUMPER INNER RETAINER	Distorted	211.00 FL	*211.00 FL
18	1		*FRONT BUMPER LOWER SIDE COVER O/S	Torn	211.50 FL	*188.50 FL
19	1		*FRONT BUMPER INNER BOARD SENSOR	Shorted	1,560.00 FL	*865.00 FL
20	1		*FRONT BUMPER INNER BOARD SENSOR WIRE	Serviceable	485.00 FL	*- FL
21	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
22	1		*HEADLAMP ASSY O/S	Broken	6,850.12 FL	*6,521.58 FL
23	1		*HEADLAMP VOLTAGE CONTROL UNIT	Broken	950.00 FL	*669.28 FL
24	1		*HEADLAMP HIGH BEAM SENSOR UNIT O/S	Cracked	885.00 FL	*628.34 FL
25	1		*HEADLAMP BALLAST O/S	No such part	820.00 FL	*- FL
26	1		*FRONT SUPPORT PANEL	Cracked	1,022.30 FL	*1,016.29 FL
27	1		*WIPER WASHER TANK	Deformed /Torn	425.60 FL	*425.60 FL
28	1		*AIR CON CONDENSER	Serviceable	1,622.30 FL	*- FL
29	1		*RADIATOR	Cracked	1,655.50 FL	*1,319.52 FL
30	1		*RADIATOR FAN ASSY	Not Necessary	1,029.30 FL	*- FL
31	1		*RADIATOR SPARE TANK	Cracked	405.80 FL	*405.80 FL
32	1		*RADIATOR COOLING HOSE	Bent	711.20 FL	*485.10 FL
33	1		*FRONT FENDER O/S	Distorted	1,122.30 FL	*1,122.30 FL
34	1		*FRONT FENDER INNER SHIELD O/S	Torn	388.20 FL	*288.20 FL
35	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 FL	*50.00 FL
36	1		*FRONT FENDER CHROME MOULDING O/S	Necessary	205.00 FL	*145.00 FL
37	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	2,820.00 FL	*- FL
38	1		*FRONT LOWER ARM O/S	Serviceable	566.00 FL	*- FL
39	1		*FRONT KNUCKLE ARM O/S	Bent	1,545.20 FL	*1,355.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT KNUCKLE ARM BEARING O/S	Necessary	488.50 FL	*365.00 FL
41	1		*FRONT TORSION ARM O/S	Serviceable	495.00 FL	*- FL
42	1		*FRONT STEERING RACK ASSY	Not Necessary	4,800.00 FL	*- FL
43	1		*FRONT SPORT RIM O/S	Dented / Bent	1,280.00 FL	*850.00 FL
44	1		*FRONT DOOR O/S	Badly Dented	3,950.00 FL	*3,125.00 FL
45	1		*FRONT DOOR VIEW MIRROR ASSY O/S	Shorted / Cracked	1,290.50 FL	*1,255.20 FL
46	1		*FRONT DOOR VIEW MIRROR COVER O/S	Cut	199.20 FL	*199.20 FL
47	1		*FRONT DOOR CHROME LOWER MOULDING O/S	Necessary	366.20 FL	*315.00 FL
48	1		*FRONT DOOR FRAME CHROME TOP MOULDING O/S	Necessary	395.50 FL	*395.50 FL
49	1		*FRONT DOOR GLASS REGULATOR O/S	Not Necessary	799.20 FL	*- FL
50	1		*FRONT DOOR INNER LOCK O/S	Not Necessary	499.50 FL	*- FL
51	1		*FRONT DOOR INNER TRIM BOARD O/S	Not Necessary	1,295.30 FL	*- FL
52	1		*FRONT WATER PUMP	Not Necessary	820.20 FL	*- FL
53	1		*ROCKER PANEL GARNISH O/S	Torn	915.30 FL	*915.00 FL
54	1		*REAR DOOR O/S	Repair	3,650.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 59,634.14 33,131.78
- List Item Discount on L Items 10.00/10.00% (\$\$) 5,963.41 3,313.18

Total Parts (\$\$) 53,670.73 29,818.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING PDC SENSOR	New	80.00	50.00
3	TO SPRAY RUST PROOFING	New	120.00	80.00
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	100.00
5	TO DISMANTLE & REPLACING FRONT UNDER CARRIAGE	New	380.00	150.00
6	TO TRANSFER FRONT DOOR MECHANISM	New	120.00	80.00
7	TO RESET & REPROGRAMME SYSTEM	New	280.00	100.00
8	TO REFILL AIR CON GAS	New	120.00	100.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,200.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			4,330.00	2,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >