

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005620/KPA3Q2
Date: 31/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800088598
Claimant Vehicle No :	SMQ5590L	Insured Vehicle No :	SMD2676L
Date of Loss:	07/05/2020	Nature of Claim:	TP
		Claim No:	8335396704SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5590L	Engine No:	G4LEKS566950
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Chassis No:	KNACB81CVL5341292
Reg. Date:	25/11/2019 (Man. Year: 2019)	Odometer:	26081 km
Colour:	Metallic Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,228.10	1,961.70	1,266.40	39.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,386.18	664.84	721.34	52.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,614.28	2,626.54	1,987.74	43.08
+ GST 7.00/7.00% (S\$)	323.00	183.86	139.14	43.08

Nett Amount (S\$)	4,937.28	2,810.40	2,126.88	43.08
+ Car Rental (7.0 x S\$84.95/day) (S\$)		594.65		
+ Doc/Search Fee (S\$)		7.48		
Nett Liability (S\$)		3,412.53		

INSPECTION

Date of Assignment: 08/05/2020

Date Inspected: 11/05/2020

Inspected At:

Esteem Performance Pte Ltd (HQ)
385 SIN MING DRIVE SINGAPORE 575718

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BADGE MODEL	Necessary	25.00 FL	*25.00 FL
2	1		*BOOT/TAILGATE LOCK	Repair	205.00 FL	*- FL
3	1		*BOOT/TAILGATE SEAL	Necessary	109.00 FL	*109.00 FL
4	1		*BOOT/TAILGATE TRIM	Serviceable	164.00 FL	*- FL
5	1		*BOOT/TAILGATE TRIM	Serviceable	38.00 FL	*- FL
6	1		*BOOTLID / TAILGATE	Bent	1,311.00 FL	*1,311.00 FL
7	1		*L/LWR TAILLAMP COVER	Serviceable	45.00 FL	*- FL
8	1		*L/R LOWER LAMP	Serviceable	328.00 FL	*- FL
9	1		*L/R OUT BUMPER BRKT	Serviceable	25.00 FL	*- FL
10	1		*L/TAILGATE HINGE	Repair	24.00 FL	*- FL
11	1		*MANUFACTURER BADGE	Necessary	38.00 FL	*38.00 FL
12	1		*R/LWR TAILLAMP COVER	Serviceable	45.00 FL	*- FL
13	1		*R/R BADGE	Necessary	29.00 FL	*29.00 FL
14	1		*R/R LOWER LAMP	Serviceable	328.00 FL	*- FL
15	1		*R/R OUT BUMPER BRKT	Not Necessary	25.00 FL	*- FL
16	1		*R/TAIGATE HINGE	Repair	24.00 FL	*- FL
17	1		*REAR BUMPER COVER	Serviceable	25.00 FL	*- FL
18	1		*REAR BUMPER SUPPORT	Bent	235.00 FL	*235.00 FL
19	1		*REAR FLOOR END PANEL	Repair	526.00 FL	*- FL
20	1		*REAR LOWER BUMPER	Buckled	354.00 FL	*354.00 FL
21	1		*REAR SCREEN BOND KIT (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*REAR UPPER BUMPER	Dented / Cracked	440.00 FL	*440.00 FL
23	1		*RR BMP CLIP	Necessary	50.00 FL	*50.00 FL
24	1		*RR WS SEALANT RR WS SEALANT	Necessary	45.00 FS	*40.00 FS
25	1		*RR NUMBER PLATE RR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
26	1		*R BUMPER LOW: R.B LOW GARNISH	Necessary	90.00 FL	*90.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,573.00	2,766.00
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,344.90	804.30
Total Parts (\$\$)	3,228.10	1,961.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TUFF COAT TO TUFF COAT.	New	100.00	60.00
2	TOTAL LABOUR.	New	740.00	265.00
3	PAINT WORK: LABOUR COST.	New	390.00	210.00
4	PAINT WORK: MATERIAL COST.	New	156.18	129.84
Gross Labour Cost (\$)			1,386.18	664.84

Report was unsubmitted during this print-out.

< END OF ESTIMATES >