

ASS. REC. BY:

REF:

A/G / 20005620 / Kk₂₃

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Esteen

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1.131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMQ 55902 Yr Regn: 11, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A1 WagonMake: Hig Niro c.c. 1580Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 26081 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNACB81CVL 5341292Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD / Rlm orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 7/15/20 D.O.I. 11/5/2020

Survey held at _____

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/5 @ 2626-54 Confirmed

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS. \$ _____☐ : Interview (\$ _____) ☐ : Photos☐ : Tech Invs (\$ _____) ☐ : Others☐ : Weekend (\$ _____) ☐ : _____

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ _____)

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference: SMD2676L
Repairer Reference: 031635
Date calculated: 09/05/2020 10:45 AM

Full Report
Registration: SMQ5590L
Printed: 09/05/2020 10:45 AM

Summary Information

Claim		Work Provider:	AIG Asia Pacific Insurance
Location:	Singapore (SG)		Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:	SMD2676L	Date of Incident:	07/05/2020
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
Manufacturer: KIA
Model: E-NIRO EV (DE)
Sub Model: BASE MODEL
Model Sheet Number: 28 1E 01
Registration: SMQ5590L
VIN number:
Odometer:
Model Specs
TWO COAT METALLIC

Not Authorized
Resurvey B4 paint

5 days

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:


Damage Areas

All ☐
Underbody ☐

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Labour

		Time Base 10 WU/h	Price = 50.00 SGD/h	
Code	Description		WU	Price SGD
73700R00	RENEW TAILGATE INCLUDES: R + R TAILGATE ATTACHED PARTS ASSEMBLE AND IF NECESSARY RENEW		30.0	150.00
79770R00	R + R LEFT TAILGATE HINGE		5.0	25.00
79770R00	R + R RIGHT TAILGATE HINGE		5.0	25.00
79002A00	R + R TAILGATE LOCK PLATE		2.0	10.00
87160R00	R + R BOOT LID SEAL		3.0	15.00
86651R00	RENEW REAR BUMPER INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS		14.0	70.00
92401R0B	R + R BOTH OUTER TAILLAMPS		4.0	20.00
NO NUMBER	RENEW REAR END PANEL		67.0	335.00
84121R00)	R + R REAR CARPET		3.0	15.00
85731R00)	R + R LEFT SIDE PANEL TRIM		6.0	30.00
85731R00)	R + R RIGHT SIDE PANEL TRIM		6.0	30.00
89000R0B	R + R REAR SEAT CUSHION CPL		3.0	15.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		14.80	148.0	740.00
Total of Labour				740.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC		WU Price SGD
	REAR FLOOR END PANEL NEW PART PAINTING		21.0
	BOOTLID/TAILGATE NEW PART PAINTING		17.0
	REAR UPPER BUMPER NEW PART PAINT K1R		11.0
	REAR BUMPER COVER NEW PART PAINT K1R		3.0

Paint Material Per Part

Code	Description	Price SGD
2711	REAR FLOOR END PANEL NEW PART PAINTING	25.85
2931	BOOTLID/TAILGATE NEW PART PAINTING	51.08
2583	REAR UPPER BUMPER NEW PART PAINT K1R	51.66
2586	REAR BUMPER COVER NEW PART PAINT K1R	0.49

Labour Cost - Paint

	50.00 SGD/h	Hrs	WU	Price SGD
Factor			52.0	
Time Paint		2.10	21.0	105.00
Preparation Main Work Metal		0.50	5.0	25.00
Preparation Comp. Work Plastic		7.80	78.0	390.00
Total	10 WU/h			

Material Cost - Paint

New Part Painting
 New Part Painting - Plastic K1R
 Material-constant Metal
 Material-constant Plastic
Total

Price SGD
 76.93
 52.15
 18.10
 9.00
 156.18

Spare Parts

prices as at 2015-06-01
 Price SGD

Code	Description	Part Number	
3019	BADGE MODEL	86311G5000	25.00 ✓
2975	BOOT/TAILGATE LOCK	81230G5000	205.00 X
2944	BOOT/TAILGATE SEAL	87321G5000	109.00 ✓
4907	BOOT/TAILGATE TRIM	81750G5000WK	164.00 X
4913	BOOT/TAILGATE TRIM	81760G5000WK	38.00 X
2931	BOOTLID/TAILGATE	73700G5000	1,311.00 ✓
2627	L/LWR TAILLAMP COVER	92405Q4010	45.00 X
3401	L/R LOWER LAMP	92405Q4000	328.00 X
2603	L/R OUT BUMPER BRKT	86613G5000	25.00 X
2953	L/TAILGATE HINGE	797702L200	24.00 X
3015	MANUFACTURER BADGE	86310G5100	38.00 ✓
2628	R/LWR TAILLAMP COVER	92406Q4010	45.00 X
3020	R/R BADGE	86312Q4000	29.00 ✓
3402	R/R LOWER LAMP	92406Q4000	328.00 X
2604	R/R OUT BUMPER BRKT	86614G5000	25.00 ?
2954	R/TAILGATE HINGE	797702L200	24.00 X
2586	REAR BUMPER COVER	86617Q4000	25.00 X
2640	REAR BUMPER SUPPORT	86631Q4000	235.00 ✓
2711	REAR FLOOR END PANEL	69100G5500	526.00 X
2585	REAR LOWER BUMPER	86612Q4000	354.00 ✓
3160	REAR SCREEN BOND KIT	KNGKWI2	0.00 X
2583	REAR UPPER BUMPER	86610Q4020	440.00 ✓
1002	RR BMP CLIP	RR BMP CLIP	50.00 ✓

Original

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Savings
Subtotal
Subtotal Discount(+30.00%)
Total

0.00
 4,393.00
 -1,317.90
 3,075.10

Extras

Code	Description	Price SGD
1000	To tuff coat To tuff coat	100.00* 60L
1003	RR WS SEALANT RR WS SEALANT	45.00* 405
1004	RR NUMBER PLATE RR NUMBER PLATE	45.00* ✓
Total Extras		190.00

Final Calculation

	SGD	SGD
Parts	4,393.00	
Total Discount(+30.00%)	-1,317.90	
Total Parts		3,075.10
Labour Time Base 10 WU/h		
Total 148.0 WU X 50.00 SGD/h	740.00	
Total of Labour		740.00
Total Of Extras		190.00
Paint Work Time Base 10 WU/h		
Labour Cost 78.0 WU X 50.00 SGD/h	390.00	
Material Cost	156.18	
Total Paint Including Material		546.18
Repair Cost Excludes GST		4,551.28
GST (+7.0%)		318.59
Repair Cost Included GST		4,869.87

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.