

Our Reference : 2020/0061

Your Reference:

Vehicle Number : FBE7189E

S/N	Qty	Description	Condition	Repairer Estimate (S\$)	Our Assessment (S\$)
		Parts			
1	1pcs	Front fender X nn	Dislodge	120.00	120.00
2	1pcs	Front fork clamber and damper X SVC	Bent	180.00	180.00
3	1pcs	Front rims X SVC	Grazed	160.00	160.00
4	1pcs	Front rim spocket X SVC	Bent	120.00	120.00
5	2pcs	Front disc brake X SVC	Warp	105.00	105.00
6	1pcs	handle bar cover front and rear	Crack	95.00	95.00
7	2pcs	Signal light left and right @40/pes	LH Broken	80.00	40.00
8	1pcs	Front Fork Left and right @220/pes X	Repair	440.00	- SVC
9	1pcs	Front Cowling X	Serviceable	95.00	- SVC
10	1pcs	Brake lever Left and right @40/pes	LH Grazed	80.00	40.00
11	1pcs	Handle bracket X SVC	Bent	80.00	80.00
12	1pcs	Front cover X	Repair	95.00	- SVC
13	1pcs	Footrest lower fairing	Grazed	95.00	95.00
14	1pcs	Fr cover stay	Grazed	50.00	50.00
15	1pcs	headlamp complete X	Serviceable	130.00	- SVC
16	1pcs	Front shield, black X	Serviceable	120.00	- SVC
17	1pcs	Lh side board	Grazed	130.00	130.00
18	1pcs	handle bar	Bent	95.00	95.00
19	1pcs	Cone bearing X SVC	Necessary	95.00	95.00
20	1pcs	Side Mirror left and right @20/pes	LH Grazed	40.00	20.00
21	1pcs	Lh body cover	Grazed	120.00	120.00
22	1pcs	Signal, light control switches X	Serviceable	118.00	- SVC
23	1pcs	Lh body cover garnish	Grazed	140.00	140.00
24	1pcs	Fuel Tank cap Xnn	Dislodge	80.00	80.00
25	1pcs	left side panel fender	Grazed	120.00	120.00
26	1pcs	Step assy, LH	Grazed	95.00	95.00
27	1pcs	Lh side board	Grazed	105.00	105.00
28	1pcs	Rear Mud Guard	Dented	95.00	95.00
29	1pcs	Rear Tail lightlamp	Crack	95.00	95.00
30	1pcs	Lh & Rh signal light X	Serviceable	95.00	- SVC
31	1pcs	Engine crank case	Grazed	120.00	120.00
32	1pcs	Engine crank case gasket	Necessary	80.00	80.00

1455
10%
1309.50

Total 3668.00 2,475.00
Less 10% 366.80 247.50
Parts Sub Total 3301.20 2,227.50

1880 s/n

Special Nett

34	1pcs	Front Number plate xnn	Dented	15.00	15.00
35	1sets	Fork Oil Shield xnn	Deformed	70.00	70.00
36	1sets	Fork dust cover xnn	Necessary	70.00	70.00
37	1sets	Fork oil Xnn	Necessary	50.00	50.00
38	1sets	Engine oil	Necessary	60.00	60.00
39	1pcs	Pipe Leo vince SBK	Tip Crack	1800.00	1800.00

s/n 40
s/n

Total 2,065.00 2,065.00

Labour					
1		Towing xnn		80.00	80.00

2	Front & rear rims alignment	50.00	50.00	30
3	Front fork alignment	350.00	200.00	xnn
4	To R&R front suspension, handle bar, headlamp, side fairing, and attachments.	300.00	250.00	150
5	To respray on front fender, headlamp coving, LH fairing and accident affected area.	350.00	300.00	200
Labour Total		1,130.00	880.00	
Sub Total (labour and parts)		6,496.20	5,172.50	

1309.50
1880.00
+ 380.00
3569.50
20%
2855.60
L/S 2850
4 DAYS

Adjustment / Recommendations

Note: For Lump Sum Repair

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is \$4150

Under normal circumstances, the repair period would be about 7 working days.