



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 7193E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	SERVICEABLE	120.00	-
1	FRONT FORK CLAMPER AND DAMPER	SERVICEABLE	180.00	-
1	FRONT RIMS	SERVICEABLE	160.00	-
1	FRONT RIM SPOCKET	SERVICEABLE	120.00	-
2	FRONT DISC BRAKE	SERVICEABLE	105.00	-
1	HANDLE BAR COVER FRONT AND REAR	CRACKED	95.00	95.00
2	SIGNAL LIGHT LEFT AND RIGHT @\$40.00	N/S BROKEN	80.00	40.00
2	FRONT FORK LEFT AND RIGHT @\$220.00	SERVICEABLE	440.00	-
1	FRONT COWLING	SERVICEABLE	95.00	-
2	BRAKE LEVER LEFT AND RIGHT @\$40.00	N/S GRAZED	80.00	40.00
1	HANDLE BRACKET	SERVICEABLE	80.00	-
1	FRONT COVER	SERVICEABLE	95.00	-
1	FOOTREST LOWER FAIRING	GRAZED	95.00	95.00
1	FR COVER STAY	GRAZED	50.00	50.00
1	HEADLAMP COMPLETE	SERVICEABLE	130.00	-
1	FRONT SHIELD, BLACK	SERVICEABLE	120.00	-
1	LH SIDE BOARD	GRAZED	130.00	130.00
1	HANDLE BAR	BENT	95.00	95.00
1	CONE BEARING	SERVICEABLE	95.00	-
2	SIDE MIRROR LEFT AND RIGHT @\$20.00	N/S GRAZED	40.00	20.00
1	LH BODY COVER	GRAZED	120.00	120.00
1	SIGNAL, LIGHT CONTROL SWITCHES	SERVICEABLE	118.00	-
1	LH BODY COVER GARNISH	GRAZED	140.00	140.00
1	FUEL TANK CAP	SERVICEABLE	80.00	-
1	LEFT SIDE PANEL FENDER	GRAZED	120.00	120.00
1	STEP ASSY, LH	GRAZED	95.00	95.00
1	LH SIDE BOARD	GRAZED	105.00	105.00
1	REAR MUD GUARD	DENTED	95.00	95.00
1	REAR TAIL LIGHTLAMP	CRACKED	95.00	95.00
2	LH & RH SIGNAL LIGHT	SERVICEABLE	95.00	-
1	ENGINE CRANK CASE	GRAZED	120.00	120.00

Report Ref No. CS1/ASM20005622/R1sf3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-358.80	-145.50
			3,229.20	1,309.50
1	ENGINE CRANK CASE GASKET (SN)	NECESSARY	80.00	40.00
	LESS 10% DISCOUNT		-8.00	-
			72.00	40.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	15.00	-
1	SETS FORK OIL SHIELD (SN)	SERVICEABLE	70.00	-
1	SETS FORK DUST COVER (SN)	SERVICEABLE	70.00	-
1	SETS FORK OIL (SN)	SERVICEABLE	50.00	-
1	SETS ENGINE OIL (SN)	NECESSARY	60.00	40.00
1	PIPE LEO VINCE SBK (SN)	TIP CRACK	1,800.00	1,800.00
			2,065.00	1,840.00
	<u>LABOUR</u>			
	TOWING.	NOT NECESSARY	80.00	-
	FRONT & REAR RIMS ALIGNMENT.		50.00	30.00
	TO R&R FRONT SUSPENSION, HANDLE BAR, HEADLAMP, SIDE FAIRING, AND ATTACHMENT.		300.00	150.00
	TO RESPRAY ON FRONT FENDER, HEADLAMP CROWING, LH FAIRING AND ACCIDENT AFFECTED AREA.		350.00	200.00
	FRONT FORK ALIGNMENT.	NOT NECESSARY	350.00	-
			1,130.00	380.00
GRAND TOTAL			6,496.20	3,569.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,850.00

Report Ref No. CS1/ASM20005622/R1sf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.